

15 Cumberland Avenue

14-A-24

Jacob Cerino

MUNJ-NO,



MADE IN U.S.A.

2003R

CERTIFICATE  
OF  
COMPLIANCE

CITY OF PORTLAND

February 21, 1978

Department of Neighborhood Conservation  
Housing Inspections Division  
Telephone: 775-5451 - Extension 448 - 358

Jacob Cerino  
15 Cumberland Avenue  
Portland, Maine 04101

Re: Premises located at 15 Cumberland Avenue, Portland, Maine 14-A-24 MN

Dear Mr. Cerino:

A re-inspection of the premises noted above was made on Feb. 16, 1978  
by Housing Inspector Stevenson.

This is to certify that you have complied with our request to correct the violation  
of the Municipal Codes relating to housing conditions as described in our "Notice  
of Housing Conditions" dated March 15, 1977.

Thank you for your cooperation and your efforts to help us maintain decent, safe  
and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing  
inventory, it shall be the policy of this department to inspect  
each residential building at least once every five years.  
Although a property is subject to re-inspection at any time during  
the said five year period, the next regular inspection of this  
property is scheduled for 1983.

Sincerely yours,

Joseph E. Gray, Jr., Director  
Neighborhood Conservation

By

Lyle D. Noyes  
Lyle D. Noyes  
Chief of Housing Inspections

Inspector D. Stevenson  
D. Stevenson

10:00 11/16/77  
OK  
ADMINISTRATIVE HEARING DECISION

City of Portland  
Department of Neighborhood Conservation  
Housing Inspections Division  
Telephone: 775-5451 - Ext. 448 - 358

Date June 22, 1977

Jacob Cerino  
15 Cumberland Avenue  
Portland, Maine 04101

77-9376

Re: Premises located at 15 Cumberland Avenue, Portland, Maine 04101

Dear Mr. Cerino:

You are hereby notified that as a result of a recent reinspection and your request  
for additional time  
on June 21, 1977, regarding our "Notice of Housing Conditions" at the above  
referred premises resulted in the decision noted below.

XX Expiration time extended to July 22, 1977 in order to complete the work  
in progress to correct the remaining five (5) Housing Code violations as  
shown on the attached copy of "Notice of Housing Conditions" dated 3/15/77

Notice modified as follows: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Please notify this office if all violations are corrected before the above mentioned  
dates, so that a "Certificate of Compliance" may be issued.

Very truly yours,

Joseph E. Gray, Jr.  
Director Neighborhood Conservation

By Lyle D. Hayes  
Lyle D. Hayes  
Chief of Housing Inspections

In Attendance:  
Inspector Stevenson  
Mr. Cerino

NOTICE OF HOUSING CONDITIONS X

DU 2

CITY OF PORTLAND  
DEPARTMENT OF NEIGHBORHOOD CONSERVATION  
HOUSING INSPECTIONS DIVISION  
Telephone 775-5451 - Extension #448 - #358

Ch.-Bl.-Lot: 14-A-24  
Location: 15 Cumberland Ave.  
Project: Munjoy North  
Issued: March 15, 1977  
Expired: May 15, 1977

Jacob Cerino  
15 Cumberland Avenue  
Portland, Maine 04101

Dear Mr. Cerino:

An examination was made of the premises at 15 Cumberland Ave., Portland, Maine by Housing Inspector Stevenson. Violations of Municipal Codes relating to housing conditions were found as described in detail below.

In accordance with provisions of the above mentioned Codes, you are requested to correct these defects on or before May 15, 1977. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this Notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing.

Sincerely yours,  
Joseph E. Cray, Jr., Director  
Neighborhood Conservation

Inspector D. Stevenson  
D. Stevenson

By Lyle D. Noyes  
Lyle D. Noyes,  
Chief of Housing Inspections

EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" - SECTION(S)

- |                                                                      |    |
|----------------------------------------------------------------------|----|
| 1. FIRST FLOOR RIGHT FRONT - EXTERIOR WALL - replace missing siding. | 3a |
| 2. CELLAR STAIRS - replace broken tread.                             | 3d |
| 3. OVERALL EXTERIOR - FOUNDATION WALL - replace missing mortar.      | 3a |

~~4. Overall exterior - both clean up excessive soot in the cellar chimney and~~

FIRST FLOOR

- |                                                                                                                                                         |               |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| <del>5. Living Room &amp; Bedroom window - replace broken glass.</del>                                                                                  | <del>3a</del> |
| 6. BATHROOM - TUB - correct the condition at the fixture that causes a cross-connection at the bathtub.                                                 | 6d            |
| 7. RIGHT REAR, RIGHT FRONT, MIDDLE BEDROOMS AND LIVING ROOM - replace broken counter balance cords allowing window sash to remain elevated when opened. | 3c            |

SECOND FLOOR

At the time of the survey, we were unable to gain access to the second floor apartment. We suggest that if there are any conditions which need correcting in this apartment that you make the repairs while doing the work on the rest of the structure.

\* WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO THE ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

NOTICE OF HOUSING CONDITIONS X

DU 2

CITY OF PORTLAND  
 DEPARTMENT OF NEIGHBORHOOD CONSERVATION  
 HOUSING INSPECTIONS DIVISION  
 Telephone 775-5451 - Extension #448 - #358  
  
 Jacob Cerino  
 15 Cumberland Avenue  
 Portland, Maine 04101

Ch.-Bl.-Lot: 14-A-24  
 Location: 15 Cumberland Ave.  
 Project: Munjoy North  
 Issued: March 15, 1977  
 Expired: May 15, 1977

Dear Mr. Cerino:

An examination was made of the premises at 15 Cumberland Ave., Portland, Maine by Housing Inspector Stevenson. Violations of Municipal Codes relating to housing conditions were found as described in detail below.

In accordance with provisions of the above mentioned Codes, you are requested to correct these defects on or before May 15, 1977. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this Notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing.

Sincerely yours,

Joseph E. Gray, Jr., Director  
 Neighborhood Conservation

Inspector D. Stevenson  
 D. Stevenson

By Lyle D. Noyes  
 Lyle D. Noyes,  
 Chief of Housing Inspections

EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" - SECTION(S)

- |                                                                       |    |
|-----------------------------------------------------------------------|----|
| 1. FIRST FLOOR, FRONT FRONT - EXTERIOR WALL - replace missing siding. | 3a |
| 2. CELLAR STAIRS - replace broken tread.                              | 3d |
| 3. OVERALL EXTERIOR - FOUNDATION WALL - replace missing mortar.       | 3a |

~~4. CELLAR CHIMNEY - SOOT clean up excessive soot in the cellar chimney and~~

FIRST FLOOR

- |                                                                                                                                                         |               |
|---------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|
| <del>5. LIVING ROOM - BATHROOM WINDOW - replace broken glass.</del>                                                                                     | <del>3a</del> |
| 6. BATHROOM - TUB - correct the condition at the fixture that causes a cross connection at the bathtub.                                                 | 6d            |
| 7. RIGHT REAR, RIGHT FRONT, MIDDLE BEDROOMS AND LIVING ROOM - replace broken counter balance cords allowing window sash to remain elevated when opened. | 3c            |

SECOND FLOOR

At the time of the survey, we were unable to gain access to the second floor apartment. We suggest that if there are any conditions which need correcting in this apartment that you make the repairs while doing the work on the rest of the structure.

\* WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO THE ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

- 01 11 6/21/77  
NOTICE OF HOUSING CONDITIONS

DU 2

CITY OF PORTLAND  
 DEPARTMENT OF NEIGHBORHOOD CONSERVATION  
 HOUSING INSPECTIONS DIVISION  
 Telephone 775-5451 - Extension #448 - #358  
 Jacob Cerino  
 15 Cumberland Avenue  
 Portland, Maine 04101

Ch.-Bl.-Lot: 14-A-24  
 Location: 15 Cumberland Ave.  
 Project: Munjoy North  
 Issued: March 15, 1977  
 Expired: May 15, 1977

Dear **Mr. Cerino:**

An examination was made of the premises at 15 Cumberland Ave., Portland, Maine by Housing Inspector Stevenson. Violations of Municipal Codes relating to housing conditions were found as described in detail below.

In accordance with provisions of the above mentioned Codes, you are requested to correct these defects on or before May 15, 1977. You may contact this office to arrange a satisfactory repair schedule if you are unable to make such repairs within the specified time. We will assume the repairs to be in progress if we do not hear from you within ten days from this date and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with Code Standards. Please contact this office if you have any questions regarding this Notice.

Your cooperation will help this Department in its goal to maintain all Portland residents in decent, safe and sanitary housing.

Sincerely yours,  
 Joseph E. Gray, Jr., Director  
 Neighborhood Conservation

Inspector J. Stevenson

By \_\_\_\_\_  
 Lyle D. Noyes,  
 Chief of Housing Inspections

EXISTING VIOLATIONS OF CHAPTER 307 - "MINIMUM STANDARDS FOR HOUSING" -	SECTION(S)
1. FIRST FLOOR RIGHT FRONT - EXTERIOR WALL - replace missing siding.	3a
2. CELLAR STAIRS - replace broken tread.	3d
3. OVERALL EXTERIOR - FOUNDATION WALL - replace missing mortar.	3a
6/21 <del>4. CELLAR CHIMNEY - ROOF - clean up excessive soot in the cellar chimneys and dispose of it.</del>	<del>3e</del>
<u>FIRST FLOOR</u>	
6/21 <del>5. LIVING ROOM &amp; BATHROOM - WINDOW - replace broken glass.</del>	<del>3e</del>
6. BATHROOM - TUB - correct the condition at the fixture that causes a cross connection at the bathtub.	61
7. RIGHT REAR, RIGHT FRONT, MIDDLE BEDROOMS AND LIVING ROOM - replace broken counter balance cords allowing window sash to remain elevated when opened.	3c
6/21 <del>8. MIDDLE BEDROOM - WALL - remove taped electrical wire.</del>	<del>6e</del>
<u>SECOND FLOOR</u>	

At the time of the survey, we were unable to gain access to the second floor apartment. We suggest that if there are any conditions which need correcting in that apartment that you make the repairs while doing the work on the rest of the structure.

\* WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO THE ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTREME HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.



P 032 225 097

RECEIPT FOR CERTIFIED MAIL

NO INSURANCE COVERAGE PROVIDED  
NOT FOR INTERNATIONAL MAIL

(See Reverse)

Sent to Vin Salamone	
Street and No. 6 Richardson St.	
P.O. State and ZIP Code Portland, ME 04103	
Postage	\$
Certified Fee	
Special Delivery Fee	
Restricted Delivery Fee	
Return Receipt Showing to whom and Date Delivered	
Return receipt showing to whom, Date, and Address of Delivery	
TOTAL Postage and Fees	\$
Postmark or Date	

U.S.G.P.O. 1984-46-014

PS Form 3800, Feb. 1982

Re: - 6 Richardson St. - J. Torres - Housing

Form 3811, July 1983 447-945

15 Cumberland St. - J. Torres - Housing

**SENDER: Complete items 1, 2, 3 and 4.**  
Put your address in the "RETURN TO" space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check boxes for service(s) requested.

1.  Show to whom, date and address of delivery.

2.  Restricted Delivery

3. Article Addressed to:  
Vin Salamone  
6 Richardson St.  
Portland, ME 04103

4. Type of Service: Article Number  
 Registered  Insured  
 Certified  COD 225 097  
 Express Mail

Always obtain signature of addressee or agent and  
**DATE DELIVERED**

5. Signature - Addressee  
X *Vin Salamone*

6. Signature - Agent  
X

7. Date of Delivery  
3/15/89

8. Addressee's Address (ONLY if requested and fee paid)

DOMESTIC RETURN RECEIPT



CITY OF PORTLAND, MAINE

389 CONGRESS STREET  
PORTLAND, MAINE 04101  
(207)874-8300

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

P. SAMUEL HOFFSES, CHIEF  
INSPECTION SERVICES DIVISION

March 10, 1989

Vin Salamone  
6 Richardson Street  
Portland, ME 04103

Re: 15 Cumberland Ave. 14-A-24  
Apartment #1

Dear M. Salamone:

We recently received a complaint and an inspection was made by Code Enforcement Officer Joe Torres of the property owned by you at 15 Cumberland Ave., Apt. #1 Portland, Maine. As a result of that inspection, you are hereby ordered to correct the following substandard housing conditions:


1. INTERIOR 1ST. FLOOR, APT. #1 - FRONT DOOR - lock assembly missing. 108-3
2. INTERIOR 1ST. FLOOR, APT. #1 - ENTRANCE DOOR - door trim broken. 108-3
3. INTERIOR 1ST. FLOOR, APT. #1 - ENTRANCE DOOR - trim nails exposed. 108-3
4. INTERIOR 1ST. FLOOR, APT. #1 - LIVING ROOM FLOOR - broken places under rug. 108-2
5. INTERIOR 1ST. FLOOR, APT. #1 - LIVING ROOM WALLS - panels loose, open. 108-2
6. INTERIOR 1ST. FLOOR, APT. #1 - LIVING ROOM CLOSET - electrical wires exposed. 113
7. INTERIOR 1ST. FLOOR, APT. #1 - LIVING ROOM CLOSET - light fixture missing. 113
8. INTERIOR 1ST. FLOOR, APT. #1 - LIVING ROOM - wall panel missing. 108-2
9. INTERIOR 1ST. FLOOR, APT. #1 - WINDOWS - latch locks missing. 108-3
- \*10. INTERIOR 1ST. FLOOR, APT. #1 - BATHROOM - light inoperative. 113
11. INTERIOR 1ST. FLOOR, APT. #1 - BATHROOM CEILING - panels hanging loose. 108-2
12. INTERIOR 1ST. FLOOR, APT. #1 - BATHROOM - upstairs drain pipe has oversize hole on floor to basement. 108-2
- \*13. INTERIOR 1ST. FLOOR, APT. #1 - BATHROOM LIGHT - switch improperly wired. 113
14. INTERIOR 1ST. FLOOR, APT. #1 - CHILD'S BEDROOM WINDOW - latch lock missing. 108-3
15. INTERIOR 1ST. FLOOR, APT. #1 - CHILD'S BEDROOM - light fixture broken. 113
16. INTERIOR 1ST. FLOOR, APT. #1 - CHILD'S BEDROOM - plaster missing - holes. 108-2
17. INTERIOR 1ST. FLOOR, APT. #1 - OVERALL PAINT - chipping

\*WHEN MAKING YOUR REPAIRS, FIRST PRIORITY IS TO BE GIVEN TO ITEMS WITH ASTERISKS, AS THEY CONSTITUTE EXTENSIVE HAZARDS TO THE HEALTH OR SAFETY OF THE OCCUPANTS OF THIS STRUCTURE.

The above mentioned conditions are in violation of Article V of the Municipal Code of the City of Portland, Maine, and must be corrected on or before 4/3/89.

Failure to comply with this order may result in a complaint being filed for prosecution in District Court.

Sincerely,  
Joseph E. Gray, Jr., Director of  
Planning & Urban Development

By:   
P. Samuel Hoffses, Chief of Insp. Services

jmr

Joe Torres, Housing Inspector

CITY OF PORTLAND  
INSPECTION SERVICES DIVISION - HOUSING INSPECTION SCHEDULE

*Rough Draft*  
*Page 1 of 2*

Insp. Date: 3/6/89 Complaint 5 year Fire Inspector's Name JOE TORRES Dist.

TIM & BRENDA TROTT

Property Address: 15 CUMBERLAND AV. APT. 1 C-B-L: 14-A24 Leg. Units:  Exist. Units:  Stories:

Owner or Agent VIN SALAMONE Stand. Ist:  N.O.H.C.  L.O.D.   
Address 6 RICHARDSON ST.

Violation No.	Ext.	Int.	Fl.	Apt.	LOCATION	VIOLATION DESCRIPTION	CODE
1		X	1	1	FRONT DOOR	LOCK ASSEMBLY MISSING	108-3
2		X	1	1	ENTRANCE DOOR	DOOR TRIM BROKEN	108-3
3		X	1	1	ENTRANCE DOOR	DOOR TRIM NAILS EXPOSED	108-3
4		X	1	1	LIVING ROOM FLOOR	BROKEN PLACES UNDER RUG	108-2
5		X	1	1	LIVING ROOM WALLS	WALL PANELS LOOSE OPEN	108-2
6		V	1	1	LIVING ROOM CLOSET	ELECTRICAL WIRES EXPOSED	113
7		X	1	1	LIVING ROOM CLOSET	LIGHT FIXTURE MISSING	113
8		V	1	1	LIVING ROOM	WALL PANEL MISSING	108-2
9		X	1	1	<del>ALL</del> WINDOWS	LATCH LOCKS MISSING	108-3
*10		X	1	1	BATH ROOM	LIGHT INOPERATIVE	113
11		X	1	1	BATH ROOM (ceiling)	PANELS - HANGING LOOSE	108-2
12		X	1	1	BATH ROOM	UPSTAIRS DRAIN PIPE <del>HAS</del> HAS OVERSIZE HOLE ON FLOOR TO BASEMENT	108-2
13		X	1	1			
*14		X	1	1	BATH ROOM lite	Switch improperly WIRED !!	





**CITY OF PORTLAND**

DEPARTMENT OF PLANNING & URBAN DEVELOPMENT  
INSPECTION SERVICES DIVISION

March 11, 1990

James Somry  
58 Alice Street  
Portland, ME 04103

DU:

RE: 15 Cumberland Ave. 14-A-24

Dear Mr. Somry:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above referenced property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,  
Joseph E. Gray, Jr., Director  
Planning & Urban Development

*[Signature]*  
By: Samuel Hoff  
Chief of Inspection Services

*[Signature]*

Code Enforcement Officer  
Burton G. MacIsaac (1)

jmr



Inspection Services  
Samuel P. Hoffses  
Chief



Planning and Urban Development  
Joseph E. Gray Jr.  
Director

CITY OF PORTLAND

March 17, 1994

SOMMA JAMES G  
58 ALICE ST  
PORTLAND ME 04103

GUIMOND WHALEN  
20 UPLAND ST  
PORTLAND ME 04103

Re: 15 Cumberland Ave  
CBL: 014- - A-024-001-01  
DU: 5

Dear Sirs,

You are hereby notified, as owner or agent, that an inspection was made of the above referenced property. Violations of Article V of the Municipal Ordinance (Housing Code) were found as described in detail on the attached "Housing Inspections Report".


In accordance with the provisions of the above mentioned code, you are hereby ordered to correct those defects within sixty (60) days. If you are unable to make such repairs within the specified time, you may contact this office to arrange a satisfactory repair schedule. If we do not hear from you within ten (10) days from this date, we will assume the repairs to be in progress and, on re-inspection within the time set forth above, will anticipate that the premises have been brought into compliance with the Housing Code standards.


Please Note: You should consult this department to insure that any corrective action you should undertake complies with the building, plumbing, electrical, zoning and other Articles of the City code.

Please contact this office if you have any questions regarding this order.

Your cooperation will aid this department in its goal to maintain decent, safe, and sanitary housing for all of Portland's residents.

Sincerely,

  
Merlin Leary  
Code Enforcement officer

  
Samuel P. Hoffses  
Chief of Inspection Services

HOUSING INSPECTION REPORT

Location: 15 Cumberland Ave  
Housing Conditions Date: March 17, 1994  
Expiration Date: May 16, 1994

Items listed below are in violation of Article V of the Municipal Codes, "Housing Codes", and must be corrected before the expiration date:

1.	EXT - FIRE ESCAPE - MISSING BALUSTER	116.20
2.	INT - UTILITY ROOM - TEMPORARY LIGHTING	113.50
3.	INT - CELLAR - STAIRS MISSING RAILING	108.20
4.	INT - BASEMENT - BATHROOM LACK OF VENTILATION	112.00
5.	INT - 2ND FL/APT 2 - BATHROOM LACK OF VENTILATION	112.00
6.	INT - 3RD FL/APT 3 - FRONT STAIRS MISSING RAILING	108.20
7.	INT - 3RD FL/APT 3 - REAR EXIT OBSTRUCTED EGRESS	116.20
8.	INT - 3RD FL/APT 3 - FRONT HALL USED FOR STORAGE	116.40

PRIORITY VIOLATION NUMBER(S):  
2 4 5 7

Inspection Services  
Samuel P. Hoffses  
Chief



Planning and Urban Development  
Joseph E. Gray Jr.  
Director

CITY OF PORTLAND

September 30, 1994

SOMMA JAMES G  
58 ALICE ST  
PORTLAND ME 04103

Re: 15 Cumberland Ave  
CBL: 014- - A-024-001-01  
DU: 5

Dear Mr. Somma:


A re-inspection at the above noted property was made on September 28, 1994.


This is to certify that you have complied with our request to correct the violation(s) of the Municipal Code relating to housing conditions noted on our letter dated March 17, 1994.

Thank you for your cooperation and your efforts to help us maintain decent, safe and sanitary housing for all Portland residents.

In order to aid in the preservation of Portland's existing housing inventory, it shall be the policy of this department to inspect each residential building at least once every three years.

Sincerely,

  
Merlin Leary  
Code Enforcement Officer

  
Marge Schmuckal  
Asst. Chief of Inspection Services

Inspection Services  
P. Samuel Hoffses  
Chief



Planning and Urban Development  
Joseph H. Gray Jr.  
Director

CITY OF PORTLAND

NOVEMBER 27, 1996

CRUMP, J. THOMAS  
PO BOX 10179  
PORTLAND, ME 04104

Re: 15 CUMBERLAND AVE  
CBL: 014--A-024-001-01  
DU: 5

Dear Mr. Crump:

The Housing Inspections Division of the Department of Planning and Urban Development has recently completed an overall inspection of the above-referenced property.

Congratulations are extended to you for the general condition of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely,

Handwritten signature of Marland Wing in cursive.

Marland Wing  
Code Enforcement Officer

Handwritten signature of Tammy Munson in cursive.

Tammy Munson  
Code Enfc. Offr. / Field Supv.