cowles studio | landscape architecture

Level I – Minor Residential Development Review King-Clements Residence 46 Merrill Street Portland, ME 04101 09-19-2017

Book/Page 34090/213 CBL 014 C008001

Proposed construction at 46 Merrill Street is comprised of a single family, multi-story home. The currently vacant site is located in the R-6 Zone, and consists of HB soils* (gravelly sandy loam), and slopes at roughly 5% from the highest portion (rear) of the property towards Merrill Street. Proposed grading and drainage is designed to encourage infiltration, and to comply with applicable sections of the Portland Stormwater Management Standards and MDEP Chapter 500 Standards. A silt fence (or sediment barrier) shall be employed throughout construction to prevent runoff, and proposed landscaping shall commence upon completion of the home construction.

As proposed, the majority of surfaces on site are sloped at no greater than 3% to encourage groundwater recharge. Similarly, an underdrain (4" perforated pipe) is proposed below the Peastone Terrace which is designed to capture stormwater as it percolates, conveying it to the north side of the house into a infiltration basin/ rain garden.

Proposed landscaped areas (L/A) are noted on sheet L-3.0, and shall be landscaped with a combination of trees, shrubs, groundcover, and perennials. The Plant List will be finalized with the Owner in the upcoming weeks, and if necessary, can be provided to City Staff for review.

Site Calculations

3,890 SF Total Lot Size (0.089 Acres)

1677 SF KBA Architectural Footprint (43% of Entire Site)

Impervious Surface (Proposed)

150 SF Driveway 227 SF Pavers 64 SF Steps

44 SF Seat Walls/Retaining Walls

485 SF (13% of Entire Site)

Permeable

220 SF Peastone Terrace (permeable) 91 SF Stone Drip Edge (permeable)

604 SF Landscape Beds

180 SF Filter Strip/Planting area

633 SF Lawn

1,728 SF (44% of Entire Site)

Tony Cowles

Maine Licensed Landscape Architect

cowles studio | landscape architecture

(207) 415-4332 www.cowles-studio.com

^{*}According to USDA Soil Survey- Cumberland County, Maine