COPYRIGHT: Reuse or reproduction of the contents of this document is not permitted without written permission of Bild Architecture LLC

SECTION J/S2.1 1 1/2"=1'-0

SECTION K/S2.1 3/4"=1'-0

SECTION I/S2.1 3/4"=1'-0

SECTION E/S2.1 1 1/2"=1'-0

SECTION F/S2.1 3/4"=1'-0

SECTION G/S2.1 3/4"=1'-0

SECTION H/S2.1 3/4"=1'-0

NOTE: DO NOT BACK FILL BASEMENT WALLS UNTIL SLAB AND MAIN LEVEL FLOOR IS IN PLACE. IF BACK FILL NEEDS TO HAPPEN PRIOR, SHORE FND WALLS ACCORDINGLY

SECTION A/S2.1 3/4"=1'-0

SECTION B/S2.1 3/4"=1'-0

SECTION C/S2.1 3/4"=1'-0

SECTION D/S2.1 3/4"=1'-0

Structural Integrity Consulting Engineers, Inc.

77 Oak Street
Portland, ME, 04101
p. 207-774-4614
f. 866-793-7835
www.structuralinteg.com

BUILD WITH CONFIDENCE

© 2012 Structural Integrity Consulting Engineers, Inc.

SI# 17-0043

CITY OF PORTLAND, MAINE — RESURGAM

Reviewed for Code Compliance
Inspections Division
Approved with Conditions

Date: 10/27/17

REVISIONS
1 3/15/2017 CD
2
3
4
5

PROJECT NO.
16035
PROJECT NAME
7 CUMBERLAND
PORTLAND, ME

DRAWN BY
MKL
SHEET TITLE
SECTIONS

ISSUE DATE
8/8/17
SHEET SCALE
AS NOTED

S

S2.1