| Form # P 04 DISPLAY THIS CAR   | ID ON PRINCIPAL FRONTAG   | E OF WORK  |
|--|---|--|
| Please Read<br>Application And<br>Notes, If Any,<br>Attached   | DUE DING UNSPECTION   | PERMIT ISSUED<br>ermit Number: 061417<br>FEB - 1 2007  |
| This is to certify that BRADSTREET SHANE K   | ane Bradstreet  |  |
| has permission to Restoration & remodel after  |   | CITY OF PORTLAND   |
| AT 29 MERRILL ST   | L 014 F0010   | 001  |
| provided that the person or persons<br>of the provisions of the Statutes of<br>the construction, maintenance and<br>this department. | aine and of the Provinances of the<br>e of buildings and suctures, and  |  |
| Apply to Public Works for street line<br>and grade if nature of work requires<br>such information.                                   | pre this ilding of a rt there is provide the provide the second | certificate of occupancy must be<br>rocured by owner before this build-<br>ig or part thereof is occupied. |
| OTHER REQUIRED APPROVALS<br>Fire Dept  | Rin   | Lember 2/1/07<br>Director - Building & Inspection Services   |

### PENALTY FOR REMOVING THIS CARD

 $\sim$ 

| Location of Construction:   |  | Owner Name:           |             |   | Owner   | Address:                |                 |             | Phone:        |          |
|---|--|-----------------------|-------------|---|---------|-------------------------|-----------------|-------------|---------------|----------|
| 29 MERRILL ST   |  | BRADSTREE             | T SHA       | NE K  | 29 M    | ERRILL ST               | 7               |             |               |          |
| Business Name:  |  | Contractor Name       | ne:         |   | Contra  | Contractor Address:     |                 |             | Phone         |          |
|   |  | Shane Bradstr         | eet         |   | 29 M    | errill Portla           | nd              |             | 20732919      | 971      |
| Lessee/Buyer's Name   |  | Phone:                |             |   | Permit  | Туре:                   |                 |             |               | Zone     |
|   | <u></u>                                  |                       |             |   | Alte    | rations - Mu            | ılti Family     | . <u></u>   |               | R        |
| Past Use:   |  | Proposed Use:         |             |   | Permi   | t Fee:                  | Cost of Work:   | CEO         | District:     | 7        |
| 3 unit residential  |  | 3 Unit Resider        |             | storation &                                 |         | \$1,580.00              | \$156,000       |             | 1             |          |
|   |  | remodel after         | fire        |   | FIRE    | DEPT:                   | - ADDIOYCU I    | NSPECTIO    |               | m        |
| 1284  | 1036-                                    | 3 dwelling v          | nt          |   |         |                         | Denied          | Use Group:  | 22            | Туре:    |
| · · · · · · · · · · · · · · · · · · ·                               | • - • -                                  | j in ing i            |             |   | Se      | e Cin                   | diture          | TB          | 1-70          | <b>5</b> |
| Proposed Project Description:                                       |  | L                     |             |   | -       |                         |                 | + T         | _ 220         |          |
| Restoration & remodel after f                                       | īre                                      |                       |             |   | Signat  | ure:                    | ditures<br>Case | Signature   | MBZ           | 2/10     |
|   |  |                       |             |   |         |                         | IVITIES DISTR   |             | .)            | ff       |
|   |  |                       |             |   | Action  | : Appro                 | ved Appro       | oved w/Cond | itions        | Denie    |
|   |  |                       |             |   |         |                         | L.]             |             | L /           |          |
| Dorreit Talver Dav  | Data Ar                                  | - Had Par             | <del></del> |   | Signat  |                         |                 | Date        |               |          |
| Permit Taken Ey:<br>ldobson   |  | oplied For:<br>7/2006 |             |   |         | Zoning                  | g Approval      |             |               |          |
| 1. This permit application d  |  |                       | Spe         | cial Zone or Revi                           | ews     | Zoni                    | ng Appeal       | Н           | istoric Pres  | ervatio  |
| Applicant(s) from meetin<br>Federal Rules.                          |  |                       |             |   |         | Varianc                 |                 |             | lot in Distri | ct or La |
| 2. Building permits do not i septic or electrical work.             | nclude j                                 | olumbing,             | □ w         | oreland<br>etland المن<br>مم كرمو Zone محمل | X       | Miscell                 | aneous          | [] [] [     | Does Not Re   | quire R  |
| 3. Building permits are voic within six (6) months of t             | he date                                  | of issuance.          | Flo         | bod Zone                                    |         | Conditi                 | onal Use        | [] F        | Requires Rev  | view     |
| False information may in permit and stop all work.                  |  | a building            | 🔲 Su        | bdivision                                   |         | Interpre                | etation         | [] A        | Approved      |          |
|   |  |                       | 🗌 🗌 Sit     | e Plan                                      |         |                         | ed              | [ ] A       | xpproved w/   | Conditi  |
| PEPE,   | 1391                                     | JED                   | Maj [       | ] Minor [] MM                               |         | Denied                  |                 | [] [        | Denied        |          |
|   | an a |                       | 142         | 410001100/<br>9127106                       | TAN     |                         |                 |             | hen           |          |
|   | - 1 20                                   | 07                    | Date:       | 9122/06                                     | N. (    | Date:                   | TOTALT IS       | Date:       |               |          |
| : /   |  |                       |             |   |         |                         | PERMIT IS       | SUFD        |               |          |
|   | FORT                                     | LAND                  |             |   |         |                         | <b>FE</b> B - 1 | 2007        |               |          |
|   |  |                       |             |   |         |                         |                 |             |               |          |
| I hereby certify that I am the o                                    |  | • • •                 | . C         | ERTIFICATI                                  | ON      | L CIT                   | Y OF POR        | TLAND       |               |          |
| I hereby certify that I am the o<br>I have been authorized by the o | wner of                                  | record of the na      | med pro     | perty, or that t                            | he prop | os <del>ed work i</del> | s authorized b  | v me owne   | er of fecor   | d and    |
| 1 HAVE DEED AUHUHZEU DV 188 (                                       | JWHEI IC                                 | r make uns appli      | ication a   | is ins authorize                            | u agent | and r agree             | to conform to   | ан арриса   | able laws     | of this  |

| SIGNATURE OF APPLICANT                      | ADDRESS | DATE | PHONE |
|---|---------|------|-------|
| RESPONSIBLE PERSON IN CHARGE OF WORK, TITLE |         | DATE | PHONE |

· -

| •  |  | (207) 874 8716   |   | 6   |
|--|--|--|---|---|
| 389 Congress Street, 04101   | Tel: (207) 874-8703, Fax:  | (207) 874-8710   | 06-1417 09/27/200   | 014 F001001   |
| Location of Construction:  | Owner Name:  | Owner Ad   | dress:  | Phone:  |
| 29 MERRILL ST  | BRADSTREET SHA   | NE K 29 MER  | RILL ST   |   |
| Business Name:   | Contractor Name:   | Contracto  | r Address:  | Phone   |
|  | Shane Bradstreet   |  | ill Portland  | (207) 329-1971  |
| Lessee/Buyer's Name  | Phone:   | Permit Ty  |   |   |
|  |  | Alterati   | ons - Multi Family  |   |
| Proposed Use:<br>3 Unit Residential- Restoration   |  | Proposed Project   | Description:<br>emodel after fire   |   |
|  |  |  |   |   |
| Dept: Zoning Sta<br>Note:  | itus: Approved with Conditio   | ns <b>Reviewer:</b> Ann M  | achado App  | roval Date: 09/27/2006<br>Ok to Issue: 🗹  |
|  |  |  |   |   |
| 1) This property shall remain approval.  | as three family dwellings. Any   | change of use shall requi  | re a separate permit ap   | plication for review and  |
| approval.  | as three family dwellings. Any<br>I with the understanding that al   | с .  |   |   |
| <ul><li>approval.</li><li>2) This permit is being issued</li></ul>   |  | l work is being done with  | n the existing footprin   | t and shell of the building.  |
| <ul><li>approval.</li><li>2) This permit is being issued</li><li>3) This permit is being approvide work.</li></ul>   | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition  | l work is being done with itted. Any deviations sha  | n the existing footprin<br>l require a separate ap  | t and shell of the building.  |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being approvided approvi</li></ul> | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition<br>10/24/06<br>nterior reconstruction, this doe  | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer: J</b> eaning   | n the existing footprin<br>l require a separate ap<br>Bourke App  | •<br>t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ☑  |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being appro-<br/>work.</li> <li>Dept: Building Sta<br/>Note: received from fire on</li> <li>1) This permit approves the in<br/>and approvals are required</li> <li>2) Separate permits are required</li> </ul>   | with the understanding that al<br>ved on the basis of plans subm<br>tus: Approved with Condition<br>10/24/06<br>nterior reconstruction, this doe<br>for such.  | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer:</b> Jeaning<br>s not approve a rooftop de<br>g, or HVAC systems.   | n the existing footprin<br>l require a separate ap<br>Bourke App  | •<br>t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ☑  |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being appro-<br/>work.</li> <li>Dept: Building Sta<br/>Note: received from fire on</li> <li>1) This permit approves the in<br/>and approvals are required</li> <li>2) Separate permits are required</li> </ul>   | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition<br>10/24/06<br>nterior reconstruction, this doe<br>for such.<br>red for any electrical, plumbing<br>to be submitted for approval as  | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer:</b> Jeaning<br>s not approve a rooftop de<br>g, or HVAC systems.<br>a part of this process.  | n the existing footprin<br>l require a separate ap<br>Bourke App<br>eck or 4th story additio  | t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ☑<br>n. Separate application  |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being approwork.</li> <li>Dept: Building Sta</li> <li>Note: received from fire on</li> <li>1) This permit approves the in and approvals are required</li> <li>2) Separate permits are required</li> <li>2) Separate permits are required</li> <li>3) As discussed, hardwired in and on every level.</li> <li>4) All penetrations between d</li> </ul>  | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition<br>10/24/06<br>interior reconstruction, this doe<br>for such.<br>red for any electrical, plumbing<br>b be submitted for approval as<br>iterconnected battery backup su   | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer:</b> Jeaning<br>s not approve a rooftop de<br>g, or HVAC systems.<br>a part of this process.<br>noke detectors shall be in<br>ts and common areas shal                            | in the existing footprin<br>I require a separate ap<br>Bourke App<br>e Bourke App<br>eck or 4th story additions   | t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ✓<br>n. Separate application<br>, protecting the bedrooms,  |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being appro-<br/>work.</li> <li>Dept: Building Sta<br/>Note: received from fire on</li> <li>1) This permit approves the in<br/>and approvals are required</li> <li>2) Separate permits are required</li> <li>2) Separate permits are required</li> <li>3) As discussed, hardwired in<br/>and on every level.</li> <li>4) All penetrations between d<br/>and recessed lighting/vent</li> <li>Dept: Fire Sta</li> </ul>  | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition<br>10/24/06<br>nterior reconstruction, this doe<br>for such.<br>red for any electrical, plumbing<br>b be submitted for approval as<br>iterconnected battery backup su<br>welling units and dwelling uni<br>fixtures shall not reduce the (1<br><b>tus:</b> Approved with Condition   | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer:</b> Jeaning<br>s not approve a rooftop de<br>g, or HVAC systems.<br>a part of this process.<br>noke detectors shall be in<br>ts and common areas shall<br>hour) required rating. | n the existing footprin<br>l require a separate ap<br>Bourke <b>App</b><br>eck or 4th story additions<br>stalled in all bedrooms<br>be protected with app | t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ✓<br>n. Separate application<br>, protecting the bedrooms,  |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being appro-<br/>work.</li> <li>Dept: Building Sta<br/>Note: received from fire on</li> <li>1) This permit approves the in<br/>and approvals are required</li> <li>2) Separate permits are required</li> <li>2) Separate permits are required</li> <li>3) As discussed, hardwired in<br/>and on every level.</li> <li>4) All penetrations between d<br/>and recessed lighting/vent</li> <li>Dept: Fire Sta</li> </ul>  | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition<br>10/24/06<br>interior reconstruction, this doe<br>for such.<br>red for any electrical, plumbing<br>b be submitted for approval as<br>iterconnected battery backup su-<br>welling units and dwelling uni-<br>fixtures shall not reduce the (1<br><b>tus:</b> Approved with Condition<br>ect requires structure to be bro    | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer:</b> Jeaning<br>s not approve a rooftop de<br>g, or HVAC systems.<br>a part of this process.<br>noke detectors shall be in<br>ts and common areas shall<br>hour) required rating. | n the existing footprin<br>l require a separate ap<br>Bourke <b>App</b><br>eck or 4th story additions<br>stalled in all bedrooms<br>be protected with app | t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ☑<br>n. Separate application<br>, protecting the bedrooms,<br>roved firestop materials,                           |
| <ul> <li>approval.</li> <li>2) This permit is being issued</li> <li>3) This permit is being approwork.</li> <li>Dept: Building Sta</li> <li>Note: received from fire on</li> <li>1) This permit approves the in and approvals are required</li> <li>2) Separate permits are required</li> <li>2) Separate permits are required</li> <li>3) As discussed, hardwired in and on every level.</li> <li>4) All penetrations between d and recessed lighting/vent</li> <li>Dept: Fire Sta</li> <li>Note: Size and scope of proj</li> </ul>   | I with the understanding that al<br>ved on the basis of plans subm<br>itus: Approved with Condition<br>10/24/06<br>interior reconstruction, this doe<br>for such.<br>red for any electrical, plumbing<br>to be submitted for approval as<br>iterconnected battery backup su<br>welling units and dwelling uni<br>fixtures shall not reduce the (1<br>tus: Approved with Condition<br>ect requires structure to be bro<br>system. | l work is being done with<br>itted. Any deviations sha<br>ns <b>Reviewer:</b> Jeaning<br>s not approve a rooftop de<br>g, or HVAC systems.<br>a part of this process.<br>noke detectors shall be in<br>ts and common areas shall<br>hour) required rating. | n the existing footprin<br>l require a separate ap<br>Bourke <b>App</b><br>eck or 4th story additions<br>stalled in all bedrooms<br>be protected with app | t and shell of the building.<br>proval before starting that<br>roval Date: 02/01/2007<br>Ok to Issue: ☑<br>n. Separate application<br>, protecting the bedrooms,<br>roved firestop materials,<br>roval Date: 09/27/2006 |

#### **Comments:**

10/24/2006-jmb: Spoke to Shane B., need details on 1.sound transmission of rated walls & ceilings

2. guardrails/handrails associated with refurbished stairs
 3. Noting all fire doors

- 4. Note on fire penetrations and code compliance
- 5. Details on new stairs to roof
- 6. 100lbs. Load on roof top deck
- 7. Hatchway details/safety

| Location of Construction: | Owner Name:      |      | Owner Address:             | Phone:         |
|---------------------------|------------------|------|----------------------------|----------------|
| 29 MERRILL ST             | BRADSTREET SHAN  | NE K | 29 MERRILL ST              |                |
| Business Name:            | Contractor Name: |      | Contractor Address:        | Phone          |
|                           | Shane Bradstreet |      | 29 Merrill Portland        | (207) 329-1971 |
| Lessee/Buyer's Name       | Phone:           |      | Permit Type:               |                |
|                           |                  |      | Alterations - Multi Family |                |

8. Hardwired smokes

10/27/2006-jmb: Received addendum letter...no information on the deck and the separation walls show not STC rating or UL listing. Need more details on roof hatch and code compliant stairs.

11/15/2006-jmb: Shane B. Came in to inquire about permit and to verify that the deck is not going to be with this permit. He will call the architect and get info on the walls

12/1/2006-jmb: Contacted Shane on submittals from 11/30...need wall assembly info and design pro to determine a listing....still need roof hatch details to code.

1/29/2007-jmb: Shane Bradstreet came in to submit structural plans from Shelley Eng. I asked for pdf files or 11x17 reduction. The additional structural reinforcement is for a future 4th floor expansion, which will NOT be approved on this permit. Also need the details on the common and separating wall sound transmission.

2/1/2007-jmb: Shane B. Came in with the specs on the common wall construction that meet STC 50 and 1 hour rating, ok to issue


## BUILDING PERMIT INSPECTION PROCEDURES Please call 874-8703 or 874-8693 to schedule your inspections as agreed upon

Permits expire in 6 months, if the project is not started or ceases for 6 months.

The Owner or their designee is required to notify the inspections office for the following inspections and provide adequate notice. Notice must be called in 48-72 hours in advance in order to schedule an inspection:

By initializing at each inspection time, you are agreeing that you understand the inspection procedure and additional fees from a "Stop Work Order" and "Stop Work Order Release" will be incurred if the procedure is not followed as stated below.

A Pre-construction Meeting will take place upon receipt of your building permit.



Certificate of Occupancy is not required for certain projects. Your inspector can advise you if your project requires a Certificate of Occupancy. All projects **DO** require a final inspection


If any of the inspections do not occur, the project cannot go on to the next phase, REGARDLESS OF THE NOTICE OR CIRCUMSTANCES.

<u><u><u>A</u></u> CERIFICATE OF OCCUPANICES MUST BE ISSUED AND PAID FOR, BEFORE THE SPACE MAY BE OCCUPIED</u>

| / | Sh & Dh                               | 2-1-7       |
|---|---------------------------------------|-------------|
| ` | Signature of Applicant/Designee       | Date 2/1/07 |
|   | Signature of Inspections Official     | Date        |
|   | CBL: <u>14-F-1</u> Building Permit #: | 06-1417     |

## Typical Wall Assemblies

## Single Wood Stud Walls



Single 2x4 wood studs, 16" o.c., single layer 1/2" gypsum board each side, one thickness (3%- 4") fiber glass batt insulation.

| STC-45 | (Figure                                 |
|--------|---|
|        | Âh                                      |
|        | <i>.</i>                                |
|        |   |
|        |   |
|        | 000000000000000000000000000000000000000 |

Single 2x4 wood studs, 16" o.c., double layer 2" Type X gypsum board each side, one thickness (3%-4") fiber glass batt insulation.


Fire rating - 1 hr.

Balanced Finish

3)

|         | <b>F</b>  | Ft_1_4_9       |           | Fire Rating                            |
|---------|---|----------------|-----------|--|
|         | Construction  | Finish*        | STC       | ······································ |
| 1A      | " GB<br>No insulation                                 | Single         | 35        | % hr.                                  |
| 1B      | %" Type X GB<br>No insulation                         | Single         | 34        | t he                                   |
| 1C      | %" Type X GB<br>(3½"-4") fiber glass                  | Single<br>batt | 38 (cst.) | t hr.                                  |
| 10      | Studs 24" o.c.<br>%" Type X GB<br>(3%"4") fiber glass | Single<br>batt | 10 (cst.) | 1 hr.                                  |
| \$TC-40 |   |                | (         | (Figure 2                              |
| ¢.      |   |                |           |  |

Variation Construction Finish\* STC Fire Rating " Type X GB No insulation 3٨ Balanced 39 1 hr. (cst.) 3B Studs 24" o.c. Balanced 39 1 hr. (est.) X" Type X GB No insulation



Single 2x4 wood studs, 16" o.c., with resilient channel, single layer %" Type X gypsum each side, one thickness (3/2"- 4") fiber glass batt insulation.

| Fire ratir | ig - 1 hr.  |                     | ;   | Single Finish |
|------------|---|---------------------|-----|---------------|
| Variation  | Construction  | Finish <sup>4</sup> | STC | Fire Rating   |
| 4A         | %" GB<br>No insulation                                | Single              | 39  | NR            |
| 4B         | %" Type X GB<br>No insulation                         | Single              | 40  | 1 hr.         |
| 4C         | %" GB<br>(3%"-4") fiber gl <u>as</u>                  | Single<br>s batt    | 47  | NR            |
| 1D         | Studs 24" o.c.<br>%"Type X GB<br>(34"-4") fiber glass | Single              | 52  | l hr.         |


Single 2x4 wood studs, 16" o.c., single layer ½" gypsum board one side, double layer other side, one thickness (3%'-4") fiber glass batt insulation.

| Fire rating - NR |  | Unbalanced Finish |           |                |
|------------------|--|-------------------|-----------|----------------|
| Variation        | Construction                             | Finish*           | STC       | Fire Rating    |
| 2A               | X" GB<br>No insulation                   | Unbal.            | 38        | NR             |
| 2B               | %" Type X GB<br>No insulation            | Unbil.            | 38 (cst.) | ) 1 hr. (cst.) |
| <b>2</b> C       | %" Type X GB<br>(3½"-4") fiber glass bau | Unbal.<br>t       | 41        | 1 hr. (est.)   |

Univalanced - one wall finish one side, two wall haisbes other side Single - one wall finish each side. Relanced - Two mishes each side. Partitions with STC ratings within 1-2 points of the listed criteria are acceptable given the anticipated informates in repeat tests. In fact, discrepancies between testing labs of 1-2 dB on identical configurations are not gausual. (Subjectively, the human car would consider a 1-2 dB change as 'non-discernible' at best, which is insignificant.)

8


# 



2% metal studs (25 gauge), 24" o.c., single layer % gypsum board each side, one thickness (2%"-2%") fiber glass batt insulation.

| Fire rating - NR |                                      |                   | Single Fi |             |  |  |
|------------------|--------------------------------------|-------------------|-----------|-------------|--|--|
| Variation        | Construction                         | Finish*           | STC       | Fire Rating |  |  |
| 13A              | % GB<br>No insulation                | Single            | 36        | NR          |  |  |
| 13B              | %" Type X GB<br>No insulation        | Single            | 39        | t hr.       |  |  |
| 13G              | %" Type X GB<br>(2%"-2%") fiber glas | Single<br>is batt | 17        | 1 br.       |  |  |

STC-50




2½" metal studs (25 gauge), 24" o.c., double layer ½" gypsum board each side, one thickness (2½"-2¾") fiber glass batt insulation.

| Variation | Construction                         | Finish*            | \$TC | Fire Rating |
|-----------|--------------------------------------|--------------------|------|-------------|
| 15.4      | 2" Type X GB<br>No insulation        | Bulanced           | 45   | 2 hr.       |
| 15B       | %" Type X GB<br>No insulation        | Balanced           | 48   | 2 hr.       |
| 150       | %" Type X GB<br>(2%"-2%") fiber glas | Balanced<br>s batt | 57   | Z hr.       |

STC-47

(Figure 14)

(Figure 16)



3%" metal studs (25 gauge), 24" o.c., single layer ½" Type X gypsum board each side, one thickness (3%-- 4") fiber glass batt insulation.

| Fire rating - 1 hr. | Single Finish |
|---------------------|---------------|
|                     |               |

| Variatio | on Construction                      | Finish*         | STC | Fire Rating |
|----------|--------------------------------------|-----------------|-----|-------------|
| 164      | 2" GB<br>No insulation               | Single          | 39  | NR          |
| 16B      | %" Type X GB<br>No insulation        | Single          | 39  | 1 hr.       |
| 16C      | %" Type X GB<br>(3½"-4") fiber glass | Single<br>batt, | 50  | t hr.       |

24" metal studs (25 gauge), 24" o.c., single layer ½" gypsum board each side, double layer other side, one thickness (2½"-2¾") fiber glass batt insulation.

| Fire rating - NR |                                      |                   | Unbalanced Finish |             |
|------------------|--------------------------------------|-------------------|-------------------|-------------|
| Variation        | Construction                         | Finish*           | STC               | Fire Rating |
| 141              | %" GB<br>No insulation               | Unbal.            | 39                | NR          |
| 14B              | %" Type X GB<br>No insulation        | Unbal.            | 44                | 1 ht.       |
| 14C              | %" Type X GB<br>(2%"-2%") fiber glas | Unbal.<br>5 bart. | 52                | I hr.       |

\* Single - one wall finish each side Unbalanced - one wall finish one side, two wall finishes other side Balanced - two wall finishes each side.



## **General Building Permit Application**

If you or the property owner owes real estate or personal property taxes or user charges on any property within the City, payment arrangements must be made before permits of any kind are accepted.

| Location/Address of Construction: 29   | Mernill st, Portland  | ME OHIOI                            |
|--|---|-------------------------------------|
| Total Square Footage of Proposed Structure   | Square Footage of Lot   |                                     |
| 1644 59 ft   |   | ,380 ACR                            |
| Tax Assessor's Chart, Block & Lot  | Owner:  | Telephone:                          |
| Chart# Block# Lot#   | Shane Bradstreet  | 207-329-1971                        |
| Lessee/Buyer's Name (If Applicable)  | Applicant name, address & telephone:  | Cost Of                             |
|  | 29 merrill st   | Work: \$_156,000.                   |
|  | Portland ME 04101   | Work: \$_156,000.**<br>Fee: \$_1580 |
|  |   | C of O Fee: <b>\$</b>               |
| Current Specific use:Owner Occup   | ied 3 UNIT  |                                     |
| If vacant, what was the previous use?  | rent living and Benhal of 2   | Units                               |
| Proposed Specific use: Living and ?  | Unit Rintal   |                                     |
| Project description: Restonation/Re  | modeling often Fire damag   | A Junits TONY                       |
|  |   | E BUILDIN TLAND                     |
| Oct 25,06  | DEPT  | SEP 26 2005                         |
| Contractor's name, address & telephone:  | \ <b>z</b> _ \ <b>z</b> _ \ <b>z</b> \ <b>z</b> \ <b>z</b> _ \ <b>z</b> _ \ <b>z</b> \ <b>z</b> _ \ <b>z</b> \ | 2000                                |
|  |   | SEP 50                              |
| Who should we contact when the permit is read  | dy: Shane ISrads Treex  |                                     |
| Mailing address:   | Phone: <u>107-519-1971</u>  | SEP LOENED                          |
|  | 29 MERNIIST   |                                     |
|  | · · · · ·   |                                     |
|  | Perpland ME 04101   |                                     |
|  |   |                                     |
| Please submit all of the information out<br>Failure to do so will result in the automa | lined in the Commercial Application   |                                     |

In order to be sure the City fully understands the full scope of the project, the Planning and Development Department may request additional information prior to the issuance of a permit. For further information visit us on-line at <u>www.portlandmaine.gov</u>, stop by the Building Inspections office, room 315 City Hall or call 874-8703.

I hereby certify that I am the Owner of record of the named property, or that the owner of record authorizes the proposed work and that I have been authorized by the owner to make this application as his/her authorized agent. I agree to conform to all applicable laws of this jurisdiction. In addition, if a permit for work described in this application is issued, I certify that the Code Official's authorized representative shall have the authority to enter all areas covered by this permit at any reasonable hour to enforce the provisions of the codes applicable to this permit.

Date: 9-12-6 Signature of applicant:


This is not a permit; you may not commence ANY work until the permit is issued.

|  |  | RE DECTRONS  | היא וחקה   |
|--|--|--|--|
| ALREID   |  | HE RESIDENCE ZONE  | PERMIT ISSUE   |
|  |  | ION FOR PERMIT   | DECUISO  |
| CI   | lass of Building or Type of S  | 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1  |  |
|  | Purtland,  | Maine, December 9, 1960  | MARY 21 Marshe   |
| To the INSPECTO  | OR OF BUILDINGS, PORTI   | AND, MAINE   | i i i i i ka Arija, je   |
| in accordance with t<br>specifications, if any   | the Laws of the State of Main<br>y, submitted herewith and the f   | it to crect alter repair demolish in stall the following<br>e, the Building Code and Zoning Ordinance of the<br>following specifications:  |  |
| Location 29 Me   |  | Within Fire Limits?  |  |
| Owner's name and   | address Walter Gerry   | y, Old Orchard Beach, Maine  |  |
| Lessee's name and  | address  | lar GE Cumbonland Arm  | Telephone  |
| Contractor's name  |  | ley, 85 Cumberland Ave.  |  |
|  |  | Specifications   |  |
|  | lding 24 /   | partnent house   |  |
| Last use   | ······   |  | No. families <u>3</u>  |
| Material Irane   | No. stories  | tStyle of roof   | Kooing   |
| -  |  | 1991 - S. B., 1981, 1981 - 1992 - 1992 - 1994 - 1997 - 199 |  |
| Estimated cost \$_2  |  | and the second   | Fee \$2_00   |
| · · · ·  | Genera   | 1 Description of New Work  |  |
| Cause of fire  | ents, both Building D<br>- max overheated sto<br>mage - a few floor ti   |  | nediately.   |
|  | -  |  |  |
|  |  |  |  |
| n ng kiru shi ng ng ka sa k  | e e sea e e e e  |  | · · ·  |
| in i web   | • · · · • • • • •  | the second s   | M  |
|  |  | nstallation of heating apparatus which is to be taken of the second seco | ten out separately by and in   |
| · · · · ·  |  | Details of New Work  |  |
|  | olved in this work?  | Is any electrical work involved in t   | his work?  |
| Is any plumbing inv  | made to public services  | If not what a proposed for sewag   |  |
| Is connection to be  |  |  | c?   |
| Is connection to be a<br>Has septic tank not   | ice been sent?   | Form notice sent?  | C?   |
| Is connection to be a<br>Has septic tank not<br>Height average grad  | ice been sent?   | Form notice sent?<br>Height average grade to highest point   | c?<br>of roof  |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?<br>ie to top of plate<br>depthNo. sto   | Height average grade to highest point riessolid or filled land?  | c?<br>of roof<br>earth or rock?  |
| Is connection to be a<br>Has septic tank not<br>Height average grad<br>Size, front   | ice been sent?<br>de to top of plateNo. sto<br>ionNo. sto  | Form notice sent?<br>Height average grade to highest point<br>riessolid or filled land?<br>Thickness, topbottomcella   | c?<br>of roof<br>earth or rock?  |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front<br>Material of foundati<br>Kind of roof  | ice been sent?<br>ie to top of plate<br>depthNo. sto<br>ionRise per foot   | Form notice sent?<br>Height average grade to highest point<br>riessolid or filled land?<br>Thickness, topbottomcella   | c?<br>of roof,<br>earth or rock?<br>r  |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?<br>ie to top of plate<br>depthNo. sto<br>ionRise per foot<br>Material of chimi  | Form notice sent?<br>Height average grade to highest point<br>riessolid or filled land?<br>Thickness, top bottomcella<br>Roof coveringKind of hea  | c?<br>of roof<br>earth or rock?<br>r<br>t fuel   |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front<br>Material of foundati<br>Kind of roof<br>No. of chimneys<br>Framing Lumber-K   | ice been sent?<br>le to top of plate<br>depthNo. sto<br>ionRise per foot<br>Material of chimi<br>ind Dressed or                      | Form notice sent? Height average grade to highest point riessolid or filled land? top bottom cella Roof covering Kind of heat full size? Corner posts  | c?<br>of roof<br>earth or rock?<br>ir<br>t fuel  |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front<br>Material of foundati<br>Kind of roof<br>No. of chimneys<br>Framing LumberK<br>Size Girder   | ice been sent?<br>ie to top of plate<br>depthNo. sto<br>ionRise per foot<br>Material of chime<br>(indDressed or<br>Columns under gir | Form notice sent?  | c?<br>of roof<br>earth or rock?<br>r<br>t fuel<br>Sills<br>on centers  |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?<br>of roof<br>earth or rock?<br>r<br>t fuel<br>on centers<br>of span over 8 feet.                           |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front<br>Material of foundati<br>Kind of roof<br>No. of chimneys<br>Framing LumberK<br>Size Girder<br>Studs (outside walls<br>Joists and rafter                | ice been sent?   | Form notice sent? Height average grade to highest point riessolid or filled land? Thickness, topbottomcella Roof covering Kind of heat full size? Corner posts Kind of heat full size? Size Max. 4-16" O. C. Bridging in every floor and flat roo, 2nd 3rd   | c?<br>of roof<br>earth or rock?<br>ir<br>t fuel<br>on centers<br>of span over 8 fcet.<br>, roof                |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front<br>Material of foundati<br>Kind of roof<br>No. of chimneys<br>Framing LumberK<br>Size Girder<br>Studs (outside walls<br>Joists and rafter<br>On centers: | ice been sent?   | Form notice sent? Height average grade to highest point riessolid or filled land?  | c?<br>of roof<br>earth or rock?<br>r fuel<br>t fuel<br>on centers<br>of span over 8 feet.<br>, roof            |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?<br>of roof<br>earth or rock?<br>t fuel<br>t fuel<br>on centers<br>if span over 8 feet.<br>, roof            |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?<br>of roof<br>earth or rock?<br>t fuel<br>t fuel<br>on centers<br>if span over 8 feet.<br>, roof            |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?<br>of roof<br>earth or rock?<br>t fuel<br>t Sills<br>on centers<br>of span over 8 fcet.<br>, roof<br>, roof |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?   |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?   |
| Is connection to be a<br>Has septic tank noti<br>Height average grad<br>Size, front  | ice been sent?   | Form notice sent?  | c?   |

A#N: Jeanie Bourke, 29 Merrill St Inspections Services Portland ME, 04101 Division Director 11-29-06

Shane Bradstreet (207) 329-1971

Amendment to Building application Sub floor/ sound barrier





Not to include

CURRAN **DRAFTING & DESIGN** 

October 27, 2006

#### Addendum for Bradstreet Residence, 29 Merrill Street, Portland

#### (1) Handrails:

Handrails required in all stairwells @ 36" (new and existing.) Handrail also required on front porch.

(2) Sub flooring:

New 3/4" Advantech sub floor to be applied over existing 3/4" t&g flooring.

(3) Sound Proofing / Insulation:

All exterior walls to have min. of R-19 insulation. Ceiling to have min. of R-38 insulation.

All floors between units to have R-30 insulation.

(4) G.W.B. / Fire proofing:

All stairwells to have 5/8" type-x g.w.b.

All common corridors to have 1 layer 5/8" type-x g.w.b. each side.

All ceilings to have 5/8" type-x g.w.b.

All stairwells and common corridors, door to be fire rated door and assembly.


All exterior doors to be steel fire rated door and assembly.

#### (5) Smoke detector:

Each unit to have hard wired smoke detectors per local fire and building code.

Any additional information you need please don't hesitate to call

Sincerely, Michael P. Curran President



| DEPT. | OF BUILDING INSPECTION |   |
|-------|------------------------|---|
|       | OCT 2 7 2006           |   |
|       | RECEIVED               | _ |

#### Addendum for roof Product Description for Roof Ha


Product Description for Roof Hatch

Acudor A38104 A-Series Roof Hatch 30 x 96 Aluminum Acudor Roof Hatches are designed to provide convenient, economical access to the roof of a building. Available in prime coated galvanized steel or aluminum. Our hatches are designed with safety, durability, and ease of operation in mind. Acudor A38104 A-Series Roof Hatch Optional Features: Acrylic domes Louvered Curbs Stainless Steel Hardware Curb Mounted Modified Curb for Metal Building Acudor A38104 A-Series Roof Hatch Specifications: Roof Hatch Cover: 14 gage galvanized steel / .125 aluminum in box type design with 1" rigid fiberglass insulation and 22 gage galvanized steel / .040 aluminum cover liner. Continuous santoprene weather / draft seal is attached to inside of cover to provide a flush, tight fit. The cover is designed to support a live load of 40 pounds/sq.ft. Roof Hatch Curb: 14 gage galvanized steel / .125 aluminum with 1" rigid fiberglass insulation at curb exterior. Curb is 12" high, and has 3-1/2" wide mounting flange with pre-drilled holes. Roof Hatch Hinge: Steel butt hinges with brass pin. Roof Hatch Opening Device: Fully enclosed compression spring operators allow cover to open and close easily. Automatic hold open arm with red vinyl grip release keeps cover in open position when needed, and allows for easy control when closing hatch cover. Roof Hatch Latch: Selflatching outside turn handle with inside lever handle permits cover to always latch securely. Inside and outside padlock provisions allow for extra security. Roof Hatch equipped with safety railings for easy exterior access\* Roof Hatch Finish: Galvanized steel: prime painted with rust-inhibiting grey primer. Aluminum: mill finish. Convenient weather-tight access to roof Insulated cover and curb Available in galvanized steel and aluminum \* Dimensions are W x H


#### Concerning section 3 A2 "Roof Deck Detail"


#### **Revisionment of Deck detail:**

Dimensions of Deck will decrease, 21'--7" wide by 12' long, includes 6x6 PT posts every 4' along exterior walls, continued 2x6 supports to foundation













1)<u>THIRD</u>







<u>/</u>Å 5











2 SECOND FLOOR DEMO PLAN

