
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager Ajor-akol Pio Okuc		Inspector Marland Wing	Inspection Date 1/30/2003
Locatation 29 Merrill St	CBL 014 F001001	Status Green 0-4 Violations	Inspection Type Housing-Non Compliance

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-108.3	Exterior	3		Front Hall	
Violation: Exterior windows, doors and skylights					
Notes: Window has broken glass					

Comments: