THIS IS NOT A BOUNDARY SURVEY

This copyrighted document expires 03-14-16. Reproduction and/or dissemination after this date is unauthorized. MORTGAGE INSPECTION OF: DEED BOOK __32730__ PAGE ___315___ COUNTY __Cumberland__ PLAN BOOK _____ PAGE ____ LOT _____ ADDRESS: 5 Merrill Street, Portland, Maine Job Number: 872-53 Inspection Date: 12-14-15 Buyer: Landmarx Construction Scale: 1" = 10'Client File #: _2015-125354 Seller: Marcia D. Haynes abutter's abutter's paved drive building to locus underpinning 40°± Metrill Street porch 1 1/2 story wood structure w/ brick foundation DAVID L. J. HUGHES #2234 Note: Lines of occupation are shown. A boundary survey may yield different results. APPARENT EASEMENTS AND RIGHTS OF I HEREBY CERTIFY TO: Cumberland Title Services, Inc; Landmarx WAY ARE SHOWN. OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS SKETCH WILL NOT REVEAL ABUTTING DEED CONFLICTS, IF ANY. Monuments found did not conflict with the deed description. copyright@ The dwelling setbacks do not violate town zoning requirements. Livingston-Hughes As delineated on the Federal Emergency Management Agency Community Professional Land Surveyors Panel 230051-0014 B: 88 Guinea Road The structure does not fall within the special flood hazard zone. Kennebunkport, Maine 04046 The land does not fall within the special flood hazard zone. 207-967-9761 phone 207-967-4831 fax A wetlands study has not been performed. www.livingstonhughes.com