City of Portland, Maine Inspections Division Violations Report

Appointment Date Between 1/1/2015 And 2/6/2018

Dist. #	Sch. Date Contact:	CBL	Appl. Type Inspector	Schedule Type Comments	Appl #	Location			
1 HSL Yr 2018	12/04/2015 014 G005001 Fire Company MELBOURNE STREET LLC Christopher Corey			FP Routine Inspection			4 MELBOURNE ST		
	Code	Violation		Status	IntExt	Floor	Area	Corrected	Date
	NFPA 101-	Fire Doors Must Be Self- Or Auto-closing		Open					
	7.2.1.8.1- 80.46	Basement Door	•						
	NFPA 10-	Fire Extinguishe	er Inspection Tag	Open					
	7.2.4.4-	Basment							
	81 20 NFPA 720- 5.5.6.1-	Co Alarms Required		Open					
	NFPA 101- 31.3.4.5.1- 55.25	Smoke Alarms Required		Open					
	NFPA 1- 89.05	Excessive/disor Basement	derly Storage	Open					
	NFPA 101- 8.3.4.2- 80 37	60 Minute Fire Apartment Doo		Open					
HSL Yr 2018	09/14/2017 014 G005001 Fire Company MELBOURNE STREET LLC Mark Stewart			FP Routine Inspection Inspection scheduled 9/14		03-4295	4 MELBOURNE ST		
	Code	Violation		Status	IntExt	Floor	Area	Corrected	Date
	NFPA 1-	Excessive/disor	derly Storage	Open					
	89.05	Storage on second floor in stairwell must be removed.							
	NPFA 101-	Discontinue Use Of Extension Cords Open							
	590.6- 55.092	Discontinue use of extension cord as permanent wiring in basement.							
	NFPA 101-	Boiler Protection	n Required	Open					
	31.3.2.1.1-	Gas Hot Water	Heaters need protection.						
	NFPA 101-	Certify Fuel Fire	Appliance	Open					
	54-55.105	Gas Hot Water Heater vent needs to be certified.							
HSL Yr 2018	09/21/2017 014 G005001 Fire Company Melbourne Street Llc Mark Stewart		FP Routine Inspection Inspection scheduled 9/14		03-4295	4 MELBOURNE ST			
	Code	Violation		Status	IntExt	Floor	Area	Corrected	Date
	NFPA 101-	Fire Door Asser	nbly Reg Repair	Open	IIICEAC	11001	Aica		Date
	7.2.1.15.8-	Basement Door		O pe					
	73.05 NFPA 101-	Smoke Alarms I	Required	Open					
	31.3.4.5.1-	·						_	
	71 25 NFPA 101-		Self-closing & Self-latching						

Total Listed: 3