## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

July 12, 2017

Responsible Party 1:			
Ryan Patricia E			
60 MONTREAL ST # 1			
PORTLAND, ME 04101			
Location	CBL	<b>Inspection Date</b>	
<b>Location</b> 60 MONTREAL ST	CBL 015 F010001	<b>Inspection Date</b> 6/16/2017	
		_	

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 7/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
NFPA 1, CHAPTER 10 - 10.11.6 HIBACHI OR GRILL ON BALCONY; NO HIBACHI, GAS-FIRED GRILL, CHARCOAL GRILL, OR OTHER SIMILAR DEVICES USED FOR COOKING, HEATING, OROTHER PURPOSE, SHALL BE USED OR KINDLED ON ANY BALCONY OR UNDER ANY OVERHANG PORTION OR WITHIN 10 FTOF ANY STRUCTURE Grill on rear deck	//
NFPA 101- 7.2.1.8.1 FIRE DOORS MUST BE SELF- OR AUTO-CLOSING; A door leaf normally required to be kept closed shall not be secured in the open position at any time and shall be self-closing or automatic-closing in accordance with 7.2.1.8.2, unless otherwise permitted by 7.2.1.8.3.  Front stairway apartment doors	//
NFPA 720- 5.5.6.1 CO ALARMS REQUIRED; The performance, location, and mounting of notification appliances used to initiate or direct action, evacuation or relocation of the occupants, or for providing information to occupants or staff, shall comply with the requirements of Chapter 6.  First and 3rd floor apartments	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 101- 8.3.4.2 60 MINUTE FIRE DOOR REQUIRED; Refer to NFPA 101- Table 8.3.4.2 that states fire door assemblies for vertical shafts (including stairways, exits, and refuse chutes) are rated and required for 1 hour.  Front statirway apartment doors	//

Violation		Proposed Date of Completion
FINAL DATE OF COMPLETE	D VIOLATION(S)	· / / /
FIRE PREVENTION BUREAU	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	t to reject or modify any proposed plan of action, and may nical capacity to complete the proposed plan. Please contact TION	-
understand that I must conta	ons listed within the timeframes provided. If I require add act the Fire Prevention Bureau <u>prior to the deadline</u> to requ's discretion to grant or deny.	
v	is my responsibility to schedule a reinspection of my prope . My failure to schedule a reinspection shall be deemed an nedied.	•
	greement, I understand that I am liable for penalties pursurs $\{s, s, s, 1-15\}$ and 10-25, and 30-A M.R.S. $\{s, s, s$	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		

Fire Prevention Bureau

Date