

City of Portland, Maine
Inspections Division
Violations Report

Appointment Date Between 1/1/2016 And 3/15/2018

Dist. #	Sch. Date	CBL	Appl. Type	Schedule Type	Appl #	Location
	Contact:		Inspector	Comments		
1	03/31/2016	015 F018001	Fire Company	FP Routine Inspection		63 MELBOURNE ST
HSL Yr	DERRY ROBERT WILLIAM		Daniel Dyer			
2018						

Code	Violation	Status	IntExt	Floor	Area	Corrected	Date
NFPA 101-7.2.1.15.8-73 05	Fire Door Assembly Req Repair need self closers	Open				<input type="checkbox"/>	
NFPA 101-7.5.1.1-80 28	Exit Obstructed 3rd floor front stairwell	Open				<input type="checkbox"/>	
NFPA 720-5.5.6.1-55 05	Co Alarms Required each unit	Open				<input type="checkbox"/>	
NFPA 101-31.3.4.5.1-55 25	Smoke Alarms Required Hard wired detectors required	Open				<input type="checkbox"/>	
NFPA 70-590.6-91.20	Extension Cords basement	Open				<input type="checkbox"/>	
NFPA 101-31.3.2.1.1-3 011	Boiler Protection Required 2 gas water heaters in basement	Open				<input type="checkbox"/>	
NFPA 101-8.3.4.2-80 37	60 Minute Fire Door Required basement doors and front hallway	Open				<input type="checkbox"/>	

Total Listed: 1