

38 Munjoy Street

MUNJOY

SHAW-WALKER  
#8503 JR

✓ November 8, 1977

Mr. Joseph P. Adamo  
38 Munjoy Street  
Portland, Maine 04101

Dear Mr. Adamo: Re: 38 Munjoy Street, Portland, Maine NCP-East End  
16-C-5

The Housing Inspections Division of the Department of Neighborhood Conservation has recently completed an exterior inspection of your property in conjunction with the above referred program.

Congratulations are extended to you for the general conditions of your property which was found to meet the standards established by the City's Housing Code.

Good maintenance is the best way to protect the value of your property and neighborhood.

Please feel free to call on us if we can be of assistance to you.

Sincerely yours,  
Joseph E. Gray, Jr., Director  
Neighborhood Conservation

Inspector *Mark Wing*  
M. Wing

By *Lyle D. Noyes*  
Lyle D. Noyes,  
Chief of Housing Inspections





Jan 21, 65  
311 Pine St  
So. Portland, Me

Mr. Edwin Martin *file*  
House of Reps.

Dear Mr. Martin  
House of Reps.

Dear Mr. Martin

I believe the attached was  
mailed in error.

Joseph P. Walsh, who is my  
son, is over ten years of age and is  
not the owner of any property in  
Portland

Joe Walsh  
311 Pine St  
So. Portland, Me

33-39- Einar Johnson  
Joseph O. Walsh WW I Vet  
1954 - 38 Murray St.  
owner 36-38 Murray St.

Mr. Joseph P. Walsh  
311 Pine Street  
South Portland, Maine

Loc. 38 Munjoy Street  
Loc w/i S  
Bldg x Fire xElec Other  
Issued January 19, 1966  
Expires February 19, 1966

Inspection date: Dec. 11, 1965

STRUCTURAL

Repair and put in good order all dilapidated and hazardous parts of the structure as follows:

- a. Replace the missing balusters and handrail on the outside front porch.
- b. Repair or replace the sealed rear door, as it is an obstruction.
- c. Repair or replace the loose, worn, dilapidated, and hazardous parts of the stairway of the basement.
- d. Repair the missing plaster on the walls in the bedrooms and den on the 2nd floor.
- e. Repair or replace the missing plaster on the ceilings in the bedrooms and den on the 2nd floor.
- f. Putty the loose window panes, tighten the loose window sashes in all of the windows on the 2nd floor.

The above mentioned conditions are in violation of the City Ordinances, Minimum Standards for Continued Occupancy, and Authority to Vacate Buildings, and must be corrected on or before February 19, 1966.











