182 CONGRESS STREET

SHAME 110



CITY OF PORTIAND, MAINE DEPARTMENT OF BUILDING INSPECTION

Portland Renewal Authority

December 27, 1967

(Viola Construction Co.)

With relation to mermit applied for a describe a building or portion of building at 182 Congress St. it is unlawful to commence demolition work until a permit it was a issued from this department.

Section 6 of the Ordinance for them? and we min control provides: "It shall be unlawful to demolish any including or structure unless provision is made for rodent and vermin eradication. No permit for the demolition of a building or structure shall be issued by the Building Inspection Department until and unless provisions for rodent and vermin eradication have been carried out under supervision of a pest control operator registered with the Health Department.

The building permit for demolition cannot be issued until the provisions of this section have been satisfied. It is the obligation of owner or demolition contractor or both to take up with the Health Department the matter of complying with this section, being prepared to inform that department what registered pest control operator is to be employed.

Very truly yours,

Gerald E. Mayberry

Director of Building & Inspection

Eradication of this building has been completed.

1-15-68

Paul Mathieu, HD

RECEIVED JAN1 5 1968

DEPT. OF BLOG THEP.

CITY OF PORTLAND, MAINE HEALTH DEPARTMENT



JOHN R. DAVY, M.D. HEALTH OFFICER

	Date 29 December 1907
	Short Short
To: Mr. Santino Viola, 84 Pay	
Ref: (A) Location of Property 1	182 Congress Street
(B) Section VI - Chapter #313	of the Municipal Code - Rodent & Vermin Control
This property cannot be approved for from rodents by an exterminator curre Portland, Maine.	demolition until it is certified to be reasonably free ently registered with the Health Department, City of
halmy and return same to the Portland	, please have your exterminator sign the certification d Health Department. A re-inspection will then be con- rtified, the demolition permit will be released.
	for Chief Sanitarian
Copy to: Building Inspection Departm	/ ment
	116116
ED File	
-	
	(Detach)
	Date
	<i>Vacc</i>
Cer	ti fi cation
,	•
 !	hereby certify that the premises located at
	have been subject to extermination procedures
for rodents and is reasonably free f	from such infestation.
•	(Signature PCO)
	· ·
3	(Company)
	(conhairy)
•	
	(Address)
*	

APPLICATION FOR PERMIT

Class of Building or Type of Structure _____ Portland, Maine, _ Dos. 27, 1967_____

PERMIT	ISSUEL
J4N 1	\$ ₁₉₂ 35

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a perminaccordance with the Laws of the State of Maine	to erect alter repair demolish install the following b the Building Code and Zoning Ordinance of the (uilding structure equipment City of Portland, plans and
n accordance with the Laws of the State of the state	11	
pecifications, if any, submitted herewith and the fo	ttorang specifications:	
	Anna Talana	Dict No.

Location 132 Congress Street ___ Within Fire Limits? ____ Owner's name and address Fortland Renwell authority Telephone... ___ Telephone Lessee's name and address ____ Contractor's name and address Santing Viola, 84 Fayson Street Telephon-___No. of sheets ____ Specifications Plans Architect No. families Proposed use of building __ No. families __ 2 f2:1. Last use No. stories Heat Style of roof Roofing Material Other buildings on same lot ... Estimated cost \$____

General Description of New Work

To demolish existing 2-fan. dwelling

Do you agree to tightly and permanently close all dewers or drains connecting with public or private sewers from this building under supervision and approval of the Dept. of Fublic Works of the City of Portland? yes

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and is the name of the keating contractor. PERMIT TO BE ISSUED TO contractor Details of New Work Is any electrical work involved in this work? Is any plumbing involved in this work? ____ Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____ __Form notice sent? _ Has septic tank notice been sent? Height average grade to top of plate _____ Height average grade to highest point of roof_____ Size, front______ Cepth ______ No. stor.es ______solid or filled land? _____earth

Material of foundation ______ Thickness, top ______ bottom _____ cellar ____ ___earth or rock? ____ _____Rise per foot ______ Roof covering ____ Kind of roof No. of chimneys ______ Material of chimneys _____ of lining ____ _____ Kind of heat ____ : Dressed or full size? ____ Corner posts ____ Framing Lumber-Kind Size Girder _____ Columns under girders _____ Size ____ Max. on centers ____ Strids (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet. 1st floor______, 2nd______, 3rd _____ Joists and rafters: _____, 2nd______, 3rd_____ On centers: _____, 2nd____ _____, 3rd __ 1st floor_____ Maximum span: If one story building with masonry walls, thickness of walls?____ If a Garage No. cars now accommodated on same lot____, to be accommodated___number commercial cars to be accommodated___ Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?... Miscellaneous Will work require disturbing of any tree on a public street?__ Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes Santino Viola

INSPECTION COPY

Signature of owner

NOTES	
3/27/19 demolate RUL	Cert. of O Staking C Staking C Staking C Form Che
The first the first will be the first the firs	Cert. of Occu
	Date of permit Notif. closing-in Inspn. closing-in Final Notif. Final Inspn. Cert. of Occupancy Staking Out Notice Form Check Notice
Control of the state of the sta	Location & Was Locati
1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1	
Marine Committee	le la
E. John C. B. C. Land C. Bright Co.	
V. S.	120
a francisco de la constanción	
· · · · · · · · · · · · · · · · · · ·	
	= -
No. 1	
	à
	en de la companya de
	<u> </u>
-	
Reserved to the second of the	
100	

Memorandum from Department of Building Inspection, Portland, Maine

182 Congress St.—To replace damaged foundation wall with cement blocks for Sadie Blumerthal by William L. Vassar & Son, April 30, 1957

Building permit for replacement of existing stone foundation wall which has collapsed with a 12 inch concrete block wall under front wall of dwell? At the above named location is issued herewith subject to the follow-ditions:

- 1. A poured concrete footing at least 8 inches thick and 14 inches wide is to be provided for support of the concrete block wall.
- 2. The 12 inch concrete blocks are to extend at least to the surface of the sidewalk at all points. Above the surface of the sidewalk 8 inch blocks may be used if desired.
- 3. All blocks used below grade are to be concrete not cinier blocks.

AJS/B

CS-27

(Signed) Warren McDonald Inspector of Buildings



APPLICATION FOR PERMIT

Class of Building & Type of Structure

Portland, Maine, April 30, 1957

The state of the s

Phillips A		N'En
TIN.	113	

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to FEFF of accordance with the Laws of the State of Maine, the Bui specifications, if any, submitted herewith and the following s	Ming Coce and Zoning Orsin becifications:	cance by the City of Persons, promo one
182 Congress St.	Withia Fire L	imits? Dist. No
Owner's name and address <u>Miss Sadie Blumenth</u>	al, 182 Cengress Sc.	Telephone
Lessee's name and address William L, Vassa Contractor's name and address William L,	r & 50n, Bat 477, 01	ty Telephone 3=7996_
A-chitact S	pecifications Pic	ans
Proposed use of building dwelling house	- Andreas -	No. lamules
Last use	Style of roof	No. lanines
Other buildings on same lot	, and the second	Fee \$ 2.00

General Description of New Work damaged
Replace front of/foundation wall with cement blocks

Permit Issued with Memo

It is understood that this peri he name of the heating contra	ctor. PERMIT TO	BE ISSUED TO	Contra	actor
		Details of New V?o.	rk	
Is any plumbing involved in	this work	Is any clect	trical work involve	ed in this work?
r i i i i i i i i i i i i i i i i i i i	nublic sewer?	If not, "vha	it is proposed for	sewager
TTis sout notice been	sent?	Form noti	ce sent?	
	C = lata	Height average	e grade to highest	point of tool
Size, front dept	1No. sto	riessolid or fille	ed land?	earth or rock?
Material of foundation	cement blacks	Thickness, top	bottom12	ellar
** . '* * *	-	- Height		_ I IIICVIIC92
Wind of mod	Rise per foot.	Roof cover	ring	
No of chimneus	Material of chim	neys of lining _	Kind	1 of neat
T turber Cind		Dressed or	full size?	
Carran north	Sille Gi	rt or ledger board?		51ZE
Ciadose Size	Columns	under girders	Size	Max. on centers
Studs (outside walls and ca	erving partitions) 23	x4-16" O. C. Bridging is	n every floor and	flat roof span over 8 feet.
Toiete and rafters:	ist floor	, 2nd	, 3rd	, 7COI
	4 . 0		3rd	. 100
	4 . 4 . 6	2nd	. 3rd	, roc-t
If one story building with	masonry walls, thick	mess of walls?		
		If a Garage	•	
		- he accommodated	number commer	cial cars to be accommodated
No. cars now accommodate	ed on same lot	incr moving to care hal	bitually stored in	the proposed huilding?
Will automobile repairing	he done other than h		***1	1
PROVED:				laneous
	and	Will work requir	re disturbing of an	ny tree on a public street?no
withing by	190	Will there be i	n charge of the a	bove work a person competent to
	V	see that the S	tate and City rec	quirements pertaining thereto are
A STATE OF THE STA		observed?yes	1	
	· ·		and the same that	د . د ما محسود ما ا

INSPECTION COPY

NOTES Final Inspn.
Cert. of Occupancy issued Final Notif. Form Check Norice Scaling Out Node Notif. closing-in upilon on alledine 1:-to well miner of garage attention and the specification of . . . Triller at . e star b .1. .. - 3 يُ الا يورات ed it is say to be to the anatom that they Ladiger -17 notes र्वे १९३८**सम्बद्धाः**स