CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
Elizabeth Graves		Arthur Rowe	3/28/2007
Locatation	CBL	Status	Inspection Type
97 NEWBURY ST	020 B017001	Re-Inspect 10 Days	Building Permit-Certificate of Occ

Code Int/Ext Floor Unit No. Area Compliance Date

1) 105.1 Interior

Violation: Building w/o Permit

Notes: unpermitted electrical work being done on floor 1, 2, and 3. unpermitted plumbing work being done.

Comments: no plumbing permit, no electric permit. Work being done on 1st 2nd and third floor. Plumbing vented to

third floor space. Called owner on 4/02/07 informed re permit required.