

INSPECTION REPORT

CUSTOMER: S.W. COLE		PAGE 1 OF 1	
ADDRESS: 127 FORE ST PORTLAND MAINE			
ATTENTION: CARL			
COPIES:			
PROJECT: MARRIOT HOTEL			
OWNER:			
CONTRACTOR:			
JOB No.: 06-0726.2	REPORT No.: QAL-08-0848	P. O. NUMBER: VERBAL	DATE INSPECTED: 05-05-08

REMARKS

AN ULTRASONIC INSPECTION WAS PERFORMED USING AWS D1.1

PILE # 85 & 128
 PILE SIZE# 1253
 JOB # 06-0726.2


NO INDICATIONS WERE NOTED AT TIME OF INSPECTION.

LAST ITEM

FAA REPAIR STATION NUMBER RX5R187N
 METHOD(S).PROCESS(ES).PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(S) SUPPLEMENTARY SHEET(S) NDI REPORTS VIDEO

SIGNATURES

INSPECTOR S. DYER		CERTIFICATION		DATE		
		ASNT	II	M	D	Y
SUPERVISOR						