(FORM 0703 REV 0)

Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE SOUTH PORTLAND, MAINE 04106 . TEL: (207) 799-8911 . FAX: (207) 799-7251 INSPECTION REPORT S. W. COLE ENG. PAGE 1 1 OF CUSTOMER: GRAY MAINE ADDRESS: ROGER DOMINGO ATTENTION: COPIES: RESIDENCE INN MARRIOTT - PORTLAND, MAINE PROJECT: MARRIOTT INN OWNER: CONTRACTOR: LEDGEWOOD 07 - 16 - 08 JOB No.: 06-0726,2 REPORT No.: QAL-08-1406 P.O. NUMBER: DATES INSPECTED: REMARKS >>> SITE VISIT TO VISUALLY INSPECT PROGRESS TO ENSURE COMPLETION OF LOWER LEVELS AT GRID LOCATIONS AS LISTED ON PREVIOUS FIELD REPORT DATED 06-16-08. LINES 20-26, N-X. > INSPECTION SHOWS ALL LOWER LEVELS COMPLETE FOR WELDED AND BOLTED CONNECTIONS. HOWEVER, ROOF LEVEL FLOOR PLANK TO GIRTS AT LOCATION 20-21.6, L-X SHOW (15) CLIPS STILL IN-PROGRESS FOR WELDING. ALL OTHER LEVELS AND LOCATIONS COMPLETE. COMPLETED ITEMS COMPLY WITH SITE DOCUMENTS AND AWS DI I REQUIREMENTS FOR VISUAL ACCEPTANCE. END ITEMS /// FAA REPAIR STATION NUMBER RX5R187N METHOD(S), PROCESS(ES), PROCEDURE(S) MERCURY FREE ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(ES) SUPPLEMENTARY SHEET(S) NOT REPORTS VIDEO DATE CERTIFICATION **SIGNATURES** MICHAEL DREW CWI# 99050211 INSPECTOR ASNT 11 07 | 18 | 08 SUPERVISOR