

Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04108 • TEL: (207) 799-8911 • FAX: (207) 799-7251

INSPECTION REPORT

CUSTOMER: S. W. COLE ENG.		PAGE 1 OF 1	
ADDRESS: GRAY, ME.			
ATTENTION: ROGER DOMINGO			
COPIES:			
PROJECT: RESIDENCE INN BY MARRIOTT - PORTLAND, ME.			
OWNER:			
CONTRACTOR: LEDGEWOOD CONSTRUCTION INC.			
JOB No.: 06-0726.2	REPORT No.: QAL-08-1925	P. O. NUMBER:	DATES INSPECTED: 09 - 08 - 08

REMARKS

>>>>> SITE VISIT TO PERFORM INPROCESS VISUAL INSPECTION OF STRUCTURAL STEEL CONNECTIONS: AT ZONE #6 LEVELS 1, 2, 3, & 6.


- > FIRST LEVEL FRAMING PLAN FOR COLUMN ANCHOR POINTS WHICH SHOWS INCOMPLETE SQUARE ANCHOR PLATES NOW COMPLETED ON 09 - 10 - 08 . PER LEDGEWOOD .
- > PREVIOUS ITEMS IDENTIFIED ON WALK-TROUGH DATE OF 09-08-08 SHOW ITEMS LISTED ON DAVE BERNIER'S LIST, HAVE BEEN COMPLETED PER LEDGEWOOD . IE: T/C BOLTS SNAPPED , COLUMN SPLICE PLATES NOT REQUIRED TOP WELDS TO COLUMNS .
- > LEVEL 3 FLOOR PLANK BOTTOM EMBED PLATES TO GIRDER CONNECTIONS IN-PROGRESS .

COMPLETED ITEMS COMPLY WITH SITE DOCUMENTS AND AWS D1.1 REQUIREMENTS FOR VISUAL ACCEPTANCE .

END ITEMS ////

FAA REPAIR STATION NUMBER RX5R187N
METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(ES) SUPPLEMENTARY SHEETS NDT REPORTS VIDEO

SIGNATURES		CERTIFICATION:		DATE		
INSPECTOR MICHAEL DREW CWI# 99050211 		ASNT	11	09	15	08
SUPERVISOR						