

Quality Assurance Labs Inc.

NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES

80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

INSPECTION REPORT

CUSTOMER: S. W. COLE ENG.			PAGE 1 OF 1
ADDRESS: GRAY, ME.			
ATTENTION: ROGER DOMINGO			
COPIES:			
PROJECT: RESIDENCE INN BY MARRIOTT			
OWNER: MARRIOTT			
CONTRACTOR: LEDGEWOOD CONSTRUCTION			
JOB No.: 06-0726.2	REPORT No.: QAL-08-2376	P. O. NUMBER:	DATES INSPECTED: 11 - 05 - 08

REMARKS

>>>>> SITE VISIT TO PERFORM FINAL VISUAL INSPECTIONS OF COMPLETED STRUCTURAL STEEL FIELD CONNECTIONS. ZONES 4, 6 AND 7. ALL LEVELS TO ENCLUDE STAIR WELL ATTACHMENTS.

> ALL PREVIOUS LISTED ITEMS FOR UN-TORQUED BOLTS ETC. ARE COMPLETE.

> LEVEL (5) ZONE # 7 FLOOR PLANK EMBEDDED PLATE MODIFICATIONS TO GIRDER CONNECTIONS COMPLETE.

ALL COMPLETED ITEMS COMPLY WITH SITE DOCUMENTS AND AWS D1.1 REQUIREMENTS FOR VISUAL ACCEPTANCE.

END ITEMS ////



MICHAEL W. DREW
 CWI 99050211
 QC1 EXP. 06/01/11

FAA REPAIR STATION NUMBER RX5R187N
 METHOD(S), PROCESS(ES), PROCEDURE(S) MERCURY FREE

ADDITIONAL INFORMATION - SEE ATTACHED:				<input type="checkbox"/> SKETCH(ES)	<input type="checkbox"/> SUPPLEMENTARY SHEET(S)	<input type="checkbox"/> NDT REPORTS	<input type="checkbox"/> VIDEO
SIGNATURES						CERTIFICATION	
INSPECTOR MICHAEL DREW CWI # 99050211						LEVEL	DATE
						ASNT	M D Y
SUPERVISOR						II	11 05 08