## Quality Assurance Labs Inc. NON-DESTRUCTIVE TESTING AND INSPECTION SERVICES 80 PLEASANT AVENUE • SOUTH PORTLAND, MAINE 04106 • TEL: (207) 799-8911 • FAX: (207) 799-7251

ULTRASONIC INSPECTION REPORT							
CUSTOMER: SW COLE GRAY OFFICE					DATE OF INSPECTION	M D Y O6 24 08	
ATTENTION:					REPORT No.	QAL-08-1197	
PROJECT: MARRIOTT HOTEL					PAGE 1	OF 1	
COMPONENT INSPECTED: 5TH FLOOR FRAMING					JOB No.	06-0726, 7	
AREA OF INTEREST: MOMENT CONNECTIONS					P.O. No. VERBAL		
COMPONENT LOCATION: PORTLAND, ME					INSTRUMENT		
CUSTOMER WORK ORDER No: N/A	PART No.: N/A				MAKE: PANAMETRICS		
MATERIAL: CARBON STEEL	CARBON STEEL HEAT No.: N/A					MODEL: LTC	
COMPONENT SURFACE CONDITION: AS WELDED					EQUIPMENT NO.:		
EXAMINATION DATA					MATERIAL THICKNESS: 12.7 mm (0.500 in.)		
Project Code/Spec AWS D1.1						SCREEN	
U.T.	U.T. U.T.					RANGE: 10"	
Procedure No.  RESULTS: AS NOTED	INDICATIONS	Technique N	ique No.		COUPLANT: SONO CLEAR  TRANSDUCERS		
RESULTS: AS NOTED INDICATIONS: NONE REMARKS:					<del></del>		
PERFORMED ULTRASONIC INSPECTIONS ON 3RD FLOOR FRAMMING MOMENT CONNECTIONS IAW AWS.D1.1.					MAKE: PANAMETRICS  FREQ.: 2.25 MHz ANGLE: 70°		
						n (0.500 in.)	
					STYLE: SINGLE	SHAPE: SQUARE	
GRID LINES: W-23 EAST T/B						SHAPE, SQUARE	
W-24 EAST & WEST T/B W-25 EAST & WEST T/B					MAKE: PANAMETRICS		
W-25 EAST & WEST T/B W-26 WEST T/B N-23 EAST T/B N-24 EAST & WEST T/B							
					FREQ.: 2.25 MHz	ANGLE: 0°	
N-25 EAST & WEST						n (1.000 in.)	
N-26 WEST T/B						STYLE: SINGLE	SHAPE: ROUND
T/B = TOP & BOTTOM						EQUIPMENT No.:	
					MAKE:	<u> </u>	
						FREQ.:	ANGLE:
////LAST ITEM					SIZE:		
					STYLE:	SHAPE:	
						EQUIPMENT No.:	
					REFERENCE BLOCKS		
FAA REPAIR STATION NUMBER RX5R187N					MAKE: PANAMETRICS		
METHOD(S),PROCESS(ES),PROCEDURE(S) MERCURY FREE					TYPE: IIW		
ADDITIONAL INFORMATION - SEE ATTACHED: SKETCH(ES)  SUPPLEMENTARY SHEET(S) VIDEO					MATERIAL: CARBON STEEL		
SIGNATURES CERTIFICATION DATE				EQUIPMENT No.:			
INSPECTOR S. DYER SENT SE		ASNT	LEVEL	M	D Y	SENSITIVITY: 60.	3db + 6db
SUPERVISOR		7.0117	-11	00	24   08		
				<u>.                                    </u>			
AUTHORIZED INSPECTOR CUSTOMER		<del>                                     </del>					
REPRESENTATIVE				i I	1 1	TRANSFER VALUE:	