



PHOTO
1004.1
1004 002.jpg

Carriage House Rear Wall: View of in-place wall reinforcement, showing depth of footing below bottom of timber beam.



PHOTO
1004.2
1004 008.jpg

Carriage House Rear Wall: Filter fabric and crushed stone in place, prior to installing rear form and placing concrete.



**PHOTO
1004.3**
1004 009.jpg

Carriage House Rear Wall: Archway end of wall foundation, prior to cleaning and installing dowels into rubble voids.



**PHOTO
1004.4**
1004 003.jpg

Carriage House Rear Wall: Photo showing bottom reinforcing steel.