



**PHOTO**  
**1026.1**  
1026 001.jpg

Tower Wall: Formwork and rebar adjustments prior to placing concrete.



**PHOTO**  
**1026.2**  
1026 003.jpg

Tower Wall: Corner view showing brick wall (far right) rubble shelf (near right) and reinforcement for wall (center). Note corner bars have been provided.





**PHOTO  
1026.3**  
1026 005.jpg

Tower Wall: Concrete Placement in progress.



**PHOTO  
1026.4**  
1026 006.jpg

Tower Wall: Placement nearly complete.