## CITY OF PORTLAND FIRE PREVENTION BUREAU

380 Congress Street, Portland, Maine 04101 fireprevention@portlandmaine.gov (207) 874-8400

## NOTICE OF VIOLATION AND ORDER TO CORRECT

October 4, 2017

H.H. Sawyer Realty Company PO BOX 7225 PORTLAND ME 04112

Location	CBL	Inspection Date
111 FRANKLIN ST	021 D005001	9/15/2017
Inspector	Inspection Type	Status
Daniel Small	FP Routine Inspection	Failed

The City of Portland Fire Department inspected this property, and found the fire and life safety code violations listed below, which you are hereby ordered to correct. You must propose a date of completion to remedy each violation, a final date of completion, and a date of re-inspection.

## You must send this form to the Fire Prevention Bureau no later than 10/30/2017.

Your failure to submit a plan of action by the date provided, or to correct any violation within the applicable time frame, may result in legal action against you, the imposition of civil penalties, and the pursuit of other legal remedies.

Violation	Proposed Date of Completion
PORTLAND FIRE DEPARTMENT CHAPTER 10 SECTION 12 KNOX BOX REQUIRED; Knox Boxes are required for all buildings with fire alarm or suppression systems.	//
NFPA 101- 31.3.4.5.1 SMOKE ALARMS REQUIRED; In buildings other than those equipped through out with an existing, complete automatic smoke detection system, smoke alarms shall be installed in accordance with 9.6.2.10, as modified by 31.3.4.5.2, outside every sleeping area in the immediate vicinity of the bedrooms and on all levels of the dwelling unit, including basements.  Apt 5 defective/Apt 6 low battery/Apt 7 intermittent sound	IMMEDIATELY install temporary alarms where required. Your signature below indicates that temporary alarms have already been installed.
NFPA 70- ARTICLE 110 B CERTIFY ELECTRICAL SYSTEM; Listed or labeled equipment shall be installed and used in accordance with any instructions included in the listing or labeling. Entire electrical system needs to be looked at.  Apt 4 under construction-CEO inspection when completed	//
NFPA 70- ARTICLE 110.12 B EXPOSED WIRING CONNECTIONS; Internal parts of electrical equipment, including busbars, wiring terminals, insulators, and other surfaces, shall not be damaged or contaminated by foreign materials such as paint, plaster, cleaners, abrasives, or corrosive residues. There shall be no damaged parts that may adversely affect safe operation or mechanical strength of the equipment such as parts that are broken; bent; cut; or deteriorated by corrosion, chemical reaction, or overheating.  Remove non-energized/disconnected wiring in basement	//
NFPA 70 MISSING COVER ON PANEL; Refer to NFPA 70, National Electrical Code, on requirements of missing cover on electrical panel.  Apartment #2 - missing lock on the cover of the sub-panel	//

Violation		Proposed Date of Completion
		//
FINAL DATE OF COMPLETED	VIOLATION(S)	//
FIRE PREVENTION BUREAU F	RE-INSPECTION OF COMPLETED VIOLATION(S)	//
	to reject or modify any proposed plan of action, and may cal capacity to complete the proposed plan. Please contact ION	
·	ns listed within the timeframes provided. If I require add t the Fire Prevention Bureau <u>prior to the deadline</u> to requ t discretion to grant or deny.	- ·
	my responsibility to schedule a reinspection of my prope My failure to schedule a reinspection shall be deemed an died.	
	reement, I understand that I am liable for penalties pursu $\S\S$ 1-15 and 10-25, and 30-A M.R.S. $\S$ 4452 and may be .	
Date	Responsible Party	
Date	Responsible Party	
SEEN AND AGREED		
Date	Fire Prevention Bureau	