

Legalization Inspection Form

Date: 5/4/17

Address: 158 Cumberland Avenue

Legal Use: Three unit dwellings

Proposed Use: Four unit dwelling

Common Areas The washer/dryer in the front stairwell will need to be removed or enclosed in a fire rated area with a rated fire door.

Basement

- Fire Door: _____
- Detection: yes - detection needs to be a combo photo electric
- Sprinkler Head: _____
- Electrical/panel: All Junction boxes should have a cover.

Notes: _____

Unit 1

- Fire Door: _____
- Detection: _____
- Egress: _____

Notes: Passed

Unit 2

- Fire Door: _____
- Detection: Detection in the common area of the unit will need to be a Combo
- Egress: _____

Notes: The unit needs an identification (number) on the entry door

Unit 3

- Fire Door: Fire door needs to be adjusted to self close
- Detection: _____
- Egress: _____

Notes: The rear door needs unit identification (number)

Unit 4

- Fire Door: _____
- Detection: _____
- Egress: _____

Notes: Passed

Unit ___

- Fire Door: _____
- Detection: _____
- Egress: _____

Notes: _____

Unit ___

- Fire Door: _____
- Detection: _____
- Egress: _____

Notes: _____

Overall Pass _____ Fail _____ Follow up Required

Inspector: Chet Fox

Fire Prevention: _____