

243-247 CONGRESS STREET



CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION

COMPLAINT

Arthur Addato

INSPECTION COPY

COMPLAINT NO. 82-3

Date Received 1-8-82

Location: 243-247 Congress St.

Location 243-247 Congress St. Use of Building furniture store  
Owner's name and address Harrison Sawyer - Box 7225, Portland, Me. Telephone 04112  
Tenant's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Complainant's name and address P. Samuel Hoffses - Building Inspection Telephone Exc. 346  
Description: Obstructing sidewalk by over-excessive storage of furniture.

NOTES: 1-8-82 - Contacted 4 Tenants in business area. Informed them to control over display of wares on sidewalk where it may constitute a hazard. They will comply with our request. Also, contacted owners of building, Mr. Harrison Sawyer and Mr. Terinsky and they also stated that they would see that our request is complied with.

Insp. Arthur Addato 1-8-82



CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION

COMPLAINT

INSPECTION COPY

COMPLAINT NO. 81/0 81/40

Date Received 5-27-81

Location:

247 Congress St.

Location 247 ~~XXXXXX~~ CONGRESS ST. Use of Building APT.

Owner's name and address SAWYER REALTY

Telephone \_\_\_\_\_

Tenant's name and address \_\_\_\_\_

Telephone \_\_\_\_\_

Complainant's name and address tenant

Telephone \_\_\_\_\_

Description:

Bldg is unsafe, Main support beam has given way. Bldg. is split in middle. see apt. 4 B

NOTES: 5-27-81 - Performed a complete inspection on dwelling units, commercial areas, exterior and cellar. Findings are 10x12 wood beam beams set properly in beam sockets. No sign of moving out. Floor joists of 3x12 are very sound and solid. Support posts every 8' on concrete base, 8x8 black. Foundation is stone and mortar, no signs of spalling or deterioration. Cross beams of 4x8 black and sound. Trunks and stringers of 2 cellar stairs should be repaired. A general clean up of cellar storage is very necessary. Leaking sewerage, rear cellar floor. (Apts) show no settlement cracks. No doors jammed or signs of exceptional movement. Floors are tight to plates. A letter to be sent an non structural w/d. Complainant is under legal eviction. This appears to be a conflict of personalities rather than a justified complaint.

Inspr. Arthur Collette

5-28-81





CITY OF PORTLAND, MAINE  
DEPARTMENT OF BUILDING INSPECTION  
COMPLAINT

Location  
247 Congress St.

INSPECTION COPY

COMPLAINT NO. 75-119

Date Received November 6, 1975

Location 247 Congress Street Use of building \_\_\_\_\_  
Owner's name and address Mark R. Foley, 243 Congress St Telephone \_\_\_\_\_  
Tenant's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Complainant's name and address member of Health Housing Telephone \_\_\_\_\_

Description: Porch floor boards & steps unsafe. Member of Health Housing was there and almost fell through the stairs and platform of the porch. The nurse noted the boards on the porch were broken as well as one of the steps, and other cases were very dangerous. Notify owner verbally & by mail to fix immediately.

NOTES:

11-7-75 - Door locked - couldn't get in - didn't see what porch the complainant was talking about - see letter to Neum could get in - owner would return calls -



247 Congress Street

November 10, 1975

Mark R. Foley  
243 Congress Street  
Portland, ME 04101

It has been brought to our attention that a platform and stairs at the above location are in very poor condition, and that a member of the Health Department nearly fell through them. On November 7, 1975 I went to this building to check out the condition of the porch, however, I was not able to get in the building because it was locked.

If the structure of the porch and stairs are in such a poor condition, it will be necessary to repair them immediately. No building permit is required for repairs, only enlargements or structures concerning bearing weight. Please contact this office so that we can discuss and solve this problem as soon as possible.

Very truly yours,

Marge Schmuckal  
Building Inspector

MS/mj



APPLICATION FOR PERMIT  
DEPARTMENT OF BUILDING INSPECTIONS SERVICES  
ELECTRICAL INSTALLATIONS

Date Oct. 7, 19 80  
Receipt and Permit number 51769

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of  
Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 247 1/2 Congress St.

OWNER'S NAME: H. H. Sawyer Realty ADDRESS: 399 Fore St.

OUTLETS: Receptacles \_\_\_\_\_ Switches \_\_\_\_\_ Plugmold \_\_\_\_\_ ft. TOTAL 150 FEES 14.00

FIXTURES: (number of) Incandescent \_\_\_\_\_ Fluorescent \_\_\_\_\_ (not strip) TOTAL \_\_\_\_\_  
Strip Fluorescent \_\_\_\_\_ ft. \_\_\_\_\_

SERVICES: Overhead X Underground \_\_\_\_\_ Temporary \_\_\_\_\_ TOTAL amperes 800 6.00  
METERS: (number) 17 8.50

MOTORS: (number) Fractional \_\_\_\_\_  
1 HP or over \_\_\_\_\_

RESIDENTIAL HEATING: Oil or Gas (number of units) \_\_\_\_\_  
Electric (number of rooms) 36 36.00

COMMERCIAL OR INDUSTRIAL HEATING: Oil or Gas (by a main boiler) \_\_\_\_\_  
Oil or Gas (by separate units) \_\_\_\_\_  
Electric Under 20 kws \_\_\_\_\_ Over 20 kws \_\_\_\_\_

APPLIANCES: (number of) Ranges \_\_\_\_\_ Water Heaters \_\_\_\_\_  
Cook Tops \_\_\_\_\_ Disposals \_\_\_\_\_  
Wall Ovens \_\_\_\_\_ Dishwashers \_\_\_\_\_  
Dryers \_\_\_\_\_ Compactors \_\_\_\_\_  
Fans \_\_\_\_\_ Others (denote) \_\_\_\_\_

MISCELLANEOUS: (number of) Branch Panels 17 17.00

Transformers \_\_\_\_\_  
Air Conditioners Central Unit \_\_\_\_\_  
Separate Units (windows) \_\_\_\_\_

Signs 20 sq. ft. and under \_\_\_\_\_  
Over 20 sq. ft. \_\_\_\_\_

Swimming Pools Above Ground \_\_\_\_\_  
In Ground \_\_\_\_\_

Fire/Burglar Alarms Residential \_\_\_\_\_  
Commercial \_\_\_\_\_

Heavy Duty Outlets, 220 Volt (such as welders) 30 amps and under \_\_\_\_\_  
over 30 amps \_\_\_\_\_

Circus, Fairs, etc. \_\_\_\_\_

Alterations to wires \_\_\_\_\_

Repairs after fire \_\_\_\_\_

Emergency Lights, battery \_\_\_\_\_

Emergency Generators \_\_\_\_\_

FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT ..... INSTALLATION FEE DUE:  
FOR REMOVAL OF A "STOP ORDER" (304-16.b) ..... DOUBLE FEE DUE:

TOTAL AMOUNT DUE: 81.50

INSPECTION:

Will be ready on \_\_\_\_\_, 19\_\_\_\_; or Will Call xx

CONTRACTOR'S NAME: John Perry

ADDRESS: 381 Danforth St.

TEL.: \_\_\_\_\_

MASTER LICENSE NO.: 3595 SIGNATURE OF CONTRACTOR: \_\_\_\_\_

LIMITED LICENSE NO.: \_\_\_\_\_

INSPECTOR'S COPY — WHITE

OFFICE COPY — CANARY

CONTRACTOR'S COPY — GREEN

## Permit Number 01167

Permit Number 01167

Location 247 Congress St

OWNER: Mr. J. J. Jones

Date of Permit 10-1-65

Final Inspection *247*

By Inspector W. C. Sullivan

Permit Application Register Page No. 22

INSPECTIONS: Service \_\_\_\_\_ by Kibby  
Service called in 11-18-80  
Closing-in \_\_\_\_\_ by \_\_\_\_\_

PROGRESS INSPECTIONS: 11-25-80 / \_\_\_\_\_

11-25-80 \_\_\_\_\_ / \_\_\_\_\_  
12-2-80 \_\_\_\_\_ / \_\_\_\_\_

1-9-81 \_\_\_\_\_

2-12-81 \_\_\_\_\_ 1 \_\_\_\_\_

\_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

\_\_\_\_\_ / \_\_\_\_\_ / \_\_\_\_\_

CODE  
COMPLIANCE  
COMPLETED  
DATE 2-12-8

DATE: \_\_\_\_\_ RE: \_\_\_\_\_

DATE:

REMARKS:

[illegible]





APPLICATION FOR PERMIT  
DEPARTMENT OF BUILDING INSPECTIONS SERVICES  
ELECTRICAL INSTALLATIONS

Date Aug. 14, 19 78  
Receipt and Permit number A 12847

To the CHIEF ELECTRICAL INSPECTOR, Portland, Maine:

The undersigned hereby applies for a permit to make electrical installations in accordance with the laws of Maine, the Portland Electrical Ordinance, the National Electrical Code and the following specifications:

LOCATION OF WORK: 345 Outer Congress St. - accross from Elks Lodge

OWNER'S NAME: DIRENZO ADDRESS: \_\_\_\_\_

OUTLETS: (number of)

|             |                        |      |
|-------------|------------------------|------|
| Lights      | _____                  |      |
| Receptacles | _____                  |      |
| Switches    | _____                  |      |
| Plugmold    | _____ (number of feet) |      |
| TOTAL       | _____                  | FEES |

FIXTURES: (number of)

|                            |  |  |
|----------------------------|--|--|
| Incandescent               | _____                                    |  |
| Fluorescent                | _____ (Do not include strip fluorescent) |  |
| TOTAL                      | _____                                    |  |
| Strip Fluorescent, in feet | _____                                    |  |

SERVICES:

|                          |           |             |
|--------------------------|-----------|-------------|
| Permanent, total amperes | _____     |             |
| Temporary                | <u>60</u> | <u>3.00</u> |

METERS: (number of) 1 \_\_\_\_\_ .50

MOTORS: (number of)

|              |       |  |
|--------------|-------|--|
| Fractional   | _____ |  |
| 1 HP or over | _____ |  |

RESIDENTIAL HEATING:

|                              |       |  |
|------------------------------|-------|--|
| Oil or Gas (number of units) | _____ |  |
| Electric (number of rooms)   | _____ |  |

COMMERCIAL OR INDUSTRIAL HEATING:

|                                |       |  |
|--------------------------------|-------|--|
| Oil or Gas (by a main boiler)  | _____ |  |
| Oil or Gas (by separate units) | _____ |  |
| Electric (total number of kws) | _____ |  |

APPLIANCES: (number of)

|            |       |                 |       |  |
|------------|-------|-----------------|-------|--|
| Ranges     | _____ | Water Heaters   | _____ |  |
| Cook Tops  | _____ | Disposals       | _____ |  |
| Wall Ovens | _____ | Dishwashers     | _____ |  |
| Dryers     | _____ | Compactors      | _____ |  |
| Fans       | _____ | Others (denote) | _____ |  |
| TOTAL      | _____ |                 |       |  |

MISCELLANEOUS: (number of)

|                           |                                    |             |
|---------------------------|------------------------------------|-------------|
| Branch Panels             | _____                              |             |
| Transformers              | _____                              |             |
| Air Conditioners          | _____                              |             |
| Signs                     | <u>2- under 20 sq. ft. (242.1)</u> | <u>5.00</u> |
| Fire/Burglar Alarms       | <u>Pole NET 259</u>                |             |
| Circus, Fairs, etc.       | _____                              |             |
| Alterations to wires      | _____                              |             |
| Repairs after fire        | _____                              |             |
| Heavy Duty, 220v outlets  | _____                              |             |
| Emergency Lights, battery | _____                              |             |
| Emergency Generators      | _____                              |             |

INSTALLATION FEE DUE:

FOR ADDITIONAL WORK NOT ON ORIGINAL PERMIT ..... DOUBLE FEE DUE: \_\_\_\_\_

FOR REMOVAL OF A "STOP ORDER" (304-16.b) ..... \_\_\_\_\_

FOR PERFORMING WORK WITHOUT A PERMIT (304-9) ..... \_\_\_\_\_

TOTAL AMOUNT DUE: 8.50

INSPECTION:

Will be ready on ready, 19 78; or Will Call \_\_\_\_\_

CONTRACTOR'S NAME: Guy M. Maiorano - M & M Electric

ADDRESS: 16 Chevrus Rd. Cape Eliz, Me.

TEL.: \_\_\_\_\_

MASTER LICENSE NO.: 94

SIGNATURE OF CONTRACTOR:

LIMITED LICENSE NO.: \_\_\_\_\_

Guy Maiorano

INSPECTOR'S COPY

Permit Number 12847Permit Number 12847

| Location | Considers |
|----------|-----------|
|          |           |

Owner D. J. Jones

Date of Permit A-18-78

Final Inspection

By Instrument

7/17/66

Precedent Register Page No. -/

1. The first step is to identify the problem or question that needs to be addressed. This involves understanding the context and the specific requirements of the task.

[illegible]

1. The first step is to identify the problem or question that needs to be addressed. This involves understanding the context and the specific requirements of the task.

2. Next, it is important to gather relevant information and data. This can be done through research, consultation with experts, or by analyzing existing resources.

3. Once the information is gathered, the next step is to develop a plan or strategy. This involves breaking down the problem into smaller, manageable parts and determining the best approach to solve each part.

4. The fourth step is to implement the plan. This involves putting the strategy into action and monitoring progress to ensure that the goals are being met.

5. Finally, it is important to evaluate the results and make adjustments as needed. This involves reflecting on what worked well and what didn't, and using that information to improve future performance.

— / —  
— / —  
— / —  
— / —  
— / —

1. The first part of the document is a letter from the author to the reader, explaining the purpose of the study and the methods used. The letter is dated 1998 and is addressed to the reader.

by \_\_\_\_\_

1

28  
21  
-1  
-1  
-1  
-1

6-27

17

8  
9

called \_\_\_\_\_  
in \_\_\_\_\_  
S: \_\_\_\_\_  
\_\_\_\_\_

[illegible]

Se  
Cl  
PEC  
D  
LE  
21

INS  
C  
17  
8

ESS

LOGR

**PR**

1

1. The first step is to identify the problem or question that needs to be addressed. This involves understanding the context and the specific requirements of the task.

CODE  
REFERENCE  
APPLIED

DATE 8-17-78

DATE.

REMARKS:

2016 245  
2016 J 242.1  
2016 WEST 259



CITY OF PORTLAND, MAINE  
Department of Building Inspection

## Certificate of Occupancy

LOCATION 247 Congress Street

Issued to Albert C. Wilson

Date of Issue March 29, 1978

This is to certify that the building, premises, or part thereof, at the above location, built—altered—changed as to use under Building Permit No. 78/195, has had final inspection, has been found to conform substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

APPROVED OCCUPANCY

1st floor

Second hand shop

Limiting Conditions:

This certificate supersedes  
certificate issued

Approved:

3/29/78  
(Date)

H. Swings  
Inspector

Inspector of Buildings

Notice: This certificate identifies lawful use of building or premises, and ought to be transferred from owner to owner when property changes hands. Copy will be furnished to owner of record for one dollar.





# APPLICATION FOR PERMIT

B.O.C.A. USE GROUP .....  
B.O.C.A. TYPE OF CONSTRUCTION ..... 0195  
ZONING LOCATION B-2 PORTLAND, MAINE, March 28, 1978

PERMIT ISSUED

MAR 29 1978

CITY OF PORTLAND

To the DIRECTOR OF BUILDING & INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish, move or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.O.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications:

LOCATION 247 Congress St. Fire District #1 ☐ #2 ☐  
1. Owner's name and address Kirk Sawyer Realty - same Telephone 772-5866  
2. Lessor's name and address Albert C. Wilson - same Apt. B-1 Telephone same  
3. Contractor's name and address C/O Barbara Palmer Telephone .....  
4. Architect ..... Specifications ..... Plans ..... No. of sheets .....  
Proposed use of building second hand store No. families .....  
Last use novelties shop No. families .....  
Material ..... No. stories ..... Heat ..... Style of roof ..... Roofing .....  
Other buildings on same lot .....  
Estimated contractual cost \$ ..... Fee \$ 5.00

FIELD INSPECTOR—Mr. Hugh ..... GENERAL DESCRIPTION

This application is for: @ 775-5451  
Dwelling ..... Ext. 234 Change of use from novelties shop to second hand shop  
Garage .....  
Masonry Bldg. ....  
Metal Bldg. ....  
Alterations ..... Stamp of Special Conditions  
Demolitions .....  
Change of Use XX .....  
Other .....

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 ☐ 2 ☒ 3 ☐ 4 ☐  
Other: .....

## DETAILS OF NEW WORK

Is any plumbing involved in this work? ..... Is any electrical work involved in this work? .....  
Is connection to be made to public sewer? ..... If not, what is proposed for sewage? .....  
Has septic tank notice been sent? ..... Form notice sent? .....  
Height average grade to top of plate ..... Height average grade to highest point of roof .....  
Size, front ..... depth ..... No. stories ..... solid or filled land? ..... earth or rock? .....  
Material of foundation ..... Thickness, top ..... bottom ..... cellar .....  
Kind of roof ..... Rise per foot ..... Roof covering .....  
No. of chimneys ..... Material of chimneys ..... f lining ..... Kind of heat ..... fuel .....  
Framing Lumber—Kind ..... Dressed or full size? ..... Corner posts ..... Sills .....  
Size Girder ..... Columns under girders ..... Size ..... Max. on centers .....  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor ..... 2nd ..... 3rd ..... roof .....  
On centers: 1st floor ..... 2nd ..... 3rd ..... roof .....  
Maximum span: 1st floor ..... 2nd ..... 3rd ..... roof .....  
If one story building with masonry walls, thickness of walls? ..... height? .....

## IF A GARAGE

No. cars now accommodated on same lot ..... to be accommodated ..... number commercial cars to be accommodated .....  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? .....

APPROVALS BY: DATE

BUILDING INSPECTION—PLAN EXAMINER

ZONING: OK. M.G.W. 3/29/78

BUILDING CODE: .....

Fire Dept.: .....

Health Dept.: .....

Others: .....

## MISCELLANEOUS

Will work require disturbing of any tree on a public street? .....

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? .....

Signature of Applicant Albert C. Wilson Phone # same

Type Name of above Albert C. Wilson 1 ☐ 2 ☒ 3 ☐ 4 ☐

Other .....  
and Address .....

FIELD INSPECTOR'S COPY

Mar 29/78

Permit No. 78/0195

Location 24) Swampy 41

Owner Shirley D. DeWitt

Date of Permit 10-29-

Approved 3-29-78



## APPLICATION FOR PERMIT

PERMIT ISSUED

B.O.C.A. USE GROUP .....

B.O.C.A. TYPE OF CONSTRUCTION .....

ZONING LOCATION B-2 PORTLAND, MAINE, Dec. 5, 1977.

DEC 5 1977

CITY of PORTLAND

To the DIRECTOR OF BUILDING &amp; INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish, move or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.O.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications.

LOCATION 247 Congress StreetFire District #1 ☐, #2 ☐1. Owner's name and address Sawyer Realty Co., -399 Fore Street Telephone 772-65792. Lessee's name and address William Greenleaf, -38 Illsley St. Telephone 774-9656

3. Contractor's name and address ..... Telephone .....

4. Architect ..... Specifications ..... Plans ..... No. of sheets .....

Proposed use of building novelties - new ..... No. families .....Last use novelties & clothing store ..... No. families .....

Material ..... No. stories ..... Heat ..... Style of roof ..... Roofing .....

Other buildings on same lot .....

Estimated contractual cost \$ ..... Fee \$ 5.00

FIELD INSPECTOR—Mr. ....

## GENERAL DESCRIPTION

This application is for:

@ 775-5451

Dwelling ..... Ext. 234

Garage .....

Masonry Bldg. ....

Metal Bldg. ....

Alterations .....

Demolitions .....

Change of Use xx .....

Other .....

Change of use from novelties and clothing store to novelties only, new

Stamp of Special Conditions

*No alterations*

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 ☐ 2 ☐ 3 ☐ 4 ☐

Other: .....

## DETAILS OF NEW WORK

Is any plumbing involved in this work? ..... Is any electrical work involved in this work? .....

Is connection to be made to public sewer? ..... If not, what is proposed for sewage? .....

Has septic tank notice been sent? ..... Form notice sent? .....

Height average grade to top of plate ..... Height average grade to highest point of roof .....

Size, front ..... depth ..... No. stories ..... solid or filled land? ..... earth or rock? .....

Material of foundation ..... Thickness, top ..... bottom ..... cellar .....

Kind of roof ..... Rise per foot ..... Roof covering .....

No. of chimneys ..... Material of chimneys ..... of lining ..... Kind of heat ..... fuel .....

Framing Lumber—Kind ..... Dressed or full size? ..... Corner posts ..... Sills .....

Size Girder ..... Columns under girders ..... Size ..... Max. on centers .....

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor ..... 2nd ..... 3rd ..... roof .....

C.A. centers: 1st floor ..... 2nd ..... 3rd ..... roof .....

Maximum span: 1st floor ..... 2nd ..... 3rd ..... roof .....

If one story building with masonry walls, thickness of walls? ..... height? .....

## IF A GARAGE

No. cars now accommodated on same lot ...., to be accommodated ... number commercial cars to be accommodated ...

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? .....

## APPROVALS BY:

## DATE

## MISCELLANEOUS

BUILDING INSPECTION—PLAN EXAMINER .....

ZONING: OK 1126.0 12/5/77 .....

BUILDING CODE .....

Fire Dept.: .....

Health Dept.: .....

Others: .....

Will work require disturbing of any tree on a public street? ..

Will there be in charge of the above work a person competent

to see that the State and City requirements pertaining thereto

are observed? .....

Signature of Applicant William F. Greenleaf Jr. Phone # sameType Name of above William Greenleaf 1 ☐ 2 ☒ 3 ☐ 4 ☐

Other .....

and Address .....

FIELD INSPECTOR'S COPY







13-2  
APPLICATION FOR PERMIT TO ERECT 463  
SIGN OVER PUBLIC SIDEWALK OR STREET

PERMIT ISSUED

JUN 16 1975

Portland, Maine, June 13, 1975 CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 243 Congress Street Within Fire Limits? yes Dist. No.  
Owner of building to which sign is to be attached Mark Foley  
Name and address of owner of sign Louis G. Distasio, 8 Jewett Rd., Cape Elizabeth  
Contractor's name and address Coyne Sign Co., Cove Street (66) Telephone 7744330  
When does contractor's bond expire?

Information Concerning Building

No. stories 3 Material of wall to which sign is to be attached steel beam

Details of Sign and Connections

Building owner's consent and agreement filed with application yes  
Electric? no Vertical dimension after erection 24" Horizontal 30"  
Weight 30 lbs. lbs., Will there be any hollow spaces? no Any rigid frame? yes  
Material of frame XXX angle iron No. advertising faces 2 material sheet metal  
No. rigid connections 2 Are they fastened directly to frame of sign? yes  
No. through bolts none Size Location, top or bottom  
No. guys 2 material 3/16" steel cable Size  
Minimum clear height above sidewalk or street 12'  
Maximum projection into street none Fee \$ 5.50

Signature of contractor

Louis G. Distasio (owner)

INSPECTION COPY

ZONING OK 11/13/75

O.K. E.B. 6/16/75

75/463  
5AM  
Permit No. 243  
Location CONGRESS ST  
Owner FOLEY  
Date of permit 6/16/75  
Sign Contractor  
Final Inspn

NOTES  
6-17-75 ~~not started~~  
6-25-75 ~~Completed~~

RECEIVED  
CITY OF SEATTLE  
DEPT. OF PUBLIC WORKS  
DIVISION OF STREET  
IMPROVEMENTS  
JUN 17 1975  
11



WRITTEN CONSENT AND AGREEMENT RELATING TO A CERTAIN SIGN PROPOSED  
TO BE ERECTED PROJECTING OVER A PUBLIC SIDEWALK FROM THE  
PREMISES AT 243 Congress St. IN PORTLAND, MAINE

Mark R. Foley being the owner of the  
premises at 243 Congress St. in Portland, Maine hereby  
gives consent to the erection of a certain sign owned by  
\_\_\_\_\_ projecting over the public sidewalk  
from said premises as described in application to the Inspector  
of Buildings of Portland, Maine for a permit to cover erection  
of said sign;

And in consideration of the issuance of said permit  
Mark R. Foley, owner of said premises,  
in event said sign shall cease to serve the purpose for which  
it was erected or shall become dangerous and in event the owner  
of said sign shall fail to remove said sign or make it permanently  
safe in case the sign still serves the purpose for which it was  
erected, hereby agrees for himself or itself, for his heirs,  
its successors, and his or its assigns, to completely remove  
said sign within ten days of notice from said Inspector of  
Buildings that said sign is in such condition and of order from  
him to remove it.

In Witness whereof, the owner of said premises has signed  
this consent and agreement this Twelfth  
day of June 1977

Wangam Moore  
Witness

Mark R. Foley  
Owner



## APPLICATION FOR PERMIT

PERMIT ISSUED

B.O.C.A. USE GROUP .....

JUN 4 1975

B.O.C.A. TYPE OF CONSTRUCTION .....

424

ZONING LOCATION ..... PORTLAND, MAINE, June 3, 1975

CITY of PORTLAND

To the DIRECTOR OF BUILDING &amp; INSPECTION SERVICES, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect, alter, repair, demolish, move or install the following building, structure, equipment or change use in accordance with the Laws of the State of Maine, the Portland B.O.C.A. Building Code and Zoning Ordinance of the City of Portland with plans and specifications, if any, submitted herewith and the following specifications:

LOCATION 243 Congress St

Fire District #1 ☐ #2 ☐

1. Owner's name and address .. Mark Foley, same .. Telephone .. 772-8573

2. Lessee's name and address .. .. Telephone .. 775-6145

3. Contractor's name and address .. Harold J. Freeman .. Telephone ..

4. Architect .. Specifications .. Plans .. No. of sheets ..

Proposed use of building .. No. families ..

Last use .. dwelling .. No. families ..

Material .. No. stories .. Heat .. Style of roof .. Roofing ..

Other buildings on same lot ..

Estimated contractual cost \$ .. 3,000.00 .. Fee \$ .. 12.00

FIELD INSPECTOR—Mr. .... GENERAL DESCRIPTION

This application is for: @ 775-5451 to repair roof. (wind damage - structural)

Dwelling .. Ext. 234

Garage ..

Masonry Bldg. ..

Metal Bldg. ..

Alterations ..

Demolitions ..

Change of Use ..

Other ..

Stamp of Special Conditions

NOTE TO APPLICANT: Separate permits are required by the installers and subcontractors of heating, plumbing, electrical and mechanicals.

PERMIT IS TO BE ISSUED TO 1 ☐ 2 ☐ 3 ☒ 4 ☐

Other: ..

## DETAILS OF NEW WORK

Is any plumbing involved in this work? .. no .. Is any electrical work involved in this work? .. no ..

Is connection to be made to public sewer? .. If not, what is proposed for sewage? ..

Has septic tank notice been sent? .. Form notice sent? ..

Height average grade to top of plate .. Height average grade to highest point of roof ..

Size, front .. depth .. No. stories .. solid or filled land? .. earth or rock? ..

Material of foundation .. Thickness, top .. bottom .. cellar ..

Kind of roof .. Rise per foot .. Roof covering ..

No. of chimneys .. Material of chimneys .. of lining .. Kind of heat .. fuel ..

Framing Lumber—Kind .. Dressed or full size? .. Corner posts .. Sills ..

Size Girder .. Columns under girders .. Size .. Max. on centers ..

Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.

Joists and rafters: 1st floor .., 2nd .., 3rd .., roof ..

On centers: 1st floor .., 2nd .., 3rd .., roof ..

Maximum span: 1st floor .., 2nd .., 3rd .., roof ..

If one story building with masonry walls, thickness of walls? .. height? ..

## IF A GARAGE

No. cars now accommodated on same lot .., to be accommodated .. number commercial cars to be accommodated ..

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? ..

## APPROVALS BY:

## DATE

## MISCELLANEOUS

BUILDING INSPECTION—PLAN EXAMINER .. Will work require disturbing of any tree on a public street? ..

ZONING: ..

BUILDING CODE: 0.12.2.8.6(41.7) .. Will there be in charge of the above work a person competent

Fire Dept.: .. to see that the State and City requirements pertaining thereto

Health Dept.: .. are observed? .. YES ..

Others: ..

Signature of Applicant .. Mark R. Foley .. Phone # .. above ..

Type Name of above .. Mark Foley .. 1 ☒ 2 ☐ 3 ☐ 4 ☐

Other ..

and Address ..

FIELD INSPECTOR'S COPY

NOTES

6-11-75 not started  
 6-25-75 work started couldn't  
 get in  
 7-9-75 Couldn't get in  
 7-16-75 same  
 7-22-75 Completed without inspection

Permit No. 75/424  
 Location 243 Concess St  
 Owner Foley  
 Date of permit 6/4/75  
 Approved  
 SAM

PERMIT TO INSTALL PLUMBING  
Address **243 Congress St. Apt. #5** PERMIT NUMBER **3333**  
Installation For **mult.**  
Owner of Bldg **Peter Masan**  
Owner's Address **RFD #1, Trundy Rd., Cape Elizabeth**  
Plumber **Northern Utilities** Date **9-20-73**  
**1075 Forest Ave**

Date Issued **September 20, 1973**  
Portland Plumbing Inspector  
By **ERNOLD R GOODWIN**

App. First Insp.

Date

By

App. Final Insp.

Date

By

Type of Bldg.

- ☐ Commercial  
☐ Residential  
☐ Single  
☐ Multi Family  
☐ New Construction  
☐ Remodeling

| NEW | REPL |                        |  |   |      |  |
|-----|------|------------------------|--|---|------|--|
|     |      | SINKS                  |  |   |      |  |
|     |      | LAVATORIES             |  |   |      |  |
|     |      | TOILETS                |  |   |      |  |
|     |      | BATH TUBS              |  |   |      |  |
|     |      | SHOWERS                |  |   |      |  |
|     |      | DRAINS                 |  |   |      |  |
|     |      | FLOOR SURFACE          |  |   |      |  |
|     | 1    | HOT WATER TANKS        |  |   |      |  |
|     |      | TANKLESS WATER HEATERS |  | 1 | 2.00 |  |
|     |      | GARAGE DISPOSALS       |  |   |      |  |
|     |      | SEPTIC TANKS           |  |   |      |  |
|     |      | HOUSE SEWERS           |  |   |      |  |
|     |      | ROOF LEADERS           |  |   |      |  |
|     |      | AUTOMATIC WASHERS      |  |   |      |  |
|     |      | DISHWASHERS            |  |   |      |  |
|     |      | OTHER                  |  |   |      |  |

Building and Inspection Services Dept.; Plumbing Inspection

TOTAL 1 2.00



**PERMIT TO INSTALL PLUMBING**

Date Issued 5-25-72 PERMIT NUMBER 438

Portland Plumbing Inspector

By ERNOLD R. GOODWIN

App. First Insp. 5-25-72

Date \_\_\_\_\_

By \_\_\_\_\_

App. Final Insp. \_\_\_\_\_

Date \_\_\_\_\_

By \_\_\_\_\_

Type of Bldg.

☐ Commercial

☐ Residential

☐ Single

☐ Multi Family

☐ New Construction

☐ Remodeling

Address \_\_\_\_\_

Installation For: 247 Congress St.

Owner of Bldg.: Multi

Owner's Address: Woodlawn Ave.

Plumber: A. H. Cousins

| NEW   | REPL | NO.                    | FEE  |
|-------|------|------------------------|------|
|       |      | SINKS                  |      |
| 1     |      | LAVATORIES             |      |
| 1     |      | TOILETS                | 2.00 |
| 1     |      | BATH TUBS              | 2.00 |
|       |      | SHOWERS                | 2.00 |
|       |      | DRAINS                 |      |
| 1     |      | FLOOR SURFACE          |      |
|       |      | HOT WATER TANKS        |      |
|       |      | TANKLESS WATER HEATERS | 2.00 |
|       |      | GARBAGE DISPOSALS      |      |
|       |      | SEPTIC TANKS           |      |
|       |      | HOUSE SEWERS           |      |
|       |      | ROOF LEADERS           |      |
|       |      | AUTOMATIC WASHERS      |      |
|       |      | DISHWASHERS            |      |
|       |      | OTHER                  |      |
| TOTAL |      |                        | 8.00 |

Building and Inspection Services Dept.; Plumbing Inspection

☐ Commercial  
☐ Residential  
☐ Single  
☐ Multi Family  
☐ New Construction  
☐ Remodeling

LINKS NO JULY 30, 1951

| SINKS |                        | NO | DATE |
|-------|------------------------|----|------|
|       | LABORATORIES           |    |      |
|       | TOILETS                |    |      |
|       | BATH TUBS              |    |      |
|       | SHOWERS                |    |      |
|       | DRAINS FLOOR SURFACE   |    |      |
| x     | HOT WATER TANKS        | 1  |      |
|       | TANKLESS WATER HEATERS |    |      |
|       | GARBAGE DISPOSALS      |    |      |
|       | SEPTIC TANKS           |    |      |
|       | HOUSE SEWERS           |    |      |
|       | ROOF LEADERS           |    |      |
|       | AUTOMATIC WASHERS      |    |      |
|       | DISHWASHERS            |    |      |
|       | OTHER                  |    |      |

Building and Inspection Services Dept., Plumbing Inspection

# PERMIT TO INSTALL PLUMBING

Date Issued **12-27-72**

Portland Plumbing Inspector

By ERNOLD R. GOODWIN

App. First Insp.

Date \_\_\_\_\_

By

Date \_\_\_\_\_

By

Type of Bldg.

- ☐ Commercial  
☐ Residential  
☐ Single  
☐ Multi Family  
☐ New Construction  
☐ Remodeling

PERMIT NUMBER 121

Address 347 Congress St.  
Installation F

Installation For: Multi

Owner of Bldg: Mrs. Viola Tathum

Owner's Address: 160 Noyes St.

Plumber: Northern Utilities

Date: 7-27-89

| NEW | REPL. | DATE                   | NO      | FEE  |
|-----|-------|------------------------|---------|------|
|     |       | 5 Maple St.            |         |      |
|     |       | SINKS                  |         |      |
|     |       | LAVATORIES             |         |      |
|     |       | TOILETS                |         |      |
|     |       | BATH TUBS              |         |      |
|     |       | SHOWERS                |         |      |
|     |       | DRAINS FLOOR SURFACE   |         |      |
|     | 1     | HOT WATER TANKS        |         | 2.00 |
|     |       | TANKLESS WATER HEATERS |         |      |
|     |       | GARBAGE DISPOSALS      |         |      |
|     |       | SEPTIC TANKS           |         |      |
|     |       | HOUSE SEWERS           |         |      |
|     |       | ROOF LEADERS           |         |      |
|     |       | AUTOMATIC WASHERS      |         |      |
|     |       | DISHWASHERS            |         |      |
|     |       | OTHER                  |         |      |
|     |       |                        | TOTAL 1 | 2.00 |

Building and Inspection Services Dept.; Plumbing Inspection:

CITY OF PORTLAND, MAINE  
MEMORANDUM

TO: Gordon E. Martin, Housing Supervisor

DATE: August 26, 1960

FROM: Albert J. Sears, Inspector of Buildings

SUBJECT: Your memo concerning building at 243-247 Congress Street

An inspection of the building at the above named location by this department discloses no condition which can be termed unsafe from a structural standpoint or which would warrant the taking of any action by this department.

Very truly yours,

AJS/jg

Inspector of Buildings



CITY OF PORTLAND, MAINE  
MEMORANDUM

TO: Mr. Albert Sears, Building Inspector  
FROM: Gordon E. Martin, Housing Supervisor  
SUBJECT: 243-247 Congress Street

DATE August 6, 1960

We inspected 243-247 Congress Street as a part of the Bayside Urban Renewal Project. We found the center of the building near the air shaft to be sagging. On our orders dated June 6, 1960, we told the owner to determine the reason and remedy the condition which now causes the building to sag in the center.

Since that time, Mr. Donald Currier of 1695 Broadway, South Portland, Mr. Greenberg's contractor, has called and said the condition has been the same for many years and doubts if it will sag anymore. We will appreciate it if you will have one of your men check into the matter and let us know whether or not the building is all right in its present condition.

*P. H.*

8/26/60 - G. E. M. looked building over and reported that he could find nothing structurally unsound. See letter to Mr. Martin - AGS

# CITY OF PORTLAND, MAINE

## Application for Permit to Install Wires

Permit No. 55259  
 Issued Oct 6, 19 66

Portland, Maine

To the City Electrician, Portland, Maine:

The undersigned hereby applies for a permit to install wires for the purpose of conducting electric current, in accordance with the laws of Maine, the Electrical Ordinance of the City of Portland, and the following specifications:

(This form must be completely filled out — Minimum Fee, \$1.00)

Owner's Name and Address A. R. Philippe Tel. 7724420

Contractor's Name and Address Augusto Velasco

Location 247 Congress St. Use of Building

Number of Families 1 Apartments 1 Stores 1

Description of Wiring: New Work Alterations

Pipe 1 Cable 1 Metal Molding 1 BX Cable 1 Plug Molding (No. of feet) 1

No. Light Outlets 1 Plugs 2 Light Circuits 1 Plug Circuits 1

FIXTURES: No. 1 Light Switches 1 Fluor. or Strip Lighting (No. feet) 1

SERVICE: Pipe 1 Cable 1 Underground 1 No. of Wires 1 Size 1

METERS: Relocated 1 Added 1 Total No. Meters 1

MOTORS: Number 1 Phase 1 H. P. 1 Amps 1 Volts 1 Starter 1

HEATING UNITS: Domestic (Oil) 1 No. Motors 1 Phase 1 H. P. 1

Commercial (Oil) 1 No. Motors 1 Phase 1 H. P. 1

Electric Heat (No. of Rooms) 1 Brand Feeds (Size and No.) 1

APPLIANCES: No. Ranges 1 Watts 1 Extra Cabinets or Panels 1

Elec. Heaters 1 Watts 1 Signs (No. Units) 1

Miscellaneous 1 Watts 1 Inspection 1

Transformers 1 Air Conditioners (No. Units) 1 Will commence 1

Amount of Fee \$ 19 Ready to cover in 19

Signed 19

DO NOT WRITE BELOW THIS LINE

SERVICE 1 METER 1 GROUND 1

VISITS: 1 2 3 4 5 6 7 8 9 10 11 12

REMARKS: 1.50

2.50

3.50

INSPECTED BY 7 W. H. H. (OVER)

LOCATION *Congress St. 247*  
 INSPECTION DATE *11/10/66*  
 WORK COMPLETED *11/10/66*  
 TOTAL NO. INSPECTIONS *1*  
 REMARKS:

**FEE S FOR WIRING PERMITS EFFECTIVE JULY 31, 1963**

|   |                              |
|---|------------------------------|
| <b>WIRING</b>   |                              |
| 1 to 30 Outlets   |                              |
| 31 to 60 Outlets  | (including switches) \$ 2.00 |
| Over 60 Outlets, each Outlet  | (including switches) \$ 3.00 |
| (Each twelve feet or fraction thereof of fluorescent lighting or any type of plug molding will be classed as one outlet). | .05                          |
| <b>SERVICES</b>   |                              |
| Single Phase  |                              |
| Three Phase   |                              |
| <b>MOTORS</b>   |                              |
| Not exceeding 50 H.P.   | 2.00                         |
| Over 50 H.P.  | 4.00                         |
| <b>HEATING UNITS</b>  |                              |
| Domestic (Oil)  | 3.00                         |
| Commercial (Oil)  | 4.00                         |
| Electric Heat (Each Room)   | 2.00                         |
| <b>APPLIANCES</b>   |                              |
| Ranges, Cooking Tops, Ovens, Water Heaters, Disposals, Dishwashers, etc. — Each Unit                                      | 4.00                         |
| <b>TEMPORARY WORK (Limited to 6 months from date of permit)</b>   |                              |
| Service, Single Phase   | 1.50                         |
| Service, Three Phase  |                              |
| Wiring, 150 Outlets   | 1.00                         |
| Wiring, each additional outlet over 50  | 2.00                         |
| Circuits, Carnivals, Fairs, etc.  | 1.00                         |
| MISCELLANEOUS   | .02                          |
| Distribution Fee  | 10.00                        |





[illegible]

Mr. Albert Searo, Building Inspector  
Gordon E. Martin, Housing Supervisor  
243-247 Congress Street

August 8, 1960

We inspected 243-247 Congress Street as a part of the Bayside Urban Renewal Project. We found the center of the building near the air shaft to be sagging. At our orders dated June 8, 1960, we told the owner to determine the reason and remedy the condition which now causes the building to sag in the center.

Since that time, Mr. Donald Currier of 1695 Broadway, South Portland, Mr. Greenberg's contractor, has called and said the condition has been the same for many years and doubts if it will sag anymore. We will appreciate it if you will have one of your men check into the matter and let us know whether or not the building is all right in its present condition.

[illegible]

CITY OF PORTLAND  
HEALTH DEPARTMENT  
HOUSING DIVISION



Loc. 247 1000-11 STREET  
Loc. #/1 S 13 1466  
Bldg. Fire Elec. Other  
Issued June 8, 1960  
Expires July 8, 1960

Mr. Morris Greenberg  
150 11th Street  
Portland, Maine

Dear Sir:

On June 7, 1960 an examination was made of the premises located at 150 11th Street, Portland, Maine. Non-compliance with the ordinances relating to housing conditions was found as detailed below. In accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action. Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started. If any additional information is desired, visit or telephone the Housing Supervisor at this Office, Spruce 4-8221, extension 226. Kindly notify this office as soon as all corrections have been completed.

Very truly yours,  
Douglas H. Brown, V. D.  
Health Director

By \_\_\_\_\_  
Housing Supervisor

VIOLATIONS & SPECIFICATIONS

## Responsibility of Owner or Agent \*\* Responsibility of Occupant

- | ## | VIOLATIONS  | ## | SPECIFICATIONS  |
|----|---|----|---|
| 1. | Repair and put in good order all dilapidated and boarded parts of the structure as follows:   | 1. | Repair and put in good order all dilapidated and boarded parts of the structure as follows:   |
| 2. | Repair or replace the missing bricks and point up the loose joints in the foundation.   | 2. | Repair or replace the deteriorating metal covering on the rear walls.   |
| 3. | Determine the reason and remedy the condition which may cause the structure to sag to the left and center.  | 3. | Determine the reason and remedy the condition which may cause the stairs and floors to sag throughout the structure.  |
| 4. | Repair the loose window panes, tighten the loose window casings throughout the structure. Particular attention is directed to the kitchen and living room of the 2nd floor right apt., in the kitchen, living room, front bedroom, and den of the 2nd floor left apt., in the kitchen, living room, and rear bedroom of the 3rd floor right apt., in the living room, rear bedroom, and front bedroom of the 3rd floor left apt., in the kitchen, front bedroom, and rear bedroom of the 4th floor right apt., and in the kitchen, dining room, bedroom, and porch of the 4th floor left apt. | 4. | Repair or replace the defective lock on the rear kitchen door of the 2nd floor right apt.   |
| 5. | Repair or replace the tilted cellar stairs.   | 5. | Determine the reason and remedy the condition which may cause the bathroom ceiling in the 2nd floor right apt. to show signs of leakage.  |
| 6. | Repair or replace the cracked, loose, or missing plaster on the walls of the bathroom and rear bedroom of the 2nd floor right apt., in the kitchen of the 2nd floor left apt., in the kitchen of the 3rd floor left apt., and in the dining room and bedroom of the 4th floor left apt.   | 6. | Repair or replace the cracked, loose, or missing plaster on the ceiling of the living room, front bedroom, and rear bedroom of the 2nd floor right apt., in the den of the 2nd floor left apt., and in the kitchen of the 3rd floor left apt. |
| 7. | Repair and have replaced all defective electric wiring and electrical equipment throughout the structure.   | 7. | Repair or replace the loose wire in the front bedroom fixture of the 3rd floor right apt.   |

(OVER)



- b. Repair or replace the defective fixtures in the kitchen and bathroom of the 4th floor right apt.
- c. Install conveniences unless there is a dangerous extensive use of extension cords in the front and rear bedrooms of the 2nd floor right apt., in the front bedroom and den of the 2nd floor left apt., in the front and rear bedrooms of the 3rd floor right apt., in the bedrooms of the 4th floor right apt., and in the dining room of the 4th floor left apt.
- d. Disconnect and do not connect again the extension cord now unsafely running thru the wall to the porch in the 4th floor left apt.

#### Plumbing:

Owner and have repaired all defective plumbing and plumbing fixtures throughout the structure.

- a. Repair or replace the broken cast iron in the bathroom of the 4th floor right apt.
- b. Remove the recess and remove the extension which now causes the waste line to leak into the flower shop and below the 1st floor into the cellar.

#### Electric:

- a. Repair or replace the broken switch near the water heater in the 2nd floor left apt.
- b. Repair or replace the missing metal fire door.

#### Sanitation and Housekeeping (Garage and)

- a. Provide suitable, sufficient, water-tight, tightly covered metal garbage and rubbish containers to receive the accumulation of garbage and rubbish during the intervals between collections.
- b. Insure a general cleanup of the cellar by removing and properly disposing of all trash, filth, litter, and debris.

The above mentioned conditions are in violation of the City Ordinance, Minimum Standards for Sanitation, Section 24, Chapter 11, and Chapter 12, and Chapter 13, and must be corrected on or before July 8, 1960.

If in the event you are unable to correct the substandard conditions by the date specified above, please contact this office at your earliest convenience.

CITY OF PORTLAND  
HEALTH DEPARTMENT  
HOUSING DIVISION



Loc. 213 CORNER 50 STREET  
Loc. #1 S 12 1626  
Bldg # Fire # Elec # Other  
Issued June 8, 1960  
Expires July 8, 1960

Mr. Martin Schwartz  
130 12th Street  
Portland, Maine

Dear Sir:

On June 4, 1960 an examination was made of the premises located at 130 12th Street, Portland, Maine. Non-compliance with the ordinances relating to housing conditions was found as detailed below. In accordance with the provisions of the above ordinance, you are hereby ordered to correct these defects according to specifications within the time limits allowed. Failure to comply with this notice will necessitate legal action. Some repairs or improvements required will necessitate permits which are to be obtained from the Building Inspector, Health, Fire or other City Departments. These must be obtained before the work is started. If any additional information is desired, visit or telephone the Housing Supervisor at this Office, Spruce 4-8021, extension 226. Kindly notify this office as soon as all corrections have been completed.

Very truly yours,  
Douglas H. Brown, M.D.  
Health Director

By \_\_\_\_\_  
Housing Supervisor

### VIOLATIONS & SPECIFICATIONS

# Responsibility of Owner or Agent    \*\* Responsibility of Occupant

- | NO. | VIOLATION  | RESP. |
|-----|--|-------|
| 1.  | Repair and put in good order all dilapidated and hazardous parts of the structure as follows:  |       |
| 1.  | Seal up the loose joints on the rear wall of the structure.  |       |
| 2.  | Repair or replace the broken and deteriorated cement window sills.   |       |
| 3.  | Putty the loose window panes, tighten the loose window sashes in the kitchen, parlor, and bedrooms of the 2nd floor right apt., in the kitchen, parlor, and bedroom of the 2nd floor left apt., in the kitchen, dining room, parlor and bedroom of the 3rd floor right apt., in the kitchen, living room, rear bedroom, and front bedroom of the 3rd floor left apt., in the kitchen, sitting room, and front bedroom of the 4th floor right apt., and in the kitchen, living room, and front bedroom of the 4th floor left apt. |       |
| 4.  | Determine the reason and remedy the condition which now causes the structure to show signs of settling.  |       |
| 5.  | Repair or replace the deteriorated metal covering on the rear walls of the structure.  |       |
| 6.  | Repair or replace the broken boards on the ceiling stairs.   |       |
| 7.  | Repair or replace the cracked, loose, or missing plaster on the ceiling of the kitchen, parlor, and bedroom of the 2nd floor right apt., in the kitchen and parlor of the 2nd floor left apt., in the sitting room and parlor of the 3rd floor right apt., and in the kitchen of the 4th floor right apt.  |       |
| 8.  | Determine the reason and remedy the condition which now causes the ceiling to sag or buckle in the kitchen of the 2nd floor left apt., and in the parlor of the 3rd floor right apt.   |       |
| 9.  | Determine the reason and remedy the condition which now causes the doors to swing in the kitchen, and bedroom of the 2nd floor right apt., in the kitchen and bedroom of the 3rd floor right apt., and in the kitchen, sitting room, and bedroom of the 4th floor right apt.   |       |
| 10. | Determine the reason and remedy the condition which now causes the floors to pitch in the 2nd floor right apt.   |       |
| 11. | Repair or replace the cracked, loose, or missing plaster on the walls under the kitchen sink of the 2nd floor left apt., and in the living room of the 3rd floor right apt.  |       |

(577)

ELECTRICAL INSPECTION:  
Inspectors have reviewed all defective electric wiring and electrical equipment throughout the structure.

- a. Install convenience outlets where there is a dangerous excessive use of extension cords throughout the structure. Particular attention is directed to the kitchen, parlor, and bedroom of the 1st floor right apt., in the kitchen and bedroom of the 2nd floor left apt., in the bedroom of the 2nd floor right apt., in the rear balcony, and front balcony of the 3rd floor left apt., and in the living room and middle bedroom of the 4th floor left apt.
- b. Repair or replace the defective fixtures in the bedroom of the 1st floor right apt., in the dining room of the 2nd floor right apt., and in the parlor of the 4th floor right apt.
- c. Our inspection reveals that the wiring is defective in the parlor of the 4th floor right apt. and should be thoroughly checked by a competent licensed electrician.

PLUMBING:  
Inspectors have reviewed all defective plumbing and plumbing fixtures throughout the structure.

- a. Repair or replace the defective hard connection from the pipe to the trap under the kitchen sink in the 1st floor right apt.

The above mentioned conditions are in violation of the City Ordinance, MINIMUM STANDARD FOR STRUCTURES, and SUBJECT TO ORDER, and must be corrected on or before July 8, 1966.



## APPLICATION FOR PERMIT

Class of Building or Type of Structure 2nd class  
Portland, Maine, Oct. 8, 1957

01365

OCT 10 1957

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect ~~alter repair demolish~~ install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 247 Congress St. Within Fire Limits?            Dist. No. 1  
Owner's name and address Maurice Greenberg, 130 Pitt St. Telephone             
Lessee's name and address D'Alonzo, James, 247 Congress St. Telephone             
Contractor's name and address A.F. Briggs, Co. 369 Forest Ave. Telephone 4-2689  
Architect            Specifications            Plans            No. of sheets             
Proposed use of building Store No. families             
Last use            No. families             
Material brick No. stories 4 Heat            Style of roof            Roofing             
Other building on same lot            Fee \$ 2.00  
Estimated cost \$           

### General Description of New Work

To install refrigeration equipment.

Compressors to be located on first floor as per plan.—Freon F-12

sent to Fire Dept. 10/18/57  
Rec'd from Fire Dept. 10/18/57

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** A.F. Briggs

### Details of New Work

Is any plumbing involved in this work?            Is any electrical work involved in this work?             
Is connection to be made to public sewer?            If not, what is proposed for sewage?             
Has septic tank notice been sent?            Form notice sent?             
Height average grade to top of plate            Height average grade to highest point of roof             
Size, front            depth            No. stories            solid or filled land?            earth or rock?             
Material of foundation            Thickness, top            bottom            cellar             
Material of underpinning            Height            Thickness             
Kind of roof            Rise per foot            Roof covering             
No. of chimneys            Material of chimneys            of lining            Kind of heat            fuel             
Framing Lumber—Kind            Dressed or full size?            Corner posts            Sills             
Size Girder            Columns under girders            Size            Max. on centers             
Kind and thickness of outside sheathing of exterior walls?             
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor           , 2nd           , 3rd           , roof             
On centers: 1st floor           , 2nd           , 3rd           , roof             
Maximum span: 1st floor           , 2nd           , 3rd           , height?             
If one story building with masonry walls, thickness of walls?           

### If a Garage

No. cars now accommodated on same lot           , to be accommodated            number commercial cars to be accommodated             
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?           

### Miscellaneous

Will work require disturbing of any tree on a public street?             
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed?           

D'Alonzo  
A.F. Briggs Co.

APPROVED:

Carl F. Johnson  
CHIEF OF FIRE DEPT.

INSPECTION COPY

Signature of owner by: A.F. Briggs

F.M.

NOTES

Permit No. 57/1565  
 Location 247 Lincoln St  
 Owner James Williams  
 Date of permit 10/10/67  
 Notif. closing-in  
 Inspn. closing-in  
 Final Notif.  
 Final Inspn.  
 Cert. of Occupancy issued  
 Staking Out Notice  
 Form Check Notice

*[This section contains a large 'X' mark drawn across the notes area.]*

*[This section contains faint, illegible text and lines, likely bleed-through from the reverse side of the page.]*





(B) LIMITED BUSINESS ZONE

APPLICATION FOR PERMIT TO ERECT  
SIGN OVER PUBLIC SIDEWALK OR STREET

PERMIT ISSUED  
01531

SEP 9 1955

CITY OF PORTLAND

Portland, Maine, Sept. 6, 1955

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 247 Congress St. Within Fire Limits? yes Dist. No. \_\_\_\_\_  
Owner of building to which sign is to be attached Morris Greenberg  
Name and address of owner of sign G & P Market, 247 Congress St.  
Contractor's name and address United Neon Display, 74 Elm St. Telephone W-0695  
When does contractor's bond expire? Dec. 31, 1955

Information Concerning Building

No. stories 4 Material of wall to which sign is to be attached brick CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED

Details of Sign and Connections

Building owner's consent and agreement filed with application? yes

Electric? yes Vertical dimension after erection 5' Horizontal 3'

Weight 85 lbs., Will there be any hollow spaces? yes Any rigid frame? yes

Material of frame angle iron No. advertising faces 2 material metal

No. rigid connections 2 Are they fastened directly to frame of sign? yes

No. through bolts none Size \_\_\_\_\_ Location, top or bottom \_\_\_\_\_

No. guys 4 material wire cable Size 5/16"

Minimum clear height above sidewalk or street 11' 3"

Maximum projection into street 3' 6" United Neon Display Fee \$ 2.00


Signature of contractor by: William J. Healy

INSPECTION COPY

9/28

Permit No. 55/1531  
Location 247 Congress St.  
Owner G. & P. Market  
Date of permit 9/9/55  
Sign Contractor United Neenah Display  
Final Inspn. 9/29/55

NOTES  
9/29/55 - Work done - Shop signs  
also made some time  
ago. [Signature]



BI FORM 52

WRITTEN CONSENT AND AGREEMENT RELATING TO A CERTAIN SIGN PROPOSED TO  
BE ERECTED PROJECTING OVER A PUBLIC SIDEWALK FROM THE PREMISES  
AT 247 Congress St. IN PORTLAND, MAINE

Wm. S. Roulley, being the owner of the  
premises at 247 Congress St. in Portland, Maine hereby gives  
consent to the erection of a certain sign owned by The GP Market  
projecting over the public sidewalk from said premises as described in  
application to the Inspector of Buildings of Portland, Maine for a permit  
to cover erection of said sign;

And in consideration of the issuance of said permit  
Wm. S. Roulley, owner of said premises, in event said sign shall  
cease to serve the purpose for which it was erected or shall become dangerous  
and in event the owner of said sign shall fail to remove said sign or make  
it permanently safe in case the sign still serves the purpose for which it  
was erected, hereby agrees for himself or itself, for his heirs, its  
successors, and his or its assigns, to completely remove said sign within  
ten days of notice from said Inspector of Buildings that said sign is in  
such condition and of order from him to remove it.

In Witness whereof the owner of said premises has signed this consent  
and agreement this 3rd day of September 1955

Cathie D. MacKerrow  
Witness

Wm. S. Roulley  
Owner

RECEIVED

SEP 6 1955  
DEPT. OF BLD'G. INSP.  
CITY OF PORTLAND

Each face of plastic contains 10 square feet. Each piece of plastic is marked Plexiglas. Sign bears Underwriters label.

(B) LIMITED BUSINESS ZONE



APPLICATION FOR PERMIT TO ERECT  
SIGN OVER PUBLIC SIDEWALK OR STREET

PERMIT ISSUED  
00652

MAY 21 1954

CITY of PORTLAND

Portland, Maine, May 18, 1954

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 243A Congress St. Within Fire Limits? yes Dist. No. \_\_\_\_\_

Owner of building to which sign is to be attached Morris Greenberg

Name and address of owner of sign Morse Television Co., 243A Congress St.

Contractor's name and address P. C. Roberts, 189 Anthoine St., So. Portland Telephone 2-5390

When does contractor's bond expire? Dec. 31, 1954

Information Concerning Building

No. stories 1 Material of wall to which sign is to be attached brick CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

Details of Sign and Connections

Building owner's consent and agreement filed with application yes

Electric? yes Vertical dimension after erection 2' Horizontal 7'

Weight 95 lbs. Will there be any hollow spaces? yes Any rigid frame? yes

Material of frame angle iron No. advertising faces 2 material plastic\*  
no aluminum

No. rigid connections 2 Are they fastened directly to frame of sign? yes

No. through bolts none Size \_\_\_\_\_ Location, top or bottom \_\_\_\_\_

No. guys 2 material angle iron ~~rod~~ Size 1/2" 1 1/2 x 1/6

Minimum clear height above sidewalk or street over 12'

Maximum projection into street 7' P. C. Roberts Fee \$ 2.00

Signature of contractor by: Philip P. Roberts

INSPECTION COPY



6/15

Permit No. 54/65.2  
Location 243 A Congress St.  
Owner Morse Television Co.  
Date of permit 5/21/54  
Sign Contractor D. C. Roberts  
Final Inspn. 6/15/54

NOTES  
5/21/54 - Shipping  
made P. S. S.  
6/15/54 - Done on Island  
OK - All





May 19, 1954

AP 243A Congress St.-Projecting Sign

|   |   |   |
|---|---|---|
| <sup>c</sup><br>Owner of Sign-Morse Television Co.<br>243A Congress St. | <sup>o</sup><br>Contr.-P. C. Roberts<br>189 Antoine St. So. Fort. | <sup>c</sup><br>Owner of Bldg.-Morris Greenberg<br>102 Exchange St. |
|---|---|---|

Vertical dimension of the sign is only two feet so probably one set of side guys is sufficient. If only one set, the side guy should be at the top so as to work together with the uplift.

Not enough room between windows for cable guys at top so angle should be used on one side at 45 degrees with building wall.

Cable guys at bottom are questionable anyway because they might prevent getting a ladder up to the windows in case of fire.

You would have a much better job at no great expense if you used a stiff-log guy at both top and bottom.

Both sketches returned to be revised clearly and filed again showing what you propose.

WMcD/B

Inspector of Buildings

Enclosure to Contr.--his sketches

WRITTEN CONSENT AND AGREEMENT RELATING TO A CERTAIN SIGN PROPOSED TO  
BE ERECTED PROJECTING OVER A PUBLIC SIDEWALK FROM THE PREMISES  
AT 243A CONGRESS ST. IN PORTLAND, MAINE

MORRIS GREENBERG, being the owner of the  
premises at 243A CONGRESS ST. in Portland, Maine hereby gives  
consent to the erection of a certain sign owned by MORSE RADIO CO.  
projecting over the public sidewalk from said premises as described in  
application to the Inspector of Buildings of Portland, Maine for a permit  
to cover erection of said sign;

And in consideration of the issuance of said permit MORRIS  
GREENBERG, owner of said premises, in event said sign shall  
cease to serve the purpose for which it was erected or shall become dangerous  
and in event the owner of said sign shall fail to remove said sign or make  
it permanently safe in case the sign still serves the purpose for which it  
was erected, hereby agrees for himself or itself, for his heirs, its  
successors, and his or its assigns, to completely remove said sign within  
ten days of notice from said Inspector of Buildings that said sign is in  
such condition and of order from him to remove it.

In Witness whereof the owner of said premises has signed this consent  
and agreement this 14th day of May 1957.

John T. Bush  
Witness

Morris Greenberg  
Owner



# APPLICATION FOR PERMIT

Class of Building or Type of Structure Installation

Portland, Maine, November 30, 1953

RECEIVED  
02243  
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 247 Congress Street Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
Owner's name and address G. & P. Market, 247 Congress St. Telephone \_\_\_\_\_  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address A. F. Briggs Co., 369 Forest Ave. Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans yes Fire Dept. \_\_\_\_\_  
Proposed use of building Stores and apartments No. of sheets \_\_\_\_\_  
Last use \_\_\_\_\_ No. families \_\_\_\_\_  
Material \_\_\_\_\_ No. stories \_\_\_\_\_ Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ No. families \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_ Roofing \_\_\_\_\_  
Estimated cost \$ 2.00x Fee \$ 2.00

## General Description of New Work

To install refrigeration equipment - ~~Freon #12~~ Freon #12 for refrigerant  
Compressor located in basement - Freon #12 for refrigerant

11/30/53  
12/1/53

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** A. F. Briggs Co.

## Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
Has septic tank notice been sent? \_\_\_\_\_ Form notice sent? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

## If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

## Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

A. F. Briggs Co.

Signature of owner

By:

Warren F. Kimball

NOTES

*[This section contains a large 'X' mark drawn across the notes area.]*

Permit No. 53/2243  
Location 247 Congress St.  
Owner 247 Congress St. Corp.  
Date of permit 12/1/53  
Notif. closing-in \_\_\_\_\_  
Inspn. closing-in \_\_\_\_\_  
Final Notif. \_\_\_\_\_  
Final Inspn. 12/1/53  
Cert. of Occupancy Issued \_\_\_\_\_  
Sinking Out Notice \_\_\_\_\_  
Form Check Notice \_\_\_\_\_

*[This section contains faint, mostly illegible text, likely bleed-through from the reverse side of the page.]*





(D) LIMITED BUSINESS AREA

APPLICATION FOR PERMIT TO ERECT  
SIGN OVER PUBLIC SIDEWALK OR STREET

PERMIT ISSUED

OCT 12 1953

CITY of PORTLAND

Portland, Maine, October 12, 1953

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 245-247 Congress St. Within Fire Limits?            Dist. No.           

Owner of building to which sign is to be attached Morris Greenberg, 245 Congress St.

Name and address of owner of sign Minat Films Inc. 247 Congress St.

Contractor's name and address United Neon Display, 74 Elm Street Telephone 2-0695

When does contractor's bond expire? Dec. 31, 1953

Information Concerning Building

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

No. stories 3 Material of wall to which sign is to be attached brick

Details of Sign and Connections

Building owner's consent and agreement filed with application yes

Electric? no Vertical dimension after erection 32" Horizontal 4'

Weight 55 pounds lbs., Will there be any hollow spaces? yes Any rigid frame? yes

Material of frame wood No. advertising faces 2 material masonite

No. rigid connections 2 Are they fastened directly to frame of sign? yes

No. through bolts none Size            Location, top or bottom           

No. guys 4 material cable Size 5/16

Minimum clear height above sidewalk or street 11' 9"

Maximum projection into street 4' 6" Fee \$ 2.00

10.25.01K.12.

INSPECTION COPY

Signature of contractor By:

*Thomas J. Kautz*

United Neon Display



(B) LIMITED BUSINESS ZONE



APPLICATION FOR PERMIT TO ERECT  
SIGN OVER PUBLIC SIDEWALK OR STREET

PERMIT ISSUED  
OCT 12 1953  
CITY of PORTLAND

Portland, Maine, October 12, 1953

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to erect the following described sign extending over a public sidewalk or street in accordance with the Building Code of the City of Portland, and the following specifications:

Location 245-247 Congress St. Within Fire Limits?            Dist. No.           

Owner of building to which sign is to be attached Morris Greenberg, 245 Congress St.

Name and address of owner of sign Minat Films Inc. 247 Congress St.

Contractor's name and address United Neon Display, 74 Elm Street Telephone 2-0675

When does contractor's bond expire? Dec. 31, 1953

Information Concerning Building

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

No. stories 3 Material of wall to which sign is to be attached brick

Details of Sign and Connections

Building owner's consent and agreement filed with application. yes

Electric? no Vertical dimension after erection 32" Horizontal 4'

Weight 55 pounds lbs., Will there be any hollow spaces? yes Any rigid frame? yes

Material of frame wood No. advertising faces 2, material masonite

No. rigid connections 2 Are they fastened directly to frame of sign? yes

No. through bolts none, Size           , Location, top or bottom           

No. guys 4, material cable, Size 5/16

Minimum clear height above sidewalk or street 11' 9"

Maximum projection into street 4' 6" Fee \$ 2.00

10/23/53 O.K. ad.

INSPECTION COPY

Signature of contractor By: Thomas J. Kandy

United Neon Display

10-26

Permit No. 53/1827  
Location 245-247 Congress St.  
Owner Minut Filling, Inc.  
Date of permit 10/12/53  
Sign Contractor United Steamship  
Final Inspn. 11-22-53, etc.

NOTES

10/13/53 Ready for  
inspection. OPH  
10-13-53 Ship was closed in till  
the ship was out till then  
to leave open next time off

BI FORM 52

WRITTEN CONSENT AND AGREEMENT RELATING TO A CERTAIN SIGN PROPOSED TO  
BE ERECTED PROJECTING OVER A PUBLIC SIDEWALK FROM THE PREMISES  
AT 245-247 Congress IN PORTLAND, MAINE


I Morris Furlberg, being the owner of the  
premises at 245-247 Congress in Portland, Maine hereby gives  
consent to the erection of a certain sign owned by Maurice Fildes, Inc  
projecting over the public sidewalk from said premises as described in  
application to the Inspector of Buildings of Portland, Maine for a permit  
to cover erection of said sign;

And in consideration of the issuance of said permit I Morris Furlberg  
\_\_\_\_\_, owner of said premises, in event said sign shall  
cease to serve the purpose for which it was erected or shall become dangerous  
and in event the owner of said sign shall fail to remove said sign or make  
it permanently safe in case the sign still serves the purpose for which it  
was erected, hereby agrees for himself or itself, for his heirs, its  
successors, and his or its assigns, to completely remove said sign within  
ten days of notice from said Inspector of Buildings that said sign is in  
such condition and of order from him to remove it.

In Witness whereof the owner of said premises has signed this consent  
and agreement this 25th day of September 1953.

Mary Valente  
Witness

Morris Furlberg  
Owner





(B) LIMITED BUSINESS ZONE

## APPLICATION FOR PERMIT

Class of Building or Type of Structure September 2, 1952

Portland, Maine,

01421  
SEP 4 1952  
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any submitted herewith and the following specifications:

Location 243 247 Congress Street Within Fire Limits? yes Dist. No. \_\_\_\_\_  
Owner's name and address G. P. Market, 247 Congress Street Telephone \_\_\_\_\_  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address A. F. Briggs Co. 369 Forest Ave. Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Fire Dept. Plans yes No. of sheets \_\_\_\_\_  
Proposed use of building Store No. families \_\_\_\_\_  
Last use Store No. families \_\_\_\_\_  
Material \_\_\_\_\_ No. stories \_\_\_\_\_ Heat \_\_\_\_\_ Style of roof \_\_\_\_\_ Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Estimated cost \$ \_\_\_\_\_ Fee \$ 2.00

## General Description of New Work

To install refrigeration equipment  
(Refrigerant Freon F-12)  
Condensers in basement

9/2/52  
Sent to Fire Dept. 9/4/52  
Rec'd from Fire Dept. 9/4/52  
CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO A. F. Briggs

## Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet. \_\_\_\_\_  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

If a Garage  
No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

CHIEF OF FIRE DEPT.

## Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes  
A. F. Briggs Co.

INSPECTION COPY

Signature of owner

By:

Walter F. Kimball

PH



Permit No. 52/142/

Location

0.52/14.21  
-47 Canineo dk  
-29 b.t

Owner

47 Canada  
K. G. Harber

Date of permit

G. Nader  
9/4/52

Notif. closing-in

Insom. closing in

Final Notice

Fill in the

For Duke, Ohio...

Personal Insurance

NOTES

100-442887-100





103) LIMITED BUSINESS ZONE  
APPLICATION FOR PERMIT  
Class of Building or Type of Structure Brick Building  
Portland, Maine, August 4, 1952

PERMIT ISSUED  
01391  
SEP 2 1952  
CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ alter ~~repair~~ demolish ~~or~~ all the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 243 Congress Street Within Fire Limits? \_\_\_\_\_ Dist. No. \_\_\_\_\_  
Owner's name and address Morris Greenberg, 130 Pitt Street Telephone 4-2741  
108 Exchange St.  
Lessee's name and address \_\_\_\_\_ Telephone \_\_\_\_\_  
Contractor's name and address ~~Maxwell~~ Cecil Currie, 147 Brackett St. Telephone \_\_\_\_\_  
Architect \_\_\_\_\_ Specifications \_\_\_\_\_ Plans yes No. of sheets 2  
Proposed use of building Tenement (4) No. families \_\_\_\_\_  
Last use \_\_\_\_\_ " \_\_\_\_\_ No. families \_\_\_\_\_  
Material \_\_\_\_\_ No. stories 4 Heat \_\_\_\_\_ Style of roof flat Roofing \_\_\_\_\_  
Other buildings on same lot \_\_\_\_\_  
Estimated cost \$ 1,500 Fee \$ 5.00

#### General Description of New Work

To construct new porches and stairs on rear of building as per plan submitted

Permit Issued with Letter

CERTIFICATE OF OCCUPANCY  
REQUIREMENT IS WAIVED

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Cecil Currie

#### Details of New Work

Is any plumbing involved in this work? \_\_\_\_\_ Is any electrical work involved in this work? \_\_\_\_\_  
Is connection to be made to public sewer? \_\_\_\_\_ If not, what is proposed for sewage? \_\_\_\_\_  
Height average grade to top of plate \_\_\_\_\_ Height average grade to highest point of roof \_\_\_\_\_  
Size, front \_\_\_\_\_ depth \_\_\_\_\_ No. stories \_\_\_\_\_ solid or filled land? \_\_\_\_\_ earth or rock? \_\_\_\_\_  
Material of foundation \_\_\_\_\_ Thickness, top \_\_\_\_\_ bottom \_\_\_\_\_ cellar \_\_\_\_\_  
Material of underpinning \_\_\_\_\_ Height \_\_\_\_\_ Thickness \_\_\_\_\_  
Kind of roof \_\_\_\_\_ Rise per foot \_\_\_\_\_ Roof covering \_\_\_\_\_  
No. of chimneys \_\_\_\_\_ Material of chimneys \_\_\_\_\_ of lining \_\_\_\_\_ Kind of heat \_\_\_\_\_ fuel \_\_\_\_\_  
Framing lumber—Kind \_\_\_\_\_ Dressed or full size? \_\_\_\_\_  
Corner posts \_\_\_\_\_ Sills \_\_\_\_\_ Girt or ledger board? \_\_\_\_\_ Size \_\_\_\_\_  
Girders \_\_\_\_\_ Size \_\_\_\_\_ Columns under girders \_\_\_\_\_ Size \_\_\_\_\_ Max. on centers \_\_\_\_\_  
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.  
Joists and rafters: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
On centers: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_  
Maximum span: 1st floor \_\_\_\_\_, 2nd \_\_\_\_\_, 3rd \_\_\_\_\_, roof \_\_\_\_\_

If one story building with masonry walls, thickness of walls? \_\_\_\_\_ height? \_\_\_\_\_

#### If a Garage

No. cars now accommodated on same lot \_\_\_\_\_, to be accommodated \_\_\_\_\_ number commercial cars to be accommodated \_\_\_\_\_  
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? \_\_\_\_\_

APPROVED:

with letter by AGS

#### Miscellaneous

Will work require disturbing of any tree on a public street? no  
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Morris Greenberg

~~owner~~

Signature of owner By:

Lindsay Rose

INSPECTION COPY

NOTES

9-12-52. Not started. ~~He~~  
 9-23-52. Same. ~~He~~  
 10-21-52. " Mr. Grumbine said  
 Mr. Quinn plans to start this  
 month. After the first of Nov. ~~He~~  
 11-19-52. Not started. ~~He~~  
 12-8-52. Work started although no  
 one here at time of inspection.  
 Saw tables in and saw new furniture  
 up. Some material left. ~~He~~

1-7-53. No change since above  
 inspection. Called Mr. Grumbine  
 and told him please not to  
 be used in its present condition  
 will send notices to that effect.

He will call Mr. Curran and see  
 if construction can not be  
 resumed without delay. ~~He~~

1-13-53. Some work has been  
 done. Looks as though  
 remodeling, rather than  
 rebuilding, new front  
 practically completed. ~~He~~

1-15-53. Went over with  
 Sept. 2nd with Mr. Curran.  
 Work is progressing. ~~He~~

1-26-53. Work progressing, and  
 members called for 4x6 & 2x4  
 saw for immediate use and will  
 if possible cut out 2nd floor  
 parts. Floor plan for 2nd floor  
 to be made and 2nd floor  
 structure made good for  
 building. ~~He~~

2-2-53. Work completed.  
 Painting and bottom concrete  
 steps to be done this spring.


Permit No. 521391  
 Location 243 Congress St.  
 Owner Morris Rosenberg  
 Date of permit 9/2/52  
 Notif. closing-in  
 Inspn. closing-in  
 Final Notif. 2-2-53.  
 Final Inspn. 2-2-53.  
 Cert. of Occupancy issued  
 See Comp. C-52-61

LAW OFFICES  
MORRIS GREENBERG  
EXCHANGE BUILDING  
DIAL 1-2741

102 EXCHANGE STREET  
PORTLAND, MAINE

*To inspect to note  
11/11/52*  
November 10, 1952

Donald Currie  
1695 Broadway  
South Portland, Maine



Dear Donald:

The City is getting after us again in regard to the work to be done at 243-247 Congress Street. I would appreciate if you would get in touch with Mr. MacDonald and assure him that you are going to take care of this work as soon as possible.

Very truly yours,

*Morris Greenberg*  
Morris Greenberg

MG:mv

cc

AP 243 Congress Street

September 2, 1952

Mr. Cecil Currie  
147 Brackett Street  
Mr. Morris Greenberg  
130 Pitt Street

Copies to: Dr. Lindsay Lord  
Aeronacongin Road  
Falmouth Foreside, Maine

Oliver Y. Sanborn  
Chief of the Fire Department

Gentlemen:

Building permit for rebuilding of the existing piazza on the rear of the building at 243 Congress Street is issued herewith based on the plans as revised. Since some of the details of construction shown on the plans are considerably different from those usually used in building such a structure, it is important that, if any departures are to be made from the construction shown thereon, approval be secured from this department before the work on any such changed construction is started. The permit is issued herewith to Mr. Currie subject to the conditions listed below. If for any reason you are unwilling or unable to abide by these conditions or if you do not understand what is meant, no work is to be started and the permit is to be returned to this office for adjustment. Conditions under which the permit is issued are as follows:

1. The 2x10 members along the outside edge of the piazza at the third and fourth floor levels are to be "let into" the 6x6 posts for the full thickness of those members. Likewise the 4x10 at the same locations in the framing at the second story level is to be "let into" the posts for at least half of its thickness. Incidentally, this 4x10 is required to be all one piece in cross section, not made up of two pieces of 2x10. Splices in these 4x10 and 2x10 members are to occur only at the posts and not between them as indicated in one paragraph of the specifications noted on the plans.
2. As indicated on the plans the entire new structure is to be given two coats of paint suitable for exterior work.
3. Inasmuch as the existing piazza has stairways in it which serve as a second means of egress from the upper stories of the building and the new one is also to have a stairway to serve the same purpose, the work of re-construction of the piazza will need to be planned so that an emergency means of egress will be maintained for the tenants of the building at all times, making sure that at the close of work each day some way is left for them to reach the ground should an emergency occur during the night.

Very truly yours,

Warren McDonald  
Inspector of Buildings

AJS/B



72+  
with: 1/6  
AP 243 Congress Street

August 14, 1952

Dr. Lindsay Lord  
Oneroscoggin Road  
Falmouth Foreside, Maine

c.c. Mr. Morris Greenberg  
130 Pitt Street

c.c. Mr. Cecil Currie  
147 Brackett Street

Dear Dr. Lord:-

A check of the plans filed with the application for a permit to rebuild the existing three story piazza on the rear of the building at 243 Congress Street raises a number of questions as to compliance with Building Code requirements. These are as follows:-

- ✓ 1. Concrete piers are not shown extending at least 6 in. above grade as required.
- ✓ 2. Any splices in corner posts are required to be not less than 18 in. long and should be located just above one of the floor levels.
- ✓ 3. The supporting members around the edge of the lower platform are required to be no less than 4 in. in least dimension instead of 2 in. as indicated. Method of fastening them to the posts should be indicated. The 2x10 supporting members at the other floor levels are satisfactory.
- ✓ 4. The use of 2 in. planking for the platform decking is rather unusual for a structure of this kind. Although this planking, on the span indicated figures out all right, the construction indicated would not provide as rigid a structure as the conventional type of framing with 2 in. floor timbers and ordinary flooring. Therefore, if the framing as shown is to be used, it will be necessary to provide knee braces for the posts in each direction at each floor level. In such a case size and angle of braces to be used and method of fastening should be shown.
- ✓ 5. The pitch shown for the stairs is too steep. Maximum allowable height of risers is 8 1/2 inches and minimum allowable width of treads is 9 in., these dimensions to be measured on the stair points.
- ✓ 6. A foundation extending at least four feet below grade is required for the bottom of the lower run of stairs.
- ✓ 7. The handrails are required to extend for the full length of the stairs. Due to the length of the stairs, it is likely that one or more intermediate posts will be needed for the handrails.
- ✓ 8. The method of fastening the intermediate posts of the railings at each platform level to the floor framing appears questionable in that outward pressure on the railing would tend to loosen the fastenings of these posts unless bolts extending through the supporting members were used for fastenings.
- ✓ 9. Since none of the new posts are to be placed in the same location as the existing ones, the splices in the existing 2x6 plate supporting the outer ends of the rafters, which now occur on the existing posts, will come between supports. Therefore it will be necessary to replace the existing plate, and no less than a 4x6 on edge should be used for this purpose.



August 14, 1952

Dr. Lindsay Lord - - - - - 2

10. There is no indication as to the framing around the stairwells at each floor level for support of the planking. What is to be provided across the opening where the light shaft is located at the two upper platform levels for support of the planking?

Information by way of revised plans to indicate how all of the above questions are to be cared for in compliance with Building Code requirements will need to be furnished before a permit for re-building of the piazza can be issued.

Very truly yours,

Warren McDonald  
Inspector of Buildings

AJS/G



FILL IN AND SIGN WITH INK  
APPLICATION FOR PERMIT FOR  
HEATING, COOKING OR POWER EQUIPMENT

Portland, Maine, November 9, 1946

PERMIT NO. 02544  
OCT 19 1946

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the Laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 243 Congress Street Use of Building Stores & Apts. No. Stories 4 ☒ Building Existing "☐  
Name and address of owner of appliance Morris Greenberg, 102 Exchange St.  
Installer's name and address Wilbur F. Blake, Inc., 9 Forest St. Telephone 2-5968

General Description of Work

To install steam heating system in place of steam heat from central heating boiler

IF HEATER, OR POWER BOILER

Location of appliance or source of heat basement Type of floor beneath appliance concrete  
If wood, how protected? Kind of fuel oil  
Minimum distance to wood or combustible material, from top of appliance or casing top of furnace 3'  
From top of smoke pipe 3' From front of appliance Over 4' From sides or back of appliance Over 3'  
Size of chimney flue 20x20 Other connections to same flue none  
If gas fired, how vented? Rated maximum demand per hour

IF OIL BURNER

Name and type of burner Labelled by underwriters' laboratories?  
Will operator be always in attendance? Does oil supply line feed from top or bottom of tank?  
Type of floor beneath burner  
Location of oil storage Number and capacity of tanks  
If two 275-gallon tanks, will three-way valve be provided?  
Will all tanks be more than five feet from any flame? How many tanks fire proofed?

IF COOKING APPLIANCE

Location of appliance Kind of fuel Type of floor beneath appliance  
If wood, how protected?  
Minimum distance to wood or combustible material from top of appliance  
From front of appliance From sides and back From top of smokepipe  
Size of chimney flue Other connections to same flue  
Is hood to be provided? If so, how vented?  
If gas fired, how vented? Rated maximum demand per hour

MISCELLANEOUS EQUIPMENT OR SPECIAL INFORMATION

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc., 50 cents additional for each additional heater, etc., in same building at same time.)

APPROVED:  
OK 11-13-46 WFB

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

Wilbur F. Blake, Inc.

INSPECTION COPY

Signature of Installer By:

Wilbur F. Blake

Permit No. 46/2541 <sup>615-44</sup>  
Location 243 Congress St.  
Owner Monia Greenberg  
Date of permit 12/23/1960  
Approved 12/27/1960

NOTES

*E 88*