
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager Boyd Street Partners Llc		Inspector Jeanie Bourke	Inspection Date 6/15/2009
Location 47 BOYD ST	CBL 022 I003001	Status	Inspection Type Housing-CDBG housing inspectio

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-116.(c)	Interior	1	47a	Living Room	
Violation:	Egress Obstructions				
Notes:	Remove excessive storage boxes and miscellaneous items blocking the apartment door.				
2) 6-113.(d)	Interior	1	47a	Living Room	
Violation:	Extension cords.				
Notes:	Remove extension cord are passing through the doorway in the middle room				
3) 6-109.(a)	Interior	1	47a	Through Out	
Violation:	Maintenance of assigned areas				
Notes:	Reduction or removal of excessive amounts of storage boxes stacked throughout the apartment in order to maintain safe passage and exiting.				

Comments: Notice sent to tenant in DU 47a for correction