Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

June 23, 2014

BAILEY LLOYD H JR 429 SLIGO RD YARMOUTH, ME 04096

CBL: 022 L017001

Certified Mail 7013 1090 0002 1737 7233

Located at: 145 CUMBERLAND AVE

Dear Mr. Bailey,

SECOND NOTICE OF VIOLATION

An evaluation of the above-referenced property on 06/23/2014 revealed that the structure remains non-compliant with the Housing Code of the City of Portland.

Attached is a list of the violations.

This is a **SECOND** notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected. A re-inspection will occur on **08/07/2014**, at which time compliance will be required.

Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code and in Title 30-A M.R.S.A ss 4452.

Please feel free to contact me is you wish to discuss this matter further or have any questions.

Sincerely.

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager BAILEY LLOYD H JR		Inspector	Inspection Date
		Chuck Fagone	4/25/2014
Location	CBL	Status	Inspection Type
145 CUMBERLAND AVE	022 L017001	Re-Inspect 45 Days	Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
------	---------	-------	----------	------	-----------------

1) 6-108. (a)

Exterior

Side Landing

Violation:

FOUNDATIONS CELLARS, EXTERIOR WALLS, ROOFS

Notes:

Every foundation, basement, cellar, exterior wall, and roof shall be substantially weather tight, watertight, and vermin proof; shall be structurally sound and in good repair; and shall be safe for the intended use as well as capable of supporting whatever load normal use may cause to be placed thereon. Every exterior wall or portion thereof shall be painted or stained. Insulation shall be installed and maintained so as not to present a health or safety hazard to occupants. Water from roofs shall be so drained and conveyed therefrom as not to cause repeatedly wet floors, walls, or ceilings, or hazard to adjacent buildings or the occupants thereof.

Comments:

Per inspection, retaining wall on left side of property is compromised and is a safety hazard.

CERTIFIED MAIL...

Strengthening a Remarkable City, Building a Community for Life
PORTLAND
MAINE

Inspection Services Division 389 Congress Street, RM 315 Portland, Maine 04101-3509



7013 1090 0002 1737 7233





04096

U.S. POSTAGE PAID PORTLAND.ME 04101 JUN 23:14 AMOUNT

1000

•

\$6.49 a 00030643-08

NL. 6/24/14 EC

7/3

NIXIE

915 DE 1009

0007/14/14

RETURN TO SENDER
UNCLAIMED
UNABLE TO FORWARD

04096353797 @6699

: 04101357190 *3084-01831-23-43

