

# Record of Completion

Presented To

191 Marginal Way  
191 Marginal Way  
Portland ME 04101  
USA

This site has been inspected and tested in compliance with applicable standards.

Completed  
Monday, February 25, 2019

Test Session: 02/25/19

System Additions

ACCEPTED BY

191 Marginal Way  
191 Marginal Way  
Portland ME 04101  
USA

TESTED BY

Norris Inc. P Penttila  
Norris Inc  
2257 Broadway  
South Portland ME 4106  
USA

Norris Inc



Advancing security, life safety and communications.

# Certification Information


## Certification

The equipment specified herein was inspected and tested according to the NFPA 72 standard for fire alarm and signaling systems, with the inspection completed on Monday, February 25, 2019

INSTALLED BY

2/25/2019  
Sea Bee E C  
Installer

TESTED BY

  
2/25/2019  
Norris Inc. P Penttila  
Technician

ACCEPTED BY

2/25/2019  
Building Representative

ACCEPTED BY

2/25/2019  
AHJ

# Testing Details

## Fire Control Panel

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
FCPS		Below FACP	Manual	2/25/2019 10:48 AM
		Manufacturer	Notifier	
		Model	24/s8	
		Serial Number		
		Visual Inspection	False	
		Functional Inspection	False	
		Location	sprinkler room	
		Area Served	aetna office	

## Power Supplies

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Battery - Sealed Lead-acid		fcps	Manual	2/25/2019 10:48 AM
		Model	12/7	
		Serial Number		
		Visual Inspection	False	
		Functional Inspection	False	
		Nominal Voltage	0	
		Amp Hours	0	
		Stand By Hours	0	
		Alarm Minutes	0	
		Charger Voltage	0	
		Load Voltage	0	

## Initiating Device

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Manual Pull Station	M1	aetna side exit	Manual	2/25/2019 10:47 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Alarm Verification Participation	False	
Manual Pull Station	M2	aetna employee entry	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Alarm Verification Participation	False	
Manual Pull Station	M3	aetna main entry	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Alarm Verification Participation	False	

## Alarm Notification Appliance

Norris Inc

Passed

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
Audible And Visible		main entry reception	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Visible		main entry office 1	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Visible		main entry office 2	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Audible And Visible		corr near reception	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		corr near reception	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Visible		office on west side	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Audible And Visible		west office space	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		Corr near copier room	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		copier room	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		north east office space	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	

EQUIPMENT TYPE	ADDRESS	DESCRIPTION	METHOD	DATE/TIME
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		center east office space	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Audible And Visible		corr near bathrooms	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	
Visible		Women's restroom	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Visible		men's restroom	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Visible		it closet	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Visible		storage next to it	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Visible		office before break room	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
Audible And Visible		break room	Manual	2/25/2019 10:48 AM
		Visual Inspection	False	
		Functional Inspection	False	
		Candela Rating	0	
		Ambient Sound Pressure	0	
		Active Sound Pressure	0	

## Device/Equipment Details

### Fire Control Panel

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
FCPS	Below FACP	Notifier	24/s8		2/25/2019

### Power Supplies

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Battery - Sealed Lead-acid	fcps		12/7		2/25/2019

### Initiating Device

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Manual Pull Station					
M1	aetna side exit				2/25/2019
M2	aetna employee entry				2/25/2019
M3	aetna main entry				2/25/2019

### Alarm Notification Appliance

ADDRESS	DESCRIPTION	Manufacturer	Model	SERIAL	INSTALL DATE
Audible And Visible					
	main entry reception				2/25/2019
	corr near reception				2/25/2019
	corr near reception				2/25/2019
	west office space				2/25/2019
	Corr near copier room				2/25/2019
	copier room				2/25/2019
	north east office space				2/25/2019
	center east office space				2/25/2019
	corr near bathrooms				2/25/2019
	break room				2/25/2019
Visible					
	main entry office 1				2/25/2019
	main entry office 2				2/25/2019
	office on west side				2/25/2019
	Women's restroom				2/25/2019
	men's restroom				2/25/2019
	it closet				2/25/2019
	storage next to it				2/25/2019
	office before break room				2/25/2019

# Supplementary Information