CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

	wner/Manag			Inspector			Inspection Date 6/10/2010	
MARDIGAN EDWARD L Locatation CBL				Tammy Munson Status			Inspection Type	
190 OXFORD ST 026 C004001			Re-Inspect 21 days			Complaint-Inspection		
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date
1)	6-108.(a) Violation: Notes:	Exterior Various locations Foundations cellars, exterior walls, roofs (c) Exterior windows, doors and skylights Every window or door, including basement or cellar door at hatchway, and skylight shall be substantially weathertight, watertight, and vermin proof and shall be kept in sound working condition and good repair. Every exterior window shall include storm sash with screens or an alternative equally effective for hear retention and ventilation purposes, all in operable condition						
2)	NFPA 101 a Violation: Notes:							
3)	NFPA 101 a Violation: Notes:							
4)	NFPA 101 a Violation: Notes:							
5)	NFPA 101 a Violation: Notes:	Fire Inspecti	ons Violations nall be self- closing]				
6)	NFPA 101 a Violation: Notes:	lation: Fire Inspections Violations					Stairways	
7)	NFPA 101 a Violation: Notes:	on: Fire Inspections Violations						
8)	NFPA 101 a Violation: Notes:							
9)	NFPA 101 a Violation: Notes:	Fire Inspecti	ons Violations as water heaters i	n basemen	t Boiler pro	otection requi	Basemen red	t

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
MARDIGAN EDWARD L		Tammy Munson	6/10/2010
Locatation	CBL	Status	Inspection Type
190 OXFORD ST	026 C004001	Re-Inspect 21 days	Complaint-Inspection

Comments: