

267-269 CUMBERLAND AVENUE

SHAW-WALKER

File 1004 # 9208 - 11/1/44 - 1/2/45 - 1/2/46 - 1/2/47 - 1/2/48 - 1/2/49 - 1/2/50 - 1/2/51 - 1/2/52 - 1/2/53 - 1/2/54 - 1/2/55 - 1/2/56 - 1/2/57 - 1/2/58 - 1/2/59 - 1/2/60 - 1/2/61 - 1/2/62 - 1/2/63 - 1/2/64 - 1/2/65 - 1/2/66 - 1/2/67 - 1/2/68 - 1/2/69 - 1/2/70 - 1/2/71 - 1/2/72 - 1/2/73 - 1/2/74 - 1/2/75 - 1/2/76 - 1/2/77 - 1/2/78 - 1/2/79 - 1/2/80 - 1/2/81 - 1/2/82 - 1/2/83 - 1/2/84 - 1/2/85 - 1/2/86 - 1/2/87 - 1/2/88 - 1/2/89 - 1/2/90 - 1/2/91 - 1/2/92 - 1/2/93 - 1/2/94 - 1/2/95 - 1/2/96 - 1/2/97 - 1/2/98 - 1/2/99 - 1/2/100

(COPY)



CITY OF PORTLAND, MAINE
Department of Building Inspection

Certificate of Occupancy

LOCATION #267 Cumberland Ave.

Issued to Emery J. Girouard

Date of Issue April 26, 1967

42 Lowell St. Westbrook Me.

This is to certify that the building, premises, or part thereof, at the above location, built ~~altered~~
—changed as to use under Building Permit No. _____, has had final inspection, has been found to conform
substantially to requirements of Zoning Ordinance and Building Code of the City, and is hereby approved for
occupancy or use, limited or otherwise, as indicated below.

PORTION OF BUILDING OR PREMISES

Area, as shown on plot plan.

APPROVED OCCUPANCY

Off-street parking for
thirteen passenger cars.

Limiting Conditions:

This certificate supersedes
certificate issued

Approved:

Nelson F. Cartwright

(Date)

Inspector

Herald E. Mayberry

Inspector of Buildings

CS 147

Notice: This certificate identifies the use of building or premises, and ought to be transferred from
owner to owner when property changes hands. Copy will be furnished to owner or lessee for one dollar.

AP - 267 Cumberland Ave.

June 28, 1965

Mr. Emery J. Girouard
42 Lowell St.
Westbrook, Maine

Dear Mr. Girouard:

Authorization is hereby given for construction of an off-street parking lot having frontage on Cumberland Avenue on the basis of the plot plan filed with application for certificate of occupancy, but subject to compliance with Zoning Ordinance restrictions as follows:

1. Bumper guards at least 20 inches high are to be provided along Cumberland Avenue lot line or a continuous guard curb, rectangular in cross section, at least six inches in height and permanently anchored, shall be provided and maintain least five feet from the street line.
2. Where the parking lot abuts residential dwellings on the sides and rear a chain link, picket or sapling fence, not less than 48 inches in height, shall be provided and maintained between such off-street parking and that part of the lot line involved.

Very truly yours,

A. Allan Sculo
Inspector

AAS/h

APPLICATION FOR CERTIFICATE OF OCCUPANCY FOR USE OF PREMISES

Portland, Maine May 11, 1965

Location 237 Cumberland Ave. Zone S-2 Business St.

To the INSPECTOR OF BUILDINGS, Portland, Maine

The undersigned hereby applies for a certificate of occupancy to allow the use of the above named premises for: PER 12 Lot

as set forth on the attached site plan (made by Emery J. Girouard whose address is 42 Lowell St. Westbrook Me. to show compliance with the Zoning

Ordinance according to the intended use and the zone in which the property is located; and in accordance with the following pertinent information:

Owner (name, address and phone number) Emery J. Girouard, 42 Lowell St. Westbrook Me.

Lessee (name, address and phone number) " "

Is proposed use to be accessory to a building or other use on this lot? no
If so, what is use of building or other use _____

If off-street parking is sought, what is proposed maximum number of vehicles to be parked--passenger cars? 13, commercial vehicles? none

Have you secured on the site plan the written approval of existing and proposed entrances to and exits from the premises for vehicles over public sidewalks by the Traffic Engineer (Dept. of Pub. Works)? _____
And, if access to the premises is available from more than one street, have you secured similar approval by the Planning Board? _____?

Have you shown on the site plan the true location of all trees on the public street along the frontage of the premises (both streets if a corner lot)? _____

Do you propose to remove or disturb any tree on a public street? no
If so, have you secured on the site plan the written approval of the Director of Parks and Recreation? _____

Signature of Owner Emery J. Girouard

By _____ (duly authorized thereto)

\$2.00 paid 5-11-65

THIS IS NOT A CERTIFICATE OF OCCUPANCY

To: Emery J. Girouard
42 Lowell St.
Westbrook Me.

COMMENCING the above proposed use of the premises would be IN VIOLATION of the Zoning Ordinance unless a Certificate of Occupancy is first procured from the Department of Building Inspection.

However, improvement of the premises according to the site plan and the above application may now proceed without further authorization, but subject to the conditions indicated below--notice of readiness for final inspection to be given to this department when the premises have been placed in compliance with the requirements: - See letter

DATE June 25, 1965

Albert G. Sears
Inspector of Buildings

INSPECTION COPY

4-26-67 Completed AD



B2 BUSINESS ZONE

APPLICATION FOR PERMIT

Third Class

Class of Building or Type of Structure

Portland, Maine,

May 11, 1965

PERMIT ISSUED

MAY 20 1965

CITY OF PORTLAND

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter repair demolish install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 257 Cumberland Ave. Within Fire Limits? Dist. No. Telephone 854-5277
Owner's name and address Emery J. Girouard, 42 Lowell St. Westbrook Me. Telephone
Lessee's name and address
Contractor's name and address not let Telephone
Architect Specification Plans No. of sheets
Proposed use of building Apartment House No. families
Last use No. families 4
Material frame No. stories 2 Heat Style of roof Roofing
Other buildings on same lot
Estimated cost \$ Fee \$ 5.00

General Description of New Work

To demolish existing 2-story frame apartment building.

Do you agree to tightly and permanently close all sewers or drains connecting with public or private sewers from this building or structure to be demolished, under the supervision and to the approval of the Dept. of Public Works of the City of Portland? Yes.

Land to be used for parking lot.

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO owner

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing Lumber-Kind Dressed or full size? Corner posts Sills
Size Girder Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

0.11-6, 12/165-916

Emery J Girouard

Emery J. Girouard

CS 301

INSPECTION COPY

Signature of owner

by:

7M

NOTES

7-12-65 Not started (M)
 9-2-65 shut down (M)
 9-23-65 " " (M)
 10-11-65 Down to found.
 10-15-65 " " " " (M)

~~X~~
 See new plan
 for parking (M)

Permit No. 157/664
 Location 267 Linden Blvd
 Owner George J. Lucciaro
 Date of permit 6/28/65
 Notif. closing-in
 Inspn. closing-in
 Final Notif.
 Final Inspn.
 Cert. of Occupancy issued
 Staking Out Notice
 Form Check Notice

1965-7-12

PERMIT NUMBER 9981

PERMIT TO INSTALL PLUMBING

Date Issued: 4/17/61

Address: 267 Cumberland Avenue

PORTLAND PLUMBING INSPECTOR

Installation For: Mr. John Theodorakakos

By: J. P. Welch

Owner of Bldg.: Mr. John Theodorakakos

APPROVED FIRST INSPECTION

Owner's Address: 267 Cumberland Avenue

Date: 5-5-61

Plumber: Portland Gas Light Co. Date: 4/17/61

By: J. P. Welch

PROPOSED INSTALLATIONS		NUMBER	SEE
SINKS			
LAVATORIES			
TOILETS			
BATH TUBS			
SHOWERS			
DRAINS			
HOT WATER TANKS			
TANKLESS WATER HEATERS	3	1	\$ 2.00
GARBAGE GRINDERS			
SEPTIC TANKS			
HOUSE SEWERS			
ROOF LEADERS (conn. to house drain)			

APPROVED FINAL INSPECTION

Date: JOSEPH P. WELCH

- By: JOSEPH P. WELCH
- TYPE OF BUILDING
- COMMERCIAL
 - RESIDENTIAL
 - SINGLE
 - MULTI FAMILY
 - NEW CONSTRUCTION
 - REMODELING

SM 12-53

PORTLAND HEALTH DEPT.

PLUMBING INSPECTION

1 \$ 2.00 Total



CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION
COMPLAINT

Location:
267 Cumberland Ave.

INSPECTION COPY

COMPLAINT NO. 57/21 Date Received 3/26/57

Location 267 Cumberland Ave. Use of Building _____
 Owner's name and address John Theodorakos, 263 Cumberland Ave. Telephone _____
 Tenant's name and address _____ Telephone _____
 Complainant's name and address Fire Department Telephone _____

Description: Defective chimney

NOTES: ~~1957. This is a rear chimney nearest
 the street. It has a low wall. Some bricks are missing from
 the top. Other appear to be missing the full
 on to the top. It is possibly a
 several places. The chimney is
 in poor condition. It is
 to be repaired.~~

~~4/17/57 - Closed by letter - WAD~~

To Building Department

REPORT OF FIRE

Date March 26, 1957

Location 267 Cumberland Ave.

Construction Wood

Height (Stories) 2-1/2

Owner John Karkos


Occupant Tenants

Floor of origin Chimney


Cause Defective chimney

Appx. Damage None

Remarks : Top of chimney should be inspected.



Fire Dept. C. P. Johnson
By G.R.



Reg. Mail
Return Receipt

RHT 5/2/57

April 17, 1957

Cmplt. 267 Cumberland Ave.--Chimney dangerous above the roof
and order relating thereto

Mr. John Theodorakos
263 Cumberland Ave.

Dear Mr. Theodorakos,

An inspector from this office finds that the rear chimney (nearest Chestnut St.) in the building, which you are reported to own or control at 267 Cumberland Ave., is in a dangerous condition at least above the roof, and part or all of it threatened to fall and do damage to persons or property.

As authorized and directed by Section 109 of the Building Code (copy enclosed) you are hereby required to have this dangerous condition permanently corrected before May 2, 1957.

Our inspector reports that some of the bricks are missing from the top of the chimney, and others appear to be ready to fall. The top of the chimney means definitely and evidently the entire top should be taken down until sound masonry is found and then rebuilt.

In this process if the masonry of the chimney is found to be sound above the roof and below, then no permit for the work is required. However, if unsound masonry is found below the surface of the roof, a permit is required and your mason should come and apply for it explaining the work which he intends to do.

Very truly yours,

WHCD/B

Warren McDonald
Inspector of Buildings

Enc: Copy of Section 109 of the Building Code of Portland.

413

FD 3/21/56- AAS

267-269 Cumberland Ave.

August 20, 1956

Mr. John Chendarakos
265 Cumberland Ave.

Dear Mr. Chendarakos:

It is important that you have the small shed in the rear of this property at 267-269 Cumberland Avenue, corner Stone Street completely removed before August 27, 1956, or we shall find it necessary to report to the Corporation Council of the city for whatever action he deems necessary.

While it is quite likely you may not understand what has transpired because of your difficulty with the language, it is hoped that you will get someone to read this letter and explain it to you.

You had the small shed constructed, or did it with your own hands several weeks ago without first securing the required building permit. One of our inspectors found it and told you or someone around the property that all work should be stopped and the matter straightened out as to the permit. Whereupon your wife with a friendly interpreter came to the office. We discussed the matter and found out that the location of the shed is contrary to the Zoning Ordinance, and the conclusion was reached that you would remove the building and care for storage of garbage and waste paper, etc. in some other manner, perhaps in metal cans or the burnable material put in cans and an underground garbage container for the garbage.

I realized this morning that nothing has been done to remove the shed, and that you are probably using it as it was intended, etc.

It should be noted that the shed must be removed and that before the above date notices will be sent.

Very truly yours,

WACD/H

Inspector of Buildings

PERMIT NUMBER 568

Date Issued April 11, 1955

PORTLAND PLUMBING INSPECTOR

By J. P. Welch

APPROVED FIRST INSPECTION

Date April 30-1955

By [Signature]

APPROVED FINAL INSPECTION

Date July 20-55

By [Signature]

- TYPE OF BUILDING
- COMMERCIAL
- RESIDENTIAL
- SINGLE
- MULTI FAMILY
- NEW CONSTRUCTION
- REMODELING

SM 12-53

PORTLAND HEALTH DEPT.

PERMIT TO INSTALL PLUMBING

Address: 267 Cumberland Ave.

Installation For:

Owner of Bldg.: John Kakos

Owner's Address: Same

Plumber: C. Matthews

Date: 4-11-55

NEW	REP'L	PROPOSED INSTALLATIONS	NUMBER	FEE
		SINKS		
		LAVATORIES		
		TOILETS		
		BATH TUBS		
		SHOWERS		
		DRAINS		
1		HOT WATER TANKS		
		TANKLESS WATER HEATERS	3	
		GARBAGE GRINDERS	1	1.00
		SEPTIC TANKS		
		HOUSE SEWERS		
		ROOF LEADERS (conn. to house drain)		

PLUMBING INSPECTION

Total \$1.00

City of Portland, Maine
Board of Appeals
— ZONING —

*Withdrawn
10/14/53
53/89*

October 6, 1953

To the Board of Appeals:

Your appellant, John Theodarkakos, who is the owner of property at 267-269 Cumberland Avenue, respectfully petitions the Board of Appeals of the City of Portland to permit an exception to the regulations of the Zoning Ordinance relating to this property, as provided by Section 18, Paragraph E of said Zoning Ordinance.

Building permit to construct concrete block wall about eight feet high to be supported upon concrete foundation along the rear and two side lot lines of the rear yard of the property at 267-269 Cumberland Avenue is not issuable under the Zoning Ordinance because the wall, though intended largely as a fence or barrier, would be a structure and as such would represent an unlawful encroachment upon the rear yard of the apartment house on this same property.

The facts and conditions which make this exception legally permissible are as follows:
An exception is necessary in this case to grant reasonable use of property and can be granted without substantially departing from the intent and purpose of the Zoning Ordinance.

John Theodarkakos
By *Ernest M. White*
Appellant His Attorney

After public hearing held on the 16th day of October, 1953,
~~the Board of Appeals finds that an exception is~~

APPELLANT GIVEN LEAVE TO WITHDRAW WITHOUT PREJUDICE.

~~It is therefore determined that an exception to the Zoning Ordinance may be permitted in this specific case.~~

Edward J. Colley
CHAIRMAN

BOARD OF APPEALS

DATE: OCTOBER 16, 1953

HEARING ON APPEAL UNDER THE ZONING ORDINANCE OF JOHN THEODARKAKOS
AT 267-269 CUMBERLAND AVENUE

Public hearing on above appeal was held before the BOARD OF APPEALS

<u>Board of Appeals</u>	<u>VOTE</u>		<u>Municipal Officers</u>
EDWARD T. COLLEY	Yes	No	
	()	()	
ROBERT L. GETCHELL	()	()	APPELLANT GIVEN LEAVE TO WITHDRAW
HELEN C. FROST	()	()	WITHOUT PREJUDICE.
WILLIAM H. O'BRIEN	()	()	
BEN. B. WILSON	()	()	
	()	()	
	()	()	
	()	()	
	()	()	

Record of Hearing:

CITY OF PORTLAND, MAINE
BOARD OF APPEALS

October 13, 1953

TO WHOM IT MAY CONCERN:

The Board of Appeals will hold a public hearing in the Council Chamber at City Hall, Portland, Maine on Friday, October 16, 1953 at 10:30 a. m. Eastern Standard Time to hear the appeal of John Theodorakos requesting exception to the Zoning Ordinance to cover construction of a concrete block wall about eight feet high to be supported upon concrete foundation along the rear and two side lot line of the rear yard of the property at 267-269 Cumberland Avenue.

This permit is presently not issuable under the Zoning Ordinance because the wall, though intended largely as a fence or barrier, would be a structure and as such would represent an unlawful encroachment upon the rear yard of the apartment house on this same property.

If you are interest either for or against this appeal, please be present or be represented at this hearing.

Board of Appeals
Edward T. Colley
Chairman

K

cc: Lester F. Wallace - 500 Baxter Boulevard

CITY OF PORTLAND, MAINE
BOARD OF APPEALS

October 23, 1953

Ernest M. White, Esq.
119 Exchange Street
Portland, Maine

Re: Appeal of John Theodorakos
67-269 Cumberland Ave.

Dear Mr. White:

The Board of Appeals will hold a public hearing in
the Council Chamber at City Hall, Portland, Maine on Friday,
October 16, 1953 at 10:30 a. m. Eastern Standard Time to hear
the appeal of John Theodorakos.

Please be present at this hearing in support of this
appeal.

Board of Appeals
Edward T. Colley
Chairman

K

WARREN McDONALD
INSPECTOR OF BUILDINGS

On reply refer
to file # 267-269 Cumberland Ave. Department of Building Inspection
FU

CITY OF PORTLAND, MAINE

October 1, 1953

Mr. John Theodarakos
263 Cumberland Ave.,
Maine State Builders
208 Concord St.

Copy to: Corporation Counsel ✓

Gentlemen:

Building permit intended to authorize construction of a concrete block wall about eight feet high to be supported upon a concrete foundation along the rear and two side lotlines of the rear yard of the property at 267-269 Cumberland Ave., is not issuable under the Zoning Ordinance, because the wall, though intended largely as a fence or barrier, would be a structure and as such would represent an unlawful encroachment upon the rear yard of the apartment house on the same property.

As I have written you about this situation before at some length, it is assumed that you desire to seek an exception from the Zoning Board of Appeals; so, there is enclosed an outline of the appeal procedure.

If you desire to seek such an exception from the Board of Appeals and desire the Board's consideration at the earliest possible date, it would be well for you to file the appeal in the office of Corporation Counsel before the close of business on Friday, October 9.


Very truly yours,

WMcD/B

Warren McDonald
Inspector of Buildings

Enc: Outline of appeal procedure

C
O
P
Y



APPLICATION FOR PERMIT

Class of Building or Type of Structure Structure

Portland, Maine, Sept. 24, 1953
supersedes 9/14/53

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to erect alter or demolish the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 267-269 Cumberland Ave. Within Fire Limits? yes Dist. No.
Owner's name and address John Theodarkakos, 267 Cumberland Ave. Telephone
Lessee's name and address Telephone
Contractor's name and address Maine State Builders, 206 Concord St. Telephone
Architect Specifications Plans no No. of sheets
Proposed use of building No. families
Last use No. families
Material No. stories Heat Style of roof Roofing
Other buildings on same lot
Estimated cost \$ 1,400. Fee \$ 5.00

General Description of New Work

To construct concrete wall 12" inside of lot line as shown on sketch. Wall will be 5' 6" below ground and 18" above ground, to be 16" at the bottom and 12" at the top. To construct concrete block wall 8' above foundation wall of 8" blocks.

Appeal withdrawn 10/16/53
Appeal withdrawn 9/16/53
10/13/53

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. PERMIT TO BE ISSUED TO Maine State Builders

Details of New Work

Is any plumbing involved in this work? Is any electrical work involved in this work?
Is connection to be made to public sewer? If not, what is proposed for sewage?
Has septic tank notice been sent? Form notice sent?
Height average grade to top of plate Height average grade to highest point of roof
Size, front depth No. stories solid or filled land? earth or rock?
Material of foundation Thickness, top bottom cellar
Material of underpinning Height Thickness
Kind of roof Rise per foot Roof covering
No. of chimneys Material of chimneys of lining Kind of heat fuel
Framing lumber—Kind Dressed or full size?
Corner posts Sills Girt or ledger board? Size
Girders Size Columns under girders Size Max. on centers
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor, 2nd, 3rd, roof
On centers: 1st floor, 2nd, 3rd, roof
Maximum span: 1st floor, 2nd, 3rd, roof
If one story building with masonry walls, thickness of walls? height?

If a Garage

No. cars now accommodated on same lot, to be accommodated number commercial cars to be accommodated
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building?

APPROVED:

Miscellaneous

Will work require disturbing of any tree on a public street? no
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observe? yes

John Theodarkakos

Signature of owner by:

Steven Skoulikis

INSPECTION COPY

Permit No. 531

Location 217-269 Cumberland Ave

Owner John D. Stankovic

Date of permit 1/53

Notif. closing-in

Inspn. closing-in

Final Notif.

Final Inspn.

Cert. of Occupancy issued


Staking Out Notice

Form Check Notice

NOTES

Large ruled area for notes, consisting of multiple horizontal lines.

CHESTNUT ST.



STONE ST.

CUMBERLAND

AVE


APPEAL OF JOHN THEODARKAKOS.

AT

265-269 Cumberland Ave

Scale: 1"=50'

10/16/53.



AP 267-269 Cumberland Ave.

November 3, 1953

Maine State Builders
208 Concord St.

Copies to: Mr. John Theodarakos
263 Cumberland Ave.
Ernest M. White Esq.
119 Exchange St.

Gentlemen:-

Mr. Theodarakos has withdrawn his zoning appeal with relation to construction of a concrete wall on his property at 267-269 Cumberland Ave.

Since we are unable to issue your building permit, if you will return the receipt for the paid fee of \$5.00, paid to this office, within 10 days of the date of this letter, your money will be refunded by voucher.

Very truly yours,

Warren McDonald
Inspector of Buildings

WMcD/G

AP 267-269 Cumberland Ave.

October 1, 1953

Mr. John Theodarakos
263 Cumberland Ave.,
Maine State Builders
208 Concord St.

Copy to: Corporation Counsel

Gentlemen:

Building permit intended to authorize construction of a concrete block wall about eight feet high to be supported upon a concrete foundation along the rear and two side lotlines of the rear yard of the property at 267-269 Cumberland Ave., is not issuable under the Zoning Ordinance, because the wall, though intended largely as a fence or barrier, would be a structure and as such would represent an unlawful encroachment upon the rear yard of the apartment house on the same property.

As I have written you about this situation before at some length, it is assumed that you desire to seek an exception from the Zoning Board of Appeals; so, there is enclosed an outline of the appeal procedure.

If you desire to seek such an exception from the Board of Appeals and desire the Board's consideration at the earliest possible date, it would be well for you to file the appeal in the office of Corporation Counsel before the close of business on Friday, October 9.

Very truly yours,

Warren McDonald
Inspector of Buildings

WMC/B

Enc: Outline of appeal procedure

AP 267-269 Cumberland Ave.

September 16, 1953

Mr. John Theodorakos
263 Cumberland Ave.
Maine State Builders
208 Concord St.

Gentlemen:-

Mr. Steven Skoolias as agent for the owner has applied for a building permit to authorize construction of a concrete foundation wall for a new fence at 267-269 Cumberland Ave., saying that the wall would extend only 18 inches above the ground. Inspection shows that this wall would not be called upon to retain any earth. Unless such a wall is to extend at least four feet above the grade of the ground the Building Code stipulates that no permit shall be required, and no permit is required for construction of the fence.

The location is in Fire District 15, however, and the height of a wooden fence in that Fire District is limited by the Building Code to not more than 10 feet above the ground. Probably you have no intention of building a fence to anything like that height.

Though no permit is to be issued for this work, I presume that you realize your obligations to the owner on adjoining property and your liability should anything go wrong. It is noted that the foundation for the new fence will be very close to the foundation wall of one or more buildings on adjoining lots. It would be well for you to contact these owners and tell them what you intend to do, and then take good care not to cause any damage to that adjoining property.

It is also noted that the eill of the owner's house has questionable foundations in at least one place near where the foundation of the fence will be. While this work is going on those foundations should be made permanently safe and secure.

If Mr. Skoolias will return the receipt for fee paid to this office before September 22, 1953, the fee money will be refunded by voucher.

Very truly yours,

Warren McDonald
Inspector of Buildings

WMCD/G

F. S. Our permit clerk reports that you had not decided what kind of a fence to build, but was considering a concrete block wall perhaps seven or eight feet high to serve as a fence.

If you should decide on a wall 18 inches above the ground shown on the application, then a permit is necessary not only for the foundation but for the wall. You should, in that case, change your application to show details of the wall above and give estimated cost of both walls.

It is doubtful if such a wall to serve as a fence would be allowable under the Zoning Ordinance because the wall is a structure while the usual fence is not.

You have already started excavating, and if you intend to build the wall as a fence, the owner will have to stop all excavation and notify the next owner by letter what he plans

(See Page 2)

Mr. John Theodorakos - - - -2
Maine State Builders

September 15, 1953

to do in detail, and give us a copy of the letter. We are required to verify that the adjoining owner has received such a notice before we can issue that kind of a permit.



APPLICATION FOR PERMIT

Class of Building or Type of Structure Third Class
Portland, Maine, Jan. 10, 1953

RECEIVED
00070
JAN 10 1953

To the INSPECTOR OF BUILDINGS, PORTLAND, MAINE

The undersigned hereby applies for a permit to ~~erect~~ alter ~~repair~~ ~~rebuild~~ ~~demolish~~ ~~or~~ ~~remove~~ ~~or~~ ~~change~~ ~~the~~ following building ~~structure~~ ~~or~~ ~~part~~ ~~thereof~~ in accordance with the Laws of the State of Maine, the Building Code and Zoning Ordinance of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 267 Cumberland Ave. Within Fire Limits? Yes Dist. No. _____
Owner's name and address John Kakos, 263 Cumberland Ave. Telephone _____
Lessee's name and address _____ Telephone _____
Contractor's name and address John Lyden, Mitchell Rd., Cape Eliz. Telephone 3-7803
Architect _____ Specifications _____ Plans Yes No. of sheets 1
Proposed use of building Lodging house No. families _____
Last use _____ " " _____ No. families _____
Material wood No. stories 2 1/2 Heat _____ Style of roof _____ Roofing _____
Other buildings on same lot _____
Estimated cost \$ 200. Fee \$ 2.00

General Description of New Work

To construct outside wooden fire escape second floor to ground on left hand side of building as per plan.

Permit issued with Letter:

Letter with photos and map of building location

1/13/53
1/15/53
CERTIFICATE OF COMPLIANCE
REQUIREMENTS MET

It is understood that this permit does not include installation of heating apparatus which is to be taken out separately by and in the name of the heating contractor. **PERMIT TO BE ISSUED TO** John Lyden

Details of New Work

Is any plumbing involved in this work? _____ Is any electrical work involved in this work? _____
Is connection to be made to public sewer? _____ If not, what is proposed for sewage? _____
Height average grade to top of plate: _____ Height average grade to highest point of roof _____
Size, front _____ depth _____ No. stories _____ solid or filled land? _____ earth or rock? _____
Material of foundation _____ Thickness, top _____ bottom _____ cellar _____
Material of underpinning _____ Height _____ Thickness _____
Kind of roof _____ Rise per foot _____ Roof covering _____
No. of chimneys _____ Material of chimneys _____ of lining _____ Kind of heat _____ fuel _____
Framing lumber—Kind _____ Dressed or full size? _____
Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____
Girders _____ Size _____ Columns under girders _____ Size _____ Max. on centers _____
Studs (outside walls and carrying partitions) 2x4-16" O. C. Bridging in every floor and flat roof span over 8 feet.
Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____
On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____
Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____
If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____ number commercial cars to be accommodated _____
Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will work require disturbing of any tree on a public street? NO
Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto are observed? yes

APPROVED:

with letter by [Signature]
[Signature]
INSPECTOR OF BUILDINGS

John Kakos

Signature of owner by: [Signature]

INSPECTION COPY

NOTES

1-23-53. Work not started. ~~OK~~
 1-24-53. Same. ~~OK~~
 2-7-53. Work started. ~~OK~~
 2-15-53. " " ~~OK~~
 2-25-53. " " ~~OK~~
 3-10-53. Permit on street work
 for 2nd floor. ~~OK~~
 3/17/53 - Dethen - ~~OK~~
 3-30-53. 4' depth set in, left end of main
 trench.

1-23-53 2-17-53
 2-11-53
 2-11-53
 Permit No. 53/70
 Location 917 Cambridge Road
 Owner John Gabeau
 Date of permit 1/11/53
 Notif. closing-in
 Inspn. closing-in
 Final Notif.
 Ft. & Inspn. 2-25-53, OK.
 Cert. of Occupancy issued 3/17/53

Inspector called said the
 bolts are inside studs, which
 are inside over 2"
 please see notes to take
 through with
 checked the nuts, both footing
 areas are as close as
 above.
 Concrete footing for post to be
 carried up about 6" above
 grade, verified per order of
 this ~~OK~~
 4-7-53 footing has been extended
 above grade. ~~OK~~

Blank lined area for additional notes.

18 367 Cumberland Ave.

March 19, 1953

Mr. John Lyden
Mitchell Road
Way Elizabeth
Mr. John Kakos
263 Cumberland Ave.

Location - 367 Cumberland Ave.

Owner - John Kakos

Job - Outside Wooden Fire Escape

Gentlemen:-

Upon inspection of the above job on March 10th, our inspector reports the following omissions or defects:

The through bolts fastening the brackets of the above fireescape to the wall have a 2x6 against the baseboard. The location of these bolts in relation to the wall studs is not known and it is doubtful if this construction is such that there is a solid bearing between the inside wall studs and the baseboard. Unless it can be definitely established that these through bolts receive direct bearing on the outside wall, it will be necessary to change them so they do. Also one of these through bolts did not have a washer and nut on it when the inspection was made.

When the above inspection was made, the lower ends of the stair stringers were supported by punchons about 18 feet above grade with no means of reaching the ground except by jumping. In an emergency, persons in the house, not familiar with the situation, would have reason to accept this as a useable means of egress. As can be readily seen, this is a definitely dangerous condition.

It is therefore necessary that this work be reactivated and the above matters corrected and this office notified for inspection before March 30, 1953.

If additional information relative to the above is desired, please phone Inspector Hamilton at 4-1431, extension 234, any week day but Saturday between 8:30 and 9 A. M.

Very truly yours,

Warren McDonald
Inspector of Buildings

Inspector

AJH/C

CITY OF PORTLAND, MAINE

Department of Building Inspection

To: Oliver T. Sanborn
Chief of the Fire Department

(date) 1/23/53

Location: 267 Cumberland Ave.

From: Warren McDonald
Insptr. of Bldgs.

Subject: Application for permit for
improvements at above location,
required by order of Chief of Fire
Department dated 11/19/52

While our two departments have done a good job of coordination under the Safety Ordinance--yours issuing the orders after inspection and ours issuing permits for improvements to be made,--

The confusion on the part of many people, who come in here, as to who has ordered them to do what,

The fact that on some jobs a permit has been issued, and the work done, only to have your inspector find that the situation did not then satisfy your order under the law,

And, the fact that you are permitted under the Building Code to exercise discretion as to details of means of egress in an existing building where there is no substantial increase in number of persons accommodated, while we must proceed under the precise terms of the Code unless deviation in this connection is approved by yourself--

leads me to the belief that each situation ought to be checked before any permits are issued, presumably by the inspector in your department who made the inspection on which the original order was based, to see:

1. If the work contemplated will completely satisfy the order.
2. To see, if possible, whether or not there may be some more economical way of satisfying the order, and, if so, to recommend that way to the owner.

To that end there is attached for your consideration applications for permits at the above location.

Remarks relating to this particular job:

Will the proposed arrangement shown on the accompanying plan satisfy the requirements of your order of 11/19/52?

WMS/G

Warren McDonald
Inspector of Buildings



(S) GENERAL BUSINESS ZONE
CITY OF PORTLAND, MAINE
DEPARTMENT OF BUILDING INSPECTION

Complaint No. C-42-55

INSPECTION COPY

COMPLAINT

Location 257-269 Cumberland Avenue Date received May 15, 1941
 Use Building Tenement house
 Owner's name and address Fred H. Small, Trustee, 67 North Street Telephone _____
 Tenant's name and address _____ Telephone _____
 Complainant's name and address Fire Dept. Telephone _____

Description: Question as to occupancy and means of egress.

INSPECTION NOT COMPLETED

*It seems this hall (if you) leading
 to stairs is locked at time of
 inspection. Several floors are
 practically impassable.
 Several floors from 1st floor are
 obstructed with front stairs as
 by direct means of egress.*

*The rear chimney is in
 questionable condition with
 basement there is a small
 cupboard or closet with a
 suspended board ceiling.
 A number of beams to stop
 above this with the
 smoke pipe opening just
 above the top of plate*




*The fire escape has a chimney pipe
 and is not safe.*

Complaint No. C-41-55
 Location: 767-269 Cumminsland Ave
 Date Received: 5/15/41
 Date Disposed of: (5/21/41)

NOTES

Spoke to owner surveying in 1924
 dwelling in 1924
 location date and record
 in 1970 into the family
 1941. History of floor
 foundation
 We have no records of a
 structure of building of 1924
 material. ^{split in 1929 City of Chicago}
 There are three front door
 bellows for each front door
 a should there and it. It depends through rear basement door
 addition there is a two
 room apartment on second floor front on sleeping
 four units or apart in the front door only ^{inlet} in case of egress.
 live there beside the car takes
 lives in the basement
 not sleeping in the
 front room first floor
 means of egress is a
 grateable floor
 over



CUMB. AVE.
 Generally typical floor plan

Basement Part - Rooms A, B, D, H with C-E floor
 First Floor - Rooms A, B, D, E Hall, C, G Has two...
 Second Floor - Rooms A, B, D, E Hall, C, G On top...
 front door only in case of egress.
 first floor concrete or masonry
 on first floor and is really part of



(C) GENERAL BUSINESS ZONE

CITY OF PORTLAND, MAINE

DEPARTMENT OF BUILDING INSPECTION

Complaint No. C-41-55

COMPLAINT

INSPECTION COPY

Date received May 15 1941

Location 267-269 Cumberland Avenue

Use of Building

Fragment - house

Owner's name and address Fred H. Small, Trustee, 67 North Street

Telephone

Tenant's name and address

Telephone

Complainant's name and address Fire Dept.

Telephone


Description: fire alarm to occupancy and means of egress.

INSPECTION NOT COMPLETED

The door in this hall (at fire) leading to rear stairs is locked at time of inspection & second floor was full of water & no egress was practically impossible.

Second floor - from H-F from an apartment with front stairs as only direct means of egress.

The rear chimney is in questionable condition in the basement there is a small cupola or closet with a mismatched board ceiling, chimney appears to top above this with the smoke pipe opening just above the top of the belt.



The fire department chimney has recently etc.

SURVEY AND INVESTIGATION OF TENEMENT AND LODGING HOUSES
QUESTIONABLE AS TO LEGAL AND SAFE USE

1. Location CUMBERLAND AVE 267-269 Date investigation commenced _____
2. References: Complaints 4-55 Appl. BP _____ Inq. _____
3. Present Owner and Address Fred A. Small, Inc. (Deceased) 1127 North
4. Present Lessee and Address _____
5. Building Permit Record: Shelton A. San. 11/23/29, Dem. Shed 11/22/29 Heat
11/20 1/23/29, 1/27.

Assessors' Record

6. Survey 1924: Owner Gen. Truds. A. Leavitt Maryann E. Hennessey : No. tenants _____
No. rooms _____; Class of Use Dwelling - Two Family
7. Assessors' change record since 1924 54-71 Reported to have several families
8. Change of Owners, 1924 to date Maryann E. Hennessey, 1122 Nelson Development Co
1929 Fred A. Small Trustee

9. City Directory Record Mrs. Maude A. Bishop, Lodgh.

1926 <u>Roger E. McSweeney (Stella)</u>	1936 <u>Edwin H Bishop</u>
1927 <u>Same</u>	1937 <u>Same</u>
<u>Roger E. McSweeney (Stella)</u>	
1928 <u>Benjamin W. Burton - Rose E.</u>	1938 <u>Same</u>
1929 <u>VACANT</u>	1939 <u>Same</u>
1930 <u>Mrs. Lottie Morris</u>	1940 <u>Same</u>
<u>Mrs. Lottie Morris</u>	
1931 <u>Mrs. Eleanor McCrum</u>	1941 <u>Mrs. Maud Bishop Lodgh.</u> <u>Edwin H Bishop - Frederick L. McKay (Lida)</u>
1932 <u>Mrs. Eleanor A. McCrum</u>	1942 <u>Same</u>
1933 <u>Same</u>	1943 <u>Same</u>
<u>Mrs. Maude A Bishop Lodgh.</u>	
1934 <u>Edwin H Bishop</u>	1944 <u>Mrs. Maude A Bishop Lodgh.</u> <u>Edwin H Bishop, Frederick L. McKay</u>
1935 <u>Same</u>	1945 _____

10. Miscellaneous

Conclusions and Action



FILL IN COMPLETELY AND SIGN WITH INK

Permit No. _____

APPLICATION FOR PERMIT FOR HEATING, COOKING OR POWER EQUIPMENT

To the INSPECTOR OF BUILDINGS, Portland, Me. Portland, Maine, May 1 1929

The undersigned hereby applies for a permit to install the following heating, cooking or power equipment in accordance with the laws of Maine, the Building Code of the City of Portland, and the following specifications:

Location 267 Ocean Ave Use of Building Rooming House

Name and address of owner Ed. Small, North St

Contractor's name and address N. J. Barber, 23 North St Telephone F1026 R

General Description of Work

To install Steam Boiler
IF HEATER, POWER BOILER OR COOKING DEVICE Post card sent 5/2/29

Is heater or source of heat to be in cellar? ye If not, which story _____ Kind of Fuel oil

Material of supports of heater or equipment (concrete floor or what kind) _____

Minimum distance to wood or combustible material, from top of boiler or casing top of furnace, 3 or 4 ft

from top of smoke pipe 4', from front of heater 3' from sides or back of heater 3'

IF OIL BURNER

Name and type of burner _____ Approved by Underwriters' Laboratories? _____

Location oil storage: _____ No. and capacity of tanks _____

Will all tanks be more than seven feet from any flame? _____ How many tanks fireproofed? _____

Amount of fee enclosed? 1.00 (\$1.00 for one heater, etc. 50 cents additional for each additional heater, etc in same building at same time)

Signature of contractor N. J. Barber

9100



APPLICATION FOR PERMIT

Class of Building or Type of Structure _____

Portland, Maine, May 1, 1929

PERMIT ISSUED
No. _____
MAY 2 1929

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter install the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location 267 Cumberland Avenue Ward 4 Within Fire Limits? Yes Dist. No. 1

Owner's or lessee's name and address Fred Small North St. Telephone _____

Contractor's name and address H. J. Baker, 23 North St. Telephone P 1036

Architect's name and address _____

Proposed use of building _____ No. families _____

Other buildings on same lot _____

Description of Present Building to be Altered

Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____

Last use _____ No. families _____

General Description of New Work

To install steam boiler

Minimum distance from top of smoke pipe to woodwork or ceiling above 5' or 4'
Minimum distance from smoke pipe to any other woodwork 5'
Minimum distance from top of heater to the woodwork or ceiling above 5' or 4'

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____

To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Kind of heat steam Type of fuel coal Distance, heater to chimney _____

If oil burner, name and model _____

Capacity and location of oil tanks _____

Is gas fitting involved? _____ Size of service _____

Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O.C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____

Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Plans filed as part of this application? no No. sheets _____

Estimated cost \$ _____ Fee \$ 1.00

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto

are observed? Yes

Signature of owner _____

INSPECTION COPY



PERMIT No. 10347

APPLICATION FOR PERMIT

0347

Class of Building or Type of Structure Third Class

MAR 26 1929

Portland, Maine, March 26, 1929

To the INSPECTOR OF BUILDINGS, PORTLAND, ME.

The undersigned hereby applies for a permit to ~~erect~~ alter ~~install~~ the following building structure equipment in accordance with the Laws of the State of Maine, the Building Code of the City of Portland, plans and specifications, if any, submitted herewith and the following specifications:

Location Near 267 Cumberland Avenue Ward 4 Within Fire Limits? Yes Dist. No. 1

Owner's or Lessee's name and address Fred H. Small, 67 North St. Telephone 8903

Contractor's name and address Harry McKay, 217 Cumberland Ave. Telephone _____

Architect's name and address _____

Proposed use of building Dwelling house No. families 1

Other buildings on same lot _____

Description of Present Building to be Altered

Material _____ No. stories _____ Heat _____ Style of roof _____ Roofing _____

Last use dwelling house No. families 1

General Description of New Work

To demolish shed attached to ell of dwelling house, 15 x 8

NOTIFICATION BEFORE LATHING OR CLOSING-IN IS WAIVED.

CERTIFICATE OF OCCUPANCY REQUIREMENT IS WAIVED.

Details of New Work

Size, front _____ depth _____ No. stories _____ Height average grade to highest point of roof _____

To be erected on solid or filled land? _____ earth or rock? _____

Material of foundation _____ Thickness, top _____ bottom _____

Material of underpinning _____ Height _____ Thickness _____

Kind of roof _____ Roof covering _____

No. of chimneys _____ Material of chimneys _____ of lining _____

Kind of heat _____ Type of fuel _____ Distance, heater to chimney _____

If oil burner, name and model _____

Capacity and location of oil tanks _____

Is gas fitting involved? _____ Size of service _____

Corner posts _____ Sills _____ Girt or ledger board? _____ Size _____

Material columns under girders _____ Size _____ Max. on centers _____

Studs (outside walls and carrying partitions) 2x4-16" O. C. Girders 6x8 or larger. Bridging in every floor and flat roof span over 8 feet. Sills and corner posts all one piece in cross section.

Joists and rafters: 1st floor _____, 2nd _____, 3rd _____, roof _____

On centers: 1st floor _____, 2nd _____, 3rd _____, roof _____

Maximum span: 1st floor _____, 2nd _____, 3rd _____, roof _____

If one story building with masonry walls, thickness of walls? _____ height? _____

If a Garage

No. cars now accommodated on same lot _____, to be accommodated _____

Total number commercial cars to be accommodated _____

Will automobile repairing be done other than minor repairs to cars habitually stored in the proposed building? _____

Miscellaneous

Will above work require removal or disturbing of any shade tree on a public street? no

Plans filed as part of this application? no No. sheets _____

Estimated cost \$ _____ Fee \$ 50

Will there be in charge of the above work a person competent to see that the State and City requirements pertaining thereto

are observed? Yes


Signature of owner Fred H. Small

INSPECTION COPY

8751

Ward 4 Permit No. 29/347
Location Rear 267 Cumberland Ave
Owner Fred H. Small
Date of permit 3/26/29
Notif. closing-in _____
Inspn. closing-in _____
Final Notif. _____
Final Inspn. 4/1/29 AD
Cert. of Occupancy issued _____

NOTES



[Faint, illegible text in the right margin, possibly bleed-through from the reverse side of the page.]



Location, ownership, and detail must be correct, complete and legible. Separate application required for every building.

APPLICATION FOR PERMIT TO BUILD
A PRIVATE GARAGE

Portland, Me., May 10, 1922 19

TO THE
INSPECTOR OF BUILDINGS

The undersigned hereby applies for a permit to build, according to the following Specifications:-

Location 269 Cumberland Avenue Fire Districts yes Ward 3
Name of owner is? Nina Stowell Address 176 Pearl Street
Name of mechanic is? Thomas Skinner Co Address 97 Center Street
Proposes occupancy of building (purpose)? Steel Private garage for one

cars only, and no space to be let.

Not nearer than two feet from any lot line, will not obstruct windows of adjoining property.

A Pyrene fire extinguisher to be kept in garage.

Size of building, No. of feet front? 10ft; No. of feet rear? 10ft; No. of feet deep? 18ft

No. of stories? 1

No. of feet in height from the mean grade of street to the highest part of the roof? 12ft

Floor to be? concrete

Will the roof be flat, pitch, mansard, or hip? pitch Material of roofing? steel

Will there be a chimney? no Will the flues be lined? no No stoves to be used.

Will the building conform to the requirements of the law? yes

Will the building be as good in appearance as other surrounding buildings? yes

Have you or any person acting for you previously applied for a permit to build a private garage? no

If so, state the particulars _____

Estimated Cost, _____

\$ 220. Signature of owner or authorized representative, Thomas Skinner Co

Address, 95 77 Center St.

269 Cumberland Ave

No. 6619.....

APPLICATION FOR
PRIVATE GARAGE

LOCATION
No. ²⁶⁹ 269 Cumberland Avenue

WARD 3

PERMIT GRANTED

May 10, 1922

102