

**Legalization Inspection Form**

Date: 2/2/2018

Address: 59 Myrtle Street

Legal Use: Two Family

Proposed Use: Three Family

**Common Areas**

**Basement**

- Fire Door: n/a
- Detection: Yes, a hard wired combination detector is in place.
- Sprinkler Head: Yes, in place.
- Electrical/panel: Cable wires will need to be secured so that panel door can open easily.

Notes: Dryer vent hoses need to be replaced to meet code.

Electrical switches and outlets need cover plates installed. Elimination of extension cords where used as a permanent source of power.

**Unit 1**

- Fire Door: n/a
- Detection: Yes, in place
- Egress: \_\_\_\_\_

Notes: Unit one is ground level and access is direct from outside.

---

**Unit 2**

- Fire Door: n/a \_\_\_\_\_
- Detection: Detector on the third floor needs to be a combination smoke and carbon monoxide. All other required detection is in place.
- Egress: \_\_\_\_\_

**Unit \_3\_**

- Fire Door: n/a \_\_\_\_\_
- Detection: yes, required detection is in place.
- Egress: \_\_\_\_\_

Notes: Each unit's egress is to the outside. There are no common areas.

---

**Overall**      Pass \_\_\_\_\_      Fail \_\_\_\_\_      Follow up Required \_\_\_\_\_ X \_\_\_\_\_

**Inspector:** Chuck Fagone/ Matt Sarapas \_\_\_\_\_

**Fire Prevention:** \_\_\_\_\_