Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 02/22/18

Legalization Inspection Form

Date: __2/2/2018_____

Address: 59 Myrtle Street

Legal Use: Two Family

Proposed Use: Three Family

Common Areas

Basement

- Fire Door: n/a
- Detection: Yes, a hard wired combination detector is in place.
- Sprinkler Head: Yes, in place.
- Electrical/panel: Cable wires will need to be secured so that panel door can open easily.

Notes: Dryer vent hoses need to be replaced to meet code.

Electrical switches and outlets need cover plates installed. Elimination of extension cords where used as a permanent source of power.

Unit _1__

- Fire Door: n/a
- Detection: Yes, in place
- Egress: _____

Notes: Unit one is ground level and access is direct from outside.

_____

Unit _2__

- Fire Door: n/a_____
- Detection: Detector on the third floor needs to be a combination smoke and carbon monoxide. All other required detection is in place.
- Egress: _____

Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 02/22/18

Unit _3__

- Fire Door: n/a_____
- Detection: yes, required detection is in place.
- Egress: _____

Notes: Each unit's egress is to the outside. There are no common areas.

_____

Overall Pass_____ Fail_____ Follow up Required _____X_____

Inspector: Chuck Fagone/ Matt Sarapas_____

Fire Prevention: _____