THIS IS NOT A BOUNDARY SURVEY

This copyrighted document expires 11-12-15. Reproduction and/or dissemination after this date is unauthorized. MORTGAGE INSPECTION OF: DEED BOOK __32079__ PAGE ___90___ COUNTY __Cumberland PLAN BOOK _____ PAGE ____ LOT ____ ADDRESS: 50-52 Wilmot Street, Portland, Maine Job Number: 858-91 Inspection Date: 8-12-15 Scale: 1'' = 20'Owner: 50-52 Wilmot Street, LLC UBL 926 0497 991 abutting gravel area bulk head 2 1/2 story wood structure w/ brick foundation no deed distance multi-family commércial building paved area porch gravel area garage multi-family commercial building 3 story wood structure w DAVID
L. J.
HUGHES
#2234
OF
SUPPLIED

SUPPLIED

SUPPLIED

TO SUPPLIED brick foundation abutting commercial 113'±(deed) building Lines of occupation are shown. A boundary survey may yield different results. APPARENT EASEMENTS AND RIGHTS OF I HEREBY CERTIFY TO: 50-52 Wilmot Street, LLC; WAY ARE SHOWN. OTHER ENCUMBRANCES, RECORDED OR NOT, MAY EXIST. THIS and the title insurer. SKETCH WILL NOT REVEAL ABUTTING DEED CONFLICTS, IF ANY. Monuments found did not conflict with the deed description. copyright@ The dwelling setbacks do not violate town zoning requirements. Livingston-Hughes As delineated on the Federal Emergency Management Agency Community Professional Land Surveyors Panel 230051-0013 B: 88 Guinea Road The structure does not fall within the special flood hazard zone. Kennebunkport, Maine 04046 The land does not fall within the special flood hazard zone. 207-967-4831 fax 207-967-9761 phone A wetlands study has not been performed. www.livingstonhughes.com