
NO PARKING
1½HR PARKING
GRANITE CURB
Structure to be demolished
NO PARKING
1HR PARKING
GRANITE CURB
1" IRON PIPE FOUND
N/F
REBECO LLC
26365/256
28-I-12
2,414 S.F.
GAS METER
DOWNSPOUT
SILL=44.3'
NO PARKING
DOWNSPOUT
5/8" REBAR FOUND
DOWNSPOUT
2 1/2 STORY DWELLING
32 HAMPSHIRE STREET
DOWNSPOUT
DOWNSPOUT
45.00' (45')
N 39°01'12" E
45.66'
N 46°16'56" W
50.07'
S 52°21'06" W
X=38.8'
2 1/2 STORY DWELLING
167 NEWBURY STREET
ELECTRIC METER
DOWNSPOUT
8" TRD
NO PARKING
GRANITE CURB
Parking area
50.00'
1" IRON PIPE
OHU
GRAVEL AREA