

•
•
•
•
•
•
•

131 Eight Rod Road
Augusta, Maine 04330
Phone: (207) 458 -7143
Fax: (207) 621- 8324
Email: Iconenviro@aol.com

Icon Environmental Consultants

March 30, 2010

Opechee Construction Corporation
11 Corporate Drive
Belmont, New Hampshire 03220
Attn: Mr. Dana Adams, P. E.

Re: Former Jordan Meats Facility Portland, Maine

Dear Mr. Adams:

Icon Environmental performed a Visual Evaluation of the Ammonia lines and tanks at your request.

The lines and tanks were drained, vented and breached some 5 years ago as part of the plant closure procedure as required by Maine DEP Plant Closure Requirements. Any residual gas would have escaped during the above process or dispersed in subsequent seasons.

No mechanical methods or testing methods were used in making this assumption. This was a visual survey only. Lines and valves were removed or cut during the decommission process making it highly unlikely Ammonia would remain in the tanks or lines.

Please contact us at (207) 458-7143 with any questions.

Sincerely,

Craig E. Wilson

Craig E. Wilson
Air Analyst, Air Monitor
Maine DEP # AA-0016, AM-0019

