

# Eastern Fire

Ph 207.942.6314 • Fax 207.942.0566  
 207.942.8014 • Fax 207.942.5202  
 Salisbury Ave, Auburn, ME 04210  
 4 Harlow St, Bangor, ME 04401

WHITE COPY TO OFFICE

I	T
N	O
V	
O	
T	
C	
E	

Work Order No: **103005**

DATE: 3-27-19

CUST. PO#

Check one:  SPRK  ALARM  GAS

DESCRIPTION OF WORK COMPLETED

CONDUCTED MANUAL GAS ALARM INSPECTION AND TESTING

Power in trouble. Change OUT ADDRESS 1052. Smoke BAR from smoke system

NORMAL. Smoke. DET ADDRESS 1052. KIT. PREP IN B-GOOD TR. KIT. BY STEAM - CHANGED TO HFT

DESCRIPTION OF WORK REMAINING  
 Complete  Open

## CHECK LIST

JOB NAME: 9/15 Exchange ST.  
 JOB LOCATION: 9/15 Exchange ST.  
 JOB ADDRESS: Portland ME 04101  
 CONTACT: PJ Roberts  
 PHONE: 207-633-1607

### MATERIALS USED

1) H.F.P-11 SEMIENS Smoke Detector  
 1) H.F.PT-11 SEMIENS Heat Detector  
 NOTES: ON ARRIVAL power in trouble. and Error BAR Room B-Good smoke 1052. Load volts low - No Response

2) 1061 MULTIPLE ADDRESS  
 Power testing system normal.

## ELD PURCHASED MATERIALS AND RENTALS

Active Time	Depart Time	Off hrs call out	Worker Names	LABOR	HRS	RATE	AMT
8:30	2:00		Poloid Gendreau	Foreman			
				Helper			
				Design			

As responsible for equate heat to prevent fire low point providing electricity and wiring and responding to various conditions. would purchase copies IFA Standards. ing, but not limited to.

DATE