

PORTEAND MANTE

Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Director of Planning and Urban Development Jeff Levine, AICP, Director

SEPTEMBER 18, 2012

ELEVEN EXCHANGE LLC PO BOX 4894 PORTLAND, ME 04112

CBL: 032 F014001 LOCATED AT 1 EXCHANGE ST

CERTIFIED MAIL: 70080500000145878355

Dear Mr. Joe Soley:

On September 13, 2012 the City conducted a 1:00 PM scheduled inspection of your property at 1 Exchange. Your property manager PJ, and Electrician agreed to be present for the inspection, and provide access to all portions of the building's basement.

By virtue of this letter and the violations listed below, the City is putting you on notice of existing Housing Code and Life Safety Code (Fire) Violations observed at 1 Exchange Street. These violations require immediate correction. They are as follows:

- 1) Patch/Repair: Every foundation, basement, cellar, exterior wall, and roof shall be substantially weathertight, watertight, and vermin proof, in accordance with Section 6-108 (a).
 - a. All through-penetrations (openings in the basement ceiling), must be repaired with approved materials (Gypsum board, plaster, etc.) maintaining the required fire separations.
- 2) Illumination: Lighting within the basement must be functional, in accordance with Section 6-113 (e).
 - a. Note: If new wiring is installed, the City requires an electrical permit application to be submitted by a Master Electrician no later September 24, 2012.
 - b. The illumination of means of egress shall be continuous at all times during occupancy. Automatic, motion sensor-type lighting switches (set at a minimal of fifteen-minute duration) shall be permitted within the means of egress provided that the switch controllers are equipped for fail-safe operations.
- 3) Pest Control: The presence of rodent infestation is evident in the basement, a licensed Pest Control Operator must be retained to address this condition and a certification from such Operator needs to be submitted to the City.
 - a. Note: City Inspectors found at least three dead rodents and rodent feces throughout the basement.
- 4) Garbage/Improper Storage: Garbage has been allowed to accumulate in the basement of 1 Exchange Street and throughout the rear of the property which needs to be removed, in accordance with Section 6-109 (d).
- 5) Life Safety Code (Fire) Violations
 - a. <u>Exterior Windows/ Doors:</u> The vines and other vegetation shall be removed from the exterior windows: vents, kitchen exhaust, and doors from the back exterior wall of 1 Exchange Street, in accordance with NFPA 1, 2009, Section 10.14.10 Exterior Vegetation.
 - b. See the attached notice of violation from Fire Prevention.
- 6) Defective Sewer Lateral: You must make satisfactory repairs and/or replacement of your failed sewer lateral, in accordance with Section 24-42 of the City Code.
 - a. See the attached final unappealed notice of violation from the Department of Public Services.

A re-inspection of the premises will occur on 09/28/2012 at which time compliance will be required.

Failure to comply with this notice will result in further enforcement action by the City of Portland Corporation Counsel, as provided for in § 1-15 of the Code and in Title 30-A of M.R.S.A § 4452. The above violations in paragraphs 1-5 may be appealed pursuant to §112 of the City of Portland Building Code.

The City is committed to maintaining safe buildings, quality neighborhoods and an excellent community environment. Our citizens expect us to do everything we can in this regard; we understand that this can only be achieved through the cooperation of everyone involved.

The City wants to work with you to bring this building into compliance with our minimal standard building and housing codes. We trust that your cooperation will be evident in your meeting the above time frames.

Sincerely,

Jonathan Rioux,

Code Enforcement Officer/ Plan Reviewer

cc: Mie

Michael Bobinsky, Director of Public Services Chris Pirone, Captain/ Fire Prevention Officer Harold L Downs, Senior Wastewater Technician Chuck Fagone, Code Enforcement Officer Michelle Sturgeon, Health Inspector

Prepared: 9/18/12, 10:59:18

Outstanding Violations

Page

0/00/00

0/00/00

Program: FP322L

FIRE PREVENTION

by Property Report

Property address Property name Property number Inspection type Date Inspector Seq. Violation class Reference

Violation type Actual Target Location(s) date date

0001 EXCHANGE ST, PORTLAND ME 04101 CITY BEVERAGE 1439-000-002 CITY LICENSE INSPECTION 6/07/10 JOHN MARTELL, Fire HQ, Staff 10 hrs 1 FIRE PROTECTION EQUIPMENT SUPPRESSION SYSTEM NEEDS SERVICE 7/09/10 SPRINKLET SYSTEM NEEDS ANNUAL INSPECTIO 2 ELECTRIC WIRING EXT. CORD USED FOR PERMENANT WIRING 7/09/10 THROUGHOUT STORE

7/09/10 0/00/00 3 ELECTRIC WIRING CERTIFY ELECTRICAL SYSTEM HAVE ELECTRICIAN INSPECT ALL WIRING; IN STORE AND CERTIFY

FIRE EXTINGUISHERS NEED ANNUAL SERV 7/09/10 0/00/00 4 FIRE EXTINGUISHERS

EXTINGUISHERS NEED ANNUAL INSPC. 9/13/12 JOHN JR CENATE, Munjoy Hill Station, Platoon 1 ROUTINE INSPECTION

PROVIDE TEST & COMPLIANCE DOCUMENTA 0/00/00 9/13/12 1 FIRE PROTECTION EQUIPMENT SPRINKLER SYSYTEM

0/00/00 2 HOUSE KEEPING DEBRIS INSIDE BUILDING 10/23/12 BASEMENT AREA

UNNECESSARY DEBRIS OUTSIDE OF STRUC 10/23/12 0/00/00 3 HOUSE KEEPING BY BASEMENT DOOR

4 HOUSE KEEPING COMBUSTIBLES STORED UNDER STAIRWAY 1-4-1.2.1 10/23/12 0/00/00 INDER FIRE ESCAPES

0/00/00 10/23/12 5 ELECTRIC WIRING OPEN ELECTRICAL JUNCTION BOX

BASEMENT 10/23/12 0/00/00 SMOKEPROOF ENCLOSURES 6 MERCANTILE & BUSINESS

ALL WERTICAL OPENINGS IN THE BASEMENT 0/00/00 7 LIFE SAFETY REQUIREMENTS MAINTENANCE, INSPECTION, AND TESTIN 1-4.5.8 9/13/12

PLEASE SIGN THE SPRINKLER ROOM DOOR

Violation Summary:

Closed Total Open. 11



Strengthening a Remarkable City, Building a Community for Life

www.portlandmaine.gov

Department of Public Services

Michael J. Bobinsky, Director

FINAL NOTICE

October 19, 2011

Joseph Soley 10 Exchange Street, LLC PO Box 4894 Portland ME, 04112

RE: DEFECTIVE SEWER LATERAL 377 FORE STREET

Dear Mr. Soley,

On March 10, 2011, I hand delivered to you a Defective Lateral Notice and the City of Portland's Sewer Ordinance. At that time I informed you of the seriousness of 377 Fore Street's sewer lateral condition. As you may recall, you gave me a tour of the basement of 377 Fore Street and it was obvious at that time that the building's lateral was not working properly due to the ankle deep water on the basement's floor. I explained to you that the source of the depression in the sidewalk in front of 377 Fore Street is caused by the undermining of the compact soils from your failed sewer lateral installed in 1896. The hand delivered notice informed you of the condition of the building lateral and what your responsibilities were to correct the failed lateral. You were given 15 days to make the necessary repairs to correct the failed sewer lateral. During that 15-day period the City of Portland inspected the depression, televised the City's sewer main, and made temporary repairs to the depression in the sidewalk in front of 377 Fore St. To the best of my knowledge, you have not taken any action to repair the failed sewer lateral.

Please consider this your final notice to make satisfactory repairs or replacement of your failed sewer lateral in accordance with Section 24-42 of the Portland City Code. You have 15 days from the date of this notice to make said repairs or replacement. Should you fail to comply with this order, the City will repair the sewer lateral and will charge you for the cost of said repairs. The charges will be assessed by the City upon completion of the work and shall constitute a lien on the property to be enforced in the manner provided for the collection of sewer assessments.

Please feel free to contact me if you have any questions.

cc: Michael Bobinsky, Director of Public Services

Sincerely
City of Portland

Harold L Downs Senior Wastewater Technician

Harold L Downs

Danielle West-Chuhta, Corporate Counsel
Mary Davis, Housing, and Community Services
Katherine Earley, Engineering Manager
Eric Labelle, Assistant Director – Operations
David Margolis-Pineo, Deputy City Engineer

Bradley Roland, Project Engineer Kevin Noyes, Construction Company Gordon Greenlaw, Supervisor James Sloan, Sewer Inspector

John Emerson, Wastewater Coordinator

Carol Merritt, Account Clerk II



City of Portland Inspection Services RETURN OF SERVICE

On the 19 th day of September, 2012, I made service of	PJ Roberts (NOV)
at 389 Congress Street, Room 315.	
By delivering a copy in hand	
By leaving copies at the individual's dwelling has person of a suitable age or discretion when mamed	ho resides therein and whose is
By delivering a copy to an agent authorized to name is	
By (describe other manner of service)	
DATED 9/20/12	Signature of Person Making Service
I have received the above referenced documents	Code Enforcement Officer/ Plan Reviewer Title
	P.J. Roberts
	Person Receiving Service
	Refused to Sign Unable to Sign
	Chable to Sign



PORTLAND MAINE

Strengthening a Remarkable City, Building a Community for Life . www.portlandmaine.gov

Director of Planning and Urban Development Jeff Levine, AICP, Director

SEPTEMBER 28, 2012



ELEVEN EXCHANGE LLC PO BOX 4894 PORTLAND, ME 04112

CBL: 032 F014001 LOCATED AT 1 EXCHANGE ST

CERTIFIED MAIL: 70080500000145878355

SECOND NOTICE OF VIOLATION

Dear Mr. Joe Soley:

A re-evaluation (and phone conversation with P.J. Roberts, Property Manager) of the above-referenced property on September 28, 2012 revealed that the structure remains non-compliant with the Building, Life Safety (Fire), and Public Sewer Codes of the City of Portland.

These violations require immediate correction. They are as follows:

- 1) Patch/Repair: Every foundation, basement, cellar, exterior wall, and roof shall be substantially weathertight, watertight, and vermin proof, in accordance with Section 6-108 (a).
 - a. All through-penetrations (openings in the basement ceiling), must be repaired with approved materials (Gypsum board, plaster, etc.) maintaining the required fire separations.
- 2) Illumination: Lighting within the basement must be functional, in accordance with Section 6-113 (e).
 - a. Note: If new wiring is installed, the City requires an electrical permit application to be submitted by a Master Electrician.
 - b. The illumination of means of egress shall be continuous at all times during occupancy. Automatic, motion sensor-type lighting switches (set at a minimal of fifteen-minute duration) shall be permitted within the means of egress provided that the switch controllers are equipped for fail-safe operations.
- 3) Pest Control: The presence of rodent infestation is evident in the basement, a licensed Pest Control Operator must be retained to address this condition and a certification from such Operator needs to be submitted to the City.
 - Note: City Inspectors found at least three dead rodents and rodent feces throughout the basement.
- 4) Garbage / Improper Storage: Garbage has been allowed to accumulate in the basement of 1 Exchange Street and throughout the rear of the property which needs to be removed, in accordance with Section 6-109 (d).

5) Life Safety Code (Fire) Violations

- a. Exterior Windows/ Doors: The vines and other vegetation shall be removed from the exterior windows: vents, kitchen exhaust, and doors from the back exterior wall of 1 Exchange Street, in accordance with NFPA 1, 2009, Section 10.14.10 Exterior Vegetation.
- b. See the attached notice of violation from Fire Prevention.
- 6) Defective Sewer Lateral: You must make satisfactory repairs and/or replacement of your failed sewer lateral, in accordance with Section 24-42 of the City Code.
 - a. See the attached final unappealed notice of violation from the Department of Public Services.

A re-evaluation will occur on October 4, 2012, at which time compliance will be required.

Failure to comply with this notice will result in further enforcement action by the City of Portland Corporation Counsel, as provided for in § 1-15 of the Code and in Title 30-A of M.R.S.A § 4452. Furthermore, the City Council has amended the Building regulations to include a \$75.00 re-inspection fee. Our files indicate that you owe \$275.00 in fees (see attached invoice). If there are any subsequent inspections, however, and additional \$75.00 fee will be assessed for each inspection.

The City is committed to maintaining safe buildings, quality neighborhoods and an excellent community environment. Our citizens expect us to do everything we can in this regard; we understand that this can only be achieved through the cooperation of everyone involved.

Sincerely,

Jonathan Rioux,

Lode Enforcement Officer/ Plan Reviewer

cc: Danielle West-Chuhta, Acting Corporation Counsel Michael Bobinsky, Director of Public Services Chris Pirone, Captain/ Fire Prevention Officer Harold L. Downs, Senior Wastewater Technician Chuck Fagone, Code Enforcement Officer

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

INVOICE FOR FEES

Owner:

ELEVEN EXCHANGE LLC

Location:

1 EXCHANGE ST

CBL:

032 F014001

Invoice Date:

09/28/2012

Fee Description	Fee Charge
09/28/2012	\$100.00
stop work order removal	
09/28/2012	\$100.00
stop work order	
09/28/2012	\$75.00
re inspection fee	
	Total Billed: \$275.00
A S	Total Paid: \$0.00
* A	mount Due: \$275.00







