


Reviewed for Code Compliance Permitting and Inspections Department Approved with Conditions

12/13/2018




3 Offices 1 Paralegal 1,908 RSF





New Wall location.

New door location.





Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions


12/13/2018

e: Revisions: 19 March 2010 1/8" = 1-0" SEVENTH FLOOR PLAN

2 MONUMENT SQUARE

11/12/18

PLANS DRAWN TO SHOW FLOOR PLAN LAYOUTS. DIMENSIONS SHOULD BE FIELD VERIFIED.



A1.0