Inspections Division

Date: 07/17/13

CODE SUMMARY DOCUMENTATION

Full sprinkler system monitored.

Full fire alarm system, horns and strobes, monitored.

Non-combustible construction.

Four story building.

Area of work second floor, left side.

Note:

All existing life safety devices to remain