



Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions

12/13/2018

Google Maps 1 Market St



Image capture: Jul 2018 © 2018 Google

Portland, Maine

Google, Inc.

Street View - Jul 2018



Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions

12/13/2018

- SECURE DOOR ON INSIDE AND INSTALL RAILING ON OUTSIDE.
- REMOVE 3rd floor deck AND CONNECTING STAIR.




7-9 Moulton (REAR) ie. 4 MARKET ST.

15 NOV. 18



Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions

1213 2018




Index Number - 000000

E1059

Tax Map Index: <http://www.portlandassessors.com/taxmaps.htm>

April 1 2012 fy 2013

E88E



Map data ©2018 Google 20 ft



Reviewed for Code Compliance
Permitting and Inspections Department
Approved with Conditions

12/13/2018

11/15/2018

https://www.google.com/maps/@43.6563408,-70.2524373,19.76z?hl=en