

July 28, 2017

16240

Code Enforcement Officer
389 Congress St
Portland, ME 04101

Re: 36 Alder St, Portland, ME
Statement of Special Inspections – Final Report

Dear CEO,

To the best of my information, knowledge and belief, the exterior wood framed egress stairs at 36 Alder St. have been constructed in general conformance with the permit drawings. Soil / subgrade testing, concrete testing, and backfill/compaction testing has not been completed at this time.

Sincerely,



Aaron S. Wilson, P.E.
Structural Engineer
Associated Design Partners, Inc.

