Portland, Maine



Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

June 10, 2015

TEVANIAN SHIRLEY E TRUSTEE 44 CEDAR ST PORTLAND, ME 04101

CBL: 033 H011001

Located at: 44 CEDAR ST

Certified Mail 7010 1870 0002 8136 8039

Dear Ms. Tevanian,

An evaluation of the above-referenced property on 06/09/2015 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 30 days of the date of this notice. A re-inspection of the premises will occur on 07/09/2015 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely.

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager TEVANIAN SHIRLEY E TRUSTEE		Inspector	Inspection Date
		Chuck Fagone	6/9/2015
Location	CBL	Status	Inspection Type
44 CEDAR ST	033 H011001	Re-Inspect 30 Days	Complaint-Inspection

_	Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1)	6-116. (e)	Interior			Smoke Alarms	
Vic	lation:	FIRE PROTECTION				
Every dwelling, dwelling unit, rooming house and rooming unit shall comply with the applicable provisions of the most current edition of the National Fire Protection Association Life Safety Code, ar with all other applicable state statutes and regulations.						

Comments:

Violations exist, no smoke detectors. A battery operated or hard wired smoke detector will need to be installed in each bedroom. A combination smoke/carbon monoxide detector should be installed on each floor in a common area (living room or foyer). Detectors will need to be photo-electric.