



PHOTO
1
0941.jpg

Deering Oaks Bandstand: Front View. Anticipated work scope includes temporary shoring and replacement of three perimeter trusses (arrows) as well as front drip edge replacement and side edge drip edge and shingle replacement.



PHOTO
#2
2843.jpg

Deering Oaks Bandstand: Left Elevation: Replace exterior truss and matching truss on right elevation.



PHOTO
#3
06093.jpg

End Truss Connection at Girder Truss: Arrow shows end of Front Girder Truss. See Photo #4 for downward view of girder truss bottom chord bearing location.



PHOTO
#4
0990.jpg

Girder Truss End: Downward view of bootom chord bearing seat: It will be necessary to cut or burn away front plate at top and bottom of truss (arrow) to allow new girder truss to slide into place.