Portland, Maine



Yes. Life's good here.

Planning & Urban Development Department

Director of Planning and Urban Development Jeff Levine

> Inspection Services, Director Tammy M. Munson

March 5, 2015

RUTTER JASON T 48 PARK AVE PORTLAND, ME 04101

CBL: 036 D003001

Located at: 48 PARK AVE

Certified Mail 7010 1870 0002 8136 6769

Dear Mr. Rutter,

An evaluation of the above-referenced property on 03/05/2015 shows that the structure fails to comply with Chapter 6.Article V. of the Code of Ordinances of the City of Portland, The Housing Code. Attached is a list of the violations.

This is a notice of violation pursuant to Section 6-118 of the Code. All referenced violations shall be corrected within 14 days of the date of this notice. A re-inspection of the premises will occur On 03/19/2015 at which time compliance will be required. Failure to comply will result in this office referring the matter to the City of Portland Corporation Counsel for legal action and possible civil penalties, as provided for in Section 1-15 of the Code.

This constitutes an appealable decision pursuant to Section 6-127 of the Code.

Please feel free to contact me if you wish to discuss the matter or have any questions.

Please be advised that the Portland City Council has amended the Building regulations to include a \$150.00 re-inspection fee. This violation will automatically cause a re-inspection at no charge. If there are any subsequent inspections, however, the \$150.00 fee will be assessed for each inspection.

Sincerely.

Chuck Fagone

Code Enforcement Officer

(207) 874-8789

CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
RUTTER JASON T		Chuck Fagone	3/5/2015
Location	CBL	Status	Inspection Type
48 PARK AVE	036 D003001	Re-Inspect 14 Days	Complaint-Inspection

Unit No.

Int/Ext Exterior

Area

Compliance Date

1) 22.3.3(a)

Entry Way

Violation:

PREMISES TO BE KEPT FREE FROM RODENT HARBORAGE

Notes:

Floor

The owner of a two (2) or more family residential building and the owner or occupant of a single family residential building shall maintain the building and the lot on which the building is located free from any accumulation of any putrid substance, garbage, rubbish, old lumber, debris or rubble, except in watertight covered containers.

Accumulation of debris on the rear porch

2) 6-116. (c)

Interior

Through Out

Violation:

EGRESS OBSTRUCTIONS

Notes:

Every hallway, stairway, corridor, exit, fire escape door or other means of egress shall be kept clear of

obstructions at all times.

Mattress blocking rear egress, first floor windows boarded up from the inside.

3) 6-116. (e)

Interior

Smoke Alarms

Violation:

FIRE PROTECTION

Notes:

Every dwelling, dwelling unit, rooming house and rooming unit shall comply with the applicable provisions of the most current edition of the National Fire Protection Association Life Safety Code, and with all other applicable state statutes and regulations.

Smoke detectors and carbon monoxide detector are missing on the first floor unit. Smoke detector missing in the third floor unit, front bedroom.

Comments:

Violations exist of missing smoke detector in one bedroom of the 3rd floor unit. No smoke detectors or carbon monoxide detectors in the 1st floor unit. Several windows boarded up in the 1st floor unit preventing means of egress. Rear entry blocked by mattresses and debris preventing egress.

Portland, Maine



Yes. Life's good

Planning & Urban Development Inspection Division

389 Congress Street, Room 315 Portland, Maine 04101-3509

RETURN RECEIPT REQUESTED


军事。





7010 1870 0002 8136 6758





8

MAR CANADO

X 015 NFE 1 C13C0003/13/15 FORWARD TIME EXP RTN TO SEND RUTTER 7 SAGAMORE ST PORTSMOUTH RI 02871-5825

04401823339,400

RETURN TO SENDER

