
-LOAD BEARING CENTRAL WALL FALLS ON PRE EXISTING 10" X 10" SUPPORT BEAM IN BASEMENT





CENTRAL BEARING WALL



JOB: 15-17 SHERMAN ST. PORTLAND, ME

OCTOBER 2, 2017