

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street  
 Portland, Maine 04101

**Inspection Violations**

<b>Owner/Manager</b> CUMBERLAND COUNTY YMCA		<b>Inspector</b> Arthur Rowe	<b>Inspection Date</b> 09/29/2004
<b>Locatation</b> 217 HIGH ST	<b>CBL</b> 036 G023001	<b>Status</b> Re-Inspect 30 Days	<b>Inspection Type</b> Complaint-Housing Inspection

<b>Code</b>	<b>Int/Ext</b>	<b>Floor</b>	<b>Unit No.</b>	<b>Area</b>	<b>Compliance Date</b>
1) 6-108.2	Interior	1		Kitchen	
<b>Violation:</b>	Interior floors, walls, ceilings and doors				
<b>Notes:</b>	damaged floor				
2) 6-108.2	Interior	1		Kitchen	
<b>Violation:</b>	Interior floors, walls, ceilings and doors				
<b>Notes:</b>	damaged counter top				
3) 6-109.2	Interior	1		Kitchen	
<b>Violation:</b>	Maintenance of shared areas.				
<b>Notes:</b>	dirty floor				
4) 6-111.4	Interior	1		Kitchen	
<b>Violation:</b>	Maintenance of plumbing fixtures.				
<b>Notes:</b>	leaking faucet				
5) 6-109.2	Interior	1		Bathroom	
<b>Violation:</b>	Maintenance of shared areas.				
<b>Notes:</b>	molding shower curtain				
6) 6-108.2	Interior		room 4	Bedroom	
<b>Violation:</b>	Interior floors, walls, ceilings and doors				
<b>Notes:</b>	ceiling damage				
7) 6-116.5	Interior		room 3	Bedroom	
<b>Violation:</b>	Fire Protection				
<b>Notes:</b>	smoke detector not working properly				
8) 6-116.5	Interior		room 8	Bedroom	
<b>Violation:</b>	Fire Protection				
<b>Notes:</b>	smoke detector not working properly				
9) 6-108.2	Interior	2		Bathroom	
<b>Violation:</b>	Interior floors, walls, ceilings and doors				
<b>Notes:</b>	damaged walls				
10) 6-108.2	Interior	2		Bathroom	
<b>Violation:</b>	Interior floors, walls, ceilings and doors				
<b>Notes:</b>	damaged floors				

**CITY OF PORTLAND**  
**DEPARTMENT OF PLANNING & URBAN DEVELOPMENT**

389 Congress Street  
 Portland, Maine 04101

**Inspection Violations**

<b>Owner/Manager</b> CUMBERLAND COUNTY YMCA		<b>Inspector</b> Arthur Rowe	<b>Inspection Date</b> 09/29/2004
<b>Location</b> 217 HIGH ST	<b>CBL</b> 036 G023001	<b>Status</b> Re-Inspect 30 Days	<b>Inspection Type</b> Complaint-Housing Inspection

11) 6-108.2	Interior	2		Bathroom
<b>Violation:</b>	Interior floors, walls, ceilings and doors			
<b>Notes:</b>	damaged ceilings			
12) 6-111.4	Interior	2		Bathroom
<b>Violation:</b>	Maintenance of plumbing fixtures.			
<b>Notes:</b>	tub surround damaged			
13) 6-111.4	Interior	2		Bathroom
<b>Violation:</b>	Maintenance of plumbing fixtures.			
<b>Notes:</b>	leaking faucet at tub			
14) 6-108.2	Interior		room 1	Bedroom
<b>Violation:</b>	Interior floors, walls, ceilings and doors			
<b>Notes:</b>	damaged ceiling			
15) 6-108.2	Interior		room 1	Bedroom
<b>Violation:</b>	Interior floors, walls, ceilings and doors			
<b>Notes:</b>	damaged walls			
16) 6-116.5	Interior	1	apt 1	common area
<b>Violation:</b>	Fire Protection			
<b>Notes:</b>	missing smoke detector			
17) 6-116.1	Interior	1	apt 1	throughout
<b>Violation:</b>	Flammable/Hazardous Materials			
<b>Notes:</b>	unit full of combustables			

**Comments:**