
CITY OF PORTLAND
DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street
Portland, Maine 04101

Inspection Violations

Owner/Manager Adam Elhadi		Inspector John Bisesti	Inspection Date 03/24/2006
Location 24 Mechanic St	CBL 036 H013001	Status Re-Inspect 30 Days	Inspection Type Complaint-Inspection

Code	Int/Ext	Floor	Unit No.	Area	Compliance Date
1) 6-111.4	Interior	2	2	Bathroom	
Violation: Maintenance of plumbing fixtures. Notes: Leaking bath tub plumbing					
2) 6-113.5	Interior	2	2	Dining Room	
Violation: Maintenance of lighting fixtures Notes: Loose Recepticle					
3) 6-108.2	Interior	2	2	Various locations	
Violation: Interior floors, walls, ceilings and doors Notes: Peeling paint in various locations					
4) 6-109.5	Interior	2	2	Various locations	
Violation: Rodent and vermin control. Notes: Evidence of cockroach activity, Must have proof of licensed pest control operator					

Comments: