

## SYSTEM RECORD OF COMPLETION

*This form is to be completed by the system installation contractor at the time of system acceptance and approval.*

*It shall be permitted to modify this form as needed to provide a more complete and/or clear record.*

*Insert N/A in all unused lines.*

*Attach additional sheets, data, or calculations as necessary to provide a complete record.*

Form Completion Date: 02/17/2020 Supplemental Pages Attached: 2

### 1. PROPERTY INFORMATION

Name of property: Gateway Condominiums Acct#T510142  
Address: 50 Forest Avenue / 420 Cumberland Avenue Portland, Maine 04101  
Description of property: Business Condos  
Name of property representative: Kathi Nickerson  
Address: One City Center, 4<sup>th</sup> Floor Portland, Maine 04101  
Phone: 207-871-1080 Fax: NA E-mail: kathi@dirigomgmt.com

### 2. INSTALLATION, SERVICE, TESTING, AND MONITORING INFORMATION

Installation contractor: B.H. Milliken  
Address: 235 Presumpscot Street Unit C Portland, Maine 04103  
Phone: 207-879-1877 Fax: 207-774-1492 E-mail: bhm@bhmilliken.com  
Service organization: Protection Professionals  
Address: 325 US Route 1 Falmouth, Maine 04105  
Phone: (207) 775-5755 Fax: (207) 781-2064 E-mail: mail@protectionprofessionals.net  
Testing organization: Protection Professionals  
Address: 325 US Route 1 Falmouth, Maine 04105  
Phone: (207) 775-5755 Fax: (207) 781-2064 E-mail: mail@protectionprofessionals.net  
Effective date for test and inspection contract: NA  
Monitoring organization: Rapid Response  
Address: 400 W Division Street Syracuse, New York 13204  
Phone: (800) 932-3822 Fax: NA E-mail: Rrms.com  
Account number: T510142 Phone line 1: None Phone line 2: None  
Means of transmission: AES 7707-P 2.0 Fire Radio  
Entity to which alarms are retransmitted: Portland Dispatch Phone: (207) 874-8576

### 3. DOCUMENTATION

On-site location of the required record documents and site-specific software: None

### 4. DESCRIPTION OF SYSTEM OR SERVICE

This is a:  New system  Modification to existing system Permit number: NA  
NFPA 72 edition: 18

#### 4.1 Control Unit

Manufacturer: Faraday Model number: MPC-7000

#### 4.2 Software and Firmware

Firmware revision number: 7.0005

#### 4.3 Alarm Verification

This system does not incorporate alarm verification.

Number of devices subject to alarm verification: 0 Alarm verification set for 0 seconds

**SYSTEM RECORD OF COMPLETION (continued)**

**5. SYSTEM POWER**

**5.1 Control Unit**

**5.1.1 Primary Power**

Input voltage of control panel: 120VAC Control panel amps: 15  
 Overcurrent protection: Type: Circuit Breaker Amps: 15  
 Branch circuit disconnecting means location: HP1 Electrical Room Number: CB# 17& 19

**5.1.2 Secondary Power**

Type of secondary power: SLA Battery  
 Location, if remote from the plant: In Fire Alarm Control Panel  
 Calculated capacity of secondary power to drive the system:  
 In standby mode (hours): 24 In alarm mode (minutes): 5

**5.2 Control Unit**

- This system does not have power extender panels
- Power extender panels are listed on supplementary sheet A

**6. CIRCUITS AND PATHWAYS**

Pathway Type	Dual Media Pathway	Separate Pathway	Class	Survivability Level
Signaling Line	NA	NA	NA	NA
Device Power	NA	NA	NA	NA
Initiating Device	NA	NA	B	0
Notification Appliance	NA	NA	B	0
Other (specify):	NA	NA	NA	NA

**7. REMOTE ANNUNCIATORS**

Type	Location
Faraday Alpha Numeric	50 Forest Ave Street Side Entrance to Hallway
NA	NA

**8. INITIATING DEVICES**

Type	Quantity	Addressable or Conventional	Alarm or Supervisory	Sensing Technology
Manual Pull Stations	7	Addressable	Alarm	Contact
Smoke Detectors	82	Addressable	Alarm	Photoelectric
Duct Smoke Detectors	2	Addressable	Supervisory	Photoelectric
Heat Detectors	16	Addressable	Alarm	ROR/ Fixed Temperature
Gas Detectors	0	NA	NA	NA
Waterflow Switches	0	NA	NA	NA
Tamper Switches	0	NA	NA	NA

**SYSTEM RECORD OF COMPLETION (continued)**

**9. NOTIFICATION APPLIANCES**

Type	Quantity	Description
Audible	0	NA
Visible	15	Strobe
Combination Audible and Visible	17	Horn Strobe

**10. SYSTEM CONTROL FUNCTIONS**

Type	Quantity
Hold-Open Door Releasing Devices	0
HVAC Shutdown	2
Fire/Smoke Dampers	0
Door Unlocking – Relay serves Cunningham’s Access Control Equipment	1
Elevator Recall – Primary and Alternate	2
Elevator Shunt Trip	0
Elevator Flashing Hat	1

**11. INTERCONNECTED SYSTEMS**

- This system does not have interconnected systems.
- Interconnected systems are listed on supplementary sheet \_\_\_\_\_ .

**12. CERTIFICATION AND APPROVALS**


**12.1 System Installation Contractor**

This system as specified herein has been installed according to all NFPA standards cited herein.

Signed: \_\_\_\_\_ Printed name: \_\_\_\_\_ Date: \_\_\_\_\_  
 Organization: \_\_\_\_\_ Title: \_\_\_\_\_ Phone: \_\_\_\_\_

**12.2 System Operational Test**

This system as specified herein has tested according to all NFPA standards cited herein.

Signed:  Printed name: Jordan Valliere Date: 2/29/2020  
 Organization: Protection Professionals Title: Technician Phone: (207) 775-5755

**12.3 Acceptance Test**

Date and time of acceptance test: \_\_\_\_\_  
 Installing contractor representative: \_\_\_\_\_  
 Testing contractor representative: \_\_\_\_\_  
 Property representative: \_\_\_\_\_  
 AHJ representative: \_\_\_\_\_

Conditional Record of Completion for only the renovations on this transaction. This document does not represent a full system installation nor a full system inspection.

# SYSTEM RECORD OF INSPECTION AND TESTING

*This form is to be completed by the system inspection and testing contractor at the time of a system test.  
It shall be permitted to modify this form as needed to provide a more complete and/or clear record.  
Insert N/A in all unused lines.*

*Attach additional sheets, data, or calculations as necessary to provide a complete record.*

Inspection/Test Start Date/Time: \_\_\_\_\_ Inspection/Test Completion Date/Time: \_\_\_\_\_

Supplemental Form(s) Attached: YES (yes/no)

## 1. PROPERTY INFORMATION

Name of property: Gateway Condominiums Acct#T510142

Address: 50 Forest Avenue / 420 Cumberland Avenue Portland, Maine 04101

Description of property: Business Condos

Name of property representative: Kathi Nickerson

Address: One City Center, 4<sup>th</sup> Floor Portland, Maine 04101

Phone: 207-871-1080 Fax: NA E-mail: kathi@dirigomgmt.com

## 2. TESTING AND MONITORING INFORMATION

Testing organization: Protection Professionals

Address: 325 US Route 1 Falmouth, Maine 04105

Phone: (207) 775-5755 Fax: (207) 781-2064 E-mail: info@protectionprofessionals.net

Monitoring organization: Rapid Response

Address: 400 W Division Street Syracuse, New York 13204

Phone: 1-800-932-3822 Fax: NA E-mail: NA

Account number: T510142 Phone line 1: None Phone line 2: None

Means of transmission: AES 7707-P 2.0 Fire Radio

Entity to which alarms are retransmitted: Portland Dispatch Phone: (207) 874-8576

## 3. DOCUMENTATION

On-site location of the required record documents and site-specific software: None

## 4. DESCRIPTION OF SYSTEM OR SERVICE

### 4.1 Control Unit

Manufacturer: Faraday Model number: MPC-7000

### 4.2 Software and Firmware

Firmware revision number: 7.0005

### 4.3 System Power

#### 4.3.1 Primary (Main) Power

Nominal voltage: 120 Amps: 3.2 Location: HP1 – Electrical Room

Overcurrent protection type: CB Amps: 15 Disconnecting means location: CB 17 & 19



**SYSTEM RECORD OF INSPECTION AND TESTING (continued)**

**6. TESTING RESULTS (continued)**

**6.3 Alarm and Supervisory Alarm Initiating Device**

Attach supplementary device test sheets for all initiating devices.

**6.4 Notification Appliances**

Attach supplementary appliance test sheets for all notification appliances.

**6.5 Interface Equipment**

Attach supplementary interface component test sheets for all interface components.

*Circuit Interface / Signaling Line Circuit Interface / Fire Alarm Control Interface*

**6.6 Supervising Station Monitoring**

Description	Yes	No	Time	Comments
Alarm signal	<input type="checkbox"/>	<input type="checkbox"/>		
Alarm restoration	<input type="checkbox"/>	<input type="checkbox"/>		
Trouble signal	<input type="checkbox"/>	<input type="checkbox"/>		
Trouble restoration	<input type="checkbox"/>	<input type="checkbox"/>		
Supervisory signal	<input type="checkbox"/>	<input type="checkbox"/>		
Supervisory restoration	<input type="checkbox"/>	<input type="checkbox"/>		

**6.7 Public Emergency Alarm Reporting System**

Description	Yes	No	Time	Comments
Alarm signal	<input type="checkbox"/>	<input type="checkbox"/>	NA	NA
Alarm restoration	<input type="checkbox"/>	<input type="checkbox"/>	NA	NA
Trouble signal	<input type="checkbox"/>	<input type="checkbox"/>	NA	NA
Trouble restoration	<input type="checkbox"/>	<input type="checkbox"/>	NA	NA
Supervisory signal	<input type="checkbox"/>	<input type="checkbox"/>	NA	NA
Supervisory restoration	<input type="checkbox"/>	<input type="checkbox"/>	NA	NA

SYSTEM RECORD OF INSPECTION AND TESTING (continued)

7. NOTIFICATIONS THAT TESTING IS COMPLETE

Monitoring organization	Contact: Rapid Response	Time: _____
Building management	Contact: Dirigo Management – Kathi Nickerson	Time: _____
Building occupants	Contact: ALL	Time: _____
Authority having jurisdiction	Contact: Portland Fire Department	Time: _____
Other, if required	Contact: _____	Time: _____

8. SYSTEM RESTORED TO NORMAL OPERATION

Date: 2/21/2020 Time: 14:00

9. CERTIFICATION

This system as specified herein has been inspected and tested according to NFPA 72, 2013 edition, Chapter 14.

Signed: [Signature] Printed name: Jordan Valliere Date: 2/21/2020  
Organization: Protection Professionals Title: Inspector / Technician Phone: (207) 775-5755  
Qualifications (refer to 10.5.3): NICET IMSA LICENSED

10. DEFECTS OR MALFUNCTIONS NOT CORRECTED AT CONCLUSION OF SYSTEM INSPECTION, TESTING, OR MAINTENANCE

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

10.1 Acceptance by Owner or Owner's Representative:

The undersigned accepted the test report for the system as specified herein:

Signed: \_\_\_\_\_ Printed name: \_\_\_\_\_ Date: \_\_\_\_\_  
Organization: \_\_\_\_\_ Title: \_\_\_\_\_ Phone: \_\_\_\_\_

**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING**

*This form is a supplement to the System Record of Inspection and Testing.  
It includes an initiating device test record.*

*This form is to be completed by the system inspection and testing contractor at the time of the inspection and/or test.  
It shall be permitted to modify this form as needed to provide a more complete and/or clear record.  
Insert N/A in all unused lines.*

Inspection/Test Start Date/Time: \_\_\_\_\_ Inspection/Test Completion Date/Time: \_\_\_\_\_

Number of Supplemental Pages Attached: 6

**1. PROPERTY INFORMATION**

Name of property: Gateway Condominiums Acct#T510142

Address: 50 Forest Avenue / 420 Cumberland Avenue Portland, Maine 04101

**2. INITIATING DEVICE TEST RESULTS**

Device Type	Address	Location	Test Results
HEAT	1001	HVAC ROOM CONDO #8 1 <sup>ST</sup> FLOOR	Visual
HEAT	1002	KITCHEN CONDO #8 1 <sup>ST</sup> FLOOR	Visual
HEAT	1003	BATHROOM CONDO #8 1 <sup>ST</sup> FLOOR	Visual
SMOKE	1004	STORAGE CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1005	STORAGE CONDO #8 1 <sup>ST</sup> FLOOR	Pass
HEAT	1006	BATHROOM CONDO #8 1 <sup>ST</sup> FLOOR	Visual
SMOKE	1007	OFFICE #1 CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1008	OFFICE #2 CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1009	CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1010	CONDO #8 1 <sup>ST</sup> FLOOR	Pass
PULL	1011	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1012	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1013	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	Pass
PULL	1014	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1015	MID RANGE CONDO #8 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1016	MID RANGE CONDO #8 1 <sup>ST</sup> FLOOR	Pass
PULL	1017	FOREST AVE EXT 1 <sup>ST</sup> FLOOR COMM ROOM	Pass
SMOKE	1018	HALLWAY 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1019	HALLWAY 1 <sup>ST</sup> FLOOR	Pass
HEAT	1020	STORAGE ROOM 1 <sup>ST</sup> FLOOR	Visual
SMOKE	1021	COMMON HALLWAY 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1022	CONDO #2 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1023	CONDO #2 1 <sup>ST</sup> FLOOR	Pass
SMOKE	1024	CONDO #2 1 <sup>ST</sup> FLOOR	Pass
PULL	1025	HALLWAY #1 ENTRANCE CONDO #2	Pass
SMOKE	1026	OFFICE #1 1 <sup>ST</sup> FLOOR CONDO #2	Pass
SMOKE	1027	OFFICE #2 1 <sup>ST</sup> FLOOR CONDO #2	Pass
SMOKE	1028	OFFICE #3 1 <sup>ST</sup> FLOOR CONDO #2	Pass
SMOKE	1029	RECEPTION AREA 1 <sup>ST</sup> FLOOR CONDO #2	Pass
PULL	1030	FOREST AVE EXIT 1 <sup>ST</sup> FLOOR CONDO #2	Pass



**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

SMOKE	1031	CONDO #2 1ST FLOOR	Pass
SMOKE	1032	CONDO #2 1ST FLOOR	Pass
SMOKE	1034	CONDO #2 OFFICE #4 1ST FLOOR	Pass
SMOKE	1035	CONDO #2 1ST FLOOR	Pass
HEAT	1036	MENS ROOM CONDO #2 1ST FLOOR	Visual
HEAT	1037	WOMENS ROOM CONDO #2 1ST FLOOR	Visual
HEAT	1038	EQUIPMENT ROOM #2 CONDO #2 1ST FLOOR	Visual
HEAT	1040	EQUIPMENT ROOM #1 CONDO #1 1ST FLOOR	Visual
DUCT	1041	EQUIPMENT ROOM #1 CONDO #1 1ST FLOOR	Pass
SMOKE	1043	CONDO #1 1ST FLOOR	Pass
SMOKE	1044	OFFICE #1 CONDO #1 1ST FLOOR	Pass
SMOKE	1045	CONDO #1 1ST FLOOR	Pass
SMOKE	1046	RECEPTION AREA CONDO #1 1ST FLOOR	Pass
PULL	1047	CONDO #1 EXIT CUMBERLAND AVE	Pass
SMOKE	1048	CONDO #1 ELEV LOBBY 1ST FLOOR	Pass
SMOKE	1049	SMOKE CONDO#1 1ST FLOOR	Pass
HEAT	1050	MENS ROOM CONDO #1 1ST FLOOR	Visual
HEAT	1051	WOMENS ROOM CONDO #1 1ST FLOOR	Visual
HEAT	1053	EQUIPMENT ROOM #3 CONDO #3 1ST FLOOR	Visual
SMOKE	1054	OFFICE #1 CONDO #3 1ST FLOOR	PASS
SMOKE	1055	OFFICE #2 CONDO #3 1ST FLOOR	Pass
SMOKE	1056	CONDO #3 1ST FLOOR	Pass
SMOKE	1057	OFFICE #3 CONDO #3 1ST FLOOR	Pass
SMOKE	1058	ELEVATOR LOBBY CONDO #3 1ST FLOOR	Pass
PULL	1059	2ND FLOOR CONDO #3 1ST FLOOR	Pass
SMOKE	1060	CONDO #3 1ST FLOOR	Pass
SMOKE	1061	OFFICE #4 CONDO #3 1ST FLOOR	Pass
SMOKE	1062	CONDO #3 1ST FLOOR	Pass
SMOKE	1063	CONDO #3 1ST FLOOR	Pass
SMOKE	1064	COMPUTER ROOM CONDO #3 1ST FLOOR	Pass
HEAT	1065	KITCHEN CONDO #3 1ST FLOOR	Visual
SMOKE	1066	EQUIPMENT ROOM #5 CONDO #3 1ST FLOOR	Pass
HEAT	1067	MENS ROOM CONDO #3 1ST FLOOR	Visual
HEAT	1068	WOMENS ROOM CONDO #3 1ST FLOOR	Visual
HEAT	1069	EQUIPMENT ROOM #4 CONDO #3 1ST FLR	Visual
SMOKE	1070	CONDO #3 1ST FLOOR	Pass
SMOKE	1071	CONDO #3 1ST FLOOR	Pass
SMOKE	1072	OFFICE #5 CONDO #3 1ST FLOOR	Pass
SMOKE	1073	OFFICE #6 CONDO #3 1ST FLOOR	Pass
HEAT	1074	OFFICE #7 CONDO #4 1ST FLOOR	Visual
SMOKE	1075	PRODUCTION 1ST FLOOR #4	Pass

**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

SMOKE	1076	PRODUCTION RACKS 1ST FLOOR #4	Pass
SMOKE	1077	REAR HALL 1ST FLOOR CONDO #4	Pass
PULL	1078	REAR HALL 1ST FLOOR CONDO #4	Pass
HEAT	1079	WOMENS ROOM 1ST FLOOR CONDO #4	Visual
HEAT	1080	MENS ROOM 1ST FLOOR CONDO #4	Visual
SMOKE	1081	DVD LOUNGE 1ST FLOOR CONDO #4	Pass
SMOKE	1082	DVD HALL 1ST FLOOR CONDO #4	Pass
SMOKE	1083	DVD AUTHORIZING 1ST FLOOR CONDO #4	Pass
SMOKE	1084	SIDE HALL 1ST FLOOR CONDO #4	Pass
PULL	1085	SIDE HALL 1ST FLOOR CONDO #4	Pass
SMOKE	1086	STORAGE 1ST FLOOR CONDO #4	Pass
SMOKE	1087	DOWNSTAIRS HALL 1ST FLOOR CONDO #4	Pass
SMOKE	1088	HALLWAY 1ST FLOOR CONDO #4	Pass
SMOKE	1089	EDIT ROOM 1ST FLOOR CONDO #4	Pass
SMOKE	1090	UTILITY HALL 1ST FLOOR CONDO #4	Pass
SMOKE	1091	STUIDO 1ST FLOOR CONDO #4	Pass
SMOKE	1092	PRODUCTION OFFICE CONDO #4	Pass
SMOKE	1093	RECEPTION 1ST FLOOR CONDO #4	Pass
PULL	1094	CUMBERLAND AVE EXIT 1ST FLOOR CONDO #4	Pass
SMOKE	1095	SCOTTS OFFICE 1ST FLOOR CONDO #4	Pass
SMOKE	1096	DOWNSTAIRS 1ST FLOOR HALL CONDO #4	Pass
SMOKE	1097	1ST FLOOR LOUNGE CONDO #4	Pass
SMOKE	1099	KITCHEN 2ND FLOOR CONDO #4	Pass
SMOKE	1101	2ND FLOOR LOUNGE CONDO #4	Pass
SMOKE	1102	2ND FLOOR OFFICE CONDO #4	Pass
SMOKE	1103	2ND FLOOR PRODUCTION#2 CONDO#4	Pass
SMOKE	1104	2ND FLOOR TOP OF STAIRS CONDO #4	Pass
SMOKE	1105	2ND FLOOR CONDO #4	Pass
SMOKE	1106	2ND FLOOR CONDO #4	Pass
HEAT	1107	2ND FLOOR REAR HVAC ROOM CONDO #4	Visual
HEAT	1108	2ND FLOOR STUDIO HVAC CONDO #4	Visual
PULL	1109	1ST FLOOR STAIRWELL CONDO #3	Pass
SMOKE	1122	1ST FLOOR FACP	Pass
PULL	2001	COMMON HALL EXIT TO PED HALL	Pass
SMOKE	2002	PRIVATE HALLWAY	Pass
PULL	2003	Private Parking	Pass
Smoke	2004	Private Hallway	Pass
Smoke	2005	Private Hallway	Pass
Pull Station	2006	Private Parking	Pass
Smoke	2007	Private Hallway	Pass
Heat	2008	420 Cumberland Avenue 3 <sup>rd</sup> Floor Mechanical Room 322	Visual

**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

Heat	2009	420 Cumberland Avenue 3rd Floor Break Room	Visual
Smoke	2010	420 Cumberland Avenue 3rd Floor Room 319	Pass
NA	2011	NA	NA
Smoke	2012	420 Cumberland Avenue 3rd Floor Room 320	Pass
Smoke	2013	420 Cumberland Avenue 3rd Floor Room 321	Pass
SMOKE	2014	420 Cumberland Avenue 3rd Floor Corridor by Stairwell B Exit	Pass
Smoke	2015	420 Cumberland Avenue 3rd Floor Stairwell B	Pass
Pull Station	2016	420 Cumberland Avenue 3rd Floor Stairwell B	Pass
Heat	2017	420 Cumberland Avenue 3rd Floor Restroom by Stairwell B	Pass
Heat	2018	3420 Cumberland Avenue rd Floor Restroom by Stairwell B (ADA)	Pass
Heat	2019	420 Cumberland Avenue 3rd Floor Electrical Room	Pass
Smoke	2020	420 Cumberland Avenue 3 <sup>rd</sup> Floor Vestibule Outside Electrical Room	Pass
Smoke	2021	420 Cumberland Avenue 3rd Floor Open Area By Electrical Room	Pass
Smoke	2022	420 Cumberland Avenue 3rd Floor Open Area Outside 320	Pass
Smoke	2023	420 Cumberland Avenue 3rd Floor Open Area Outside Room 323	Pass
Smoke	2024	420 Cumberland Avenue 3rd Floor Room 316	Pass
Smoke	2025	420 Cumberland Avenue 3rd Floor Room 317	Pass
Smoke	2026	420 Cumberland Avenue 3rd Floor Room 318	Pass
Smoke	2027	420 Cumberland Avenue 3rd Floor Room 315	Pass
Smoke	2028	420 Cumberland Avenue 3rd Floor Room 314	Pass
Smoke	2029	420 Cumberland Avenue 3rd Floor Room 313	Pass
Smoke	2030	420 Cumberland Avenue 3rd Floor Open Area Outside Room 317	Pass
Smoke	2031	420 Cumberland Avenue 3rd Floor Corridor Outside by Room 318	Pass
Smoke	2032	420 Cumberland Avenue 3 <sup>rd</sup> Floor Elevator Lobby	Pass
Smoke	2033	420 Cumberland Avenue 3rd Floor Room 312	Pass
NA	2034	NA	Pass
NA	2035	NA	Pass
Smoke	2036	420 Cumberland Avenue 3rd Floor Stairwell A	Pass
Pull	2037	420 Cumberland Avenue 3rd Floor Stairwell A	Pass
NA	2038	NA	Pass
Smoke	2039	420 Cumberland Avenue 3rd Floor Room 308	Pass
Smoke	2040	420 Cumberland Avenue 3rd Floor Room 307	Pass
Smoke	2041	420 Cumberland Avenue 3 <sup>rd</sup> Floor Elevator Machine Room	Pass
NA	2042	NA	Pass
Smoke	2043	420 Cumberland Avenue 3rd Floor Room 311	Pass

**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

Smoke	2044	420 Cumberland Avenue 3 <sup>rd</sup> Floor Storage by Bathroom	Pass
Heat	2045	420 Cumberland Avenue 3 <sup>rd</sup> Floor ADA Bathrooms	Pass
Smoke	2046	420 Cumberland Avenue 3 <sup>rd</sup> Floor by ADA Bathrooms	Pass
Heat	2047	420 Cumberland Avenue Mechanical Room	Pass
Heat	2048	2ND FLOOR MENS ROOM CONDO #6	Pass
Heat	2049	2ND FLOOR WOMENS ROOM CONDO #6	Pass
SMOKE	2050	CONDO #6	Pass
SMOKE	2051	ROOM #1 CONDO #6	Pass
SMOKE	2052	ROOM #2 CONDO #6	Pass
SMOKE	2053	ROOM #3 CONDO #6	Pass
SMOKE	2054	ROOM #4 CONDO #6	Pass
SMOKE	2055	ROOM #5 CONDO #6	Pass
PULL	2058	HIGH STREET EXIT CONDO #6	Pass
SMOKE	2059	CONDO #6	Pass
PULL	2060	HALLWAY #2 CONDO #6	Pass
PULL	2067	HALLWAY #2 CONDO #5	Pass
SMOKE	2068	HALLWAY #2 CONDO #5	Pass
SMOKE	2069	OFFICE #1 CONDO #5	Pass
SMOKE	2070	CONDO #5	Pass
SMOKE	2071	CONDO #5	Pass
PULL	2072	HIGH STREET EXIT CONDO #5	Pass
SMOKE	2073	CONDO #5	Pass
SMOKE	2074	CONFERENCE ROOM CONDO #5	Pass
SMOKE	2075	OFFICE #2 CONDO #5	Pass
HEAT	2076	MENS ROOM CONDO #5	Visual
HEAT	2077	WOMENS ROOM CONDO #5	Visual
SMOKE	2083	OFFICE #1 CONDO #7	Pass
SMOKE	2084	OFFICE #2 CONDO #7	Pass
SMOKE	2085	CONDO #7	Pass
SMOKE	2086	OFFICE #3 CONDO #7	Pass
SMOKE	2087	OFFICE #4 CONDO #7	Pass
SMOKE	2088	RECEPTION AREA CONDO #7	Pass
SMOKE	2089	OFFICE #5 CONDO #7	Pass
SMOKE	2090	OFFICE #6 CONDO #7	Pass
SMOKE	2091	OFFICE #7 CONDO #7	Pass
SMOKE	2092	CONFERENCE ROOM CONDO #7	Pass
SMOKE	2093	OFFICE #8 CONDO #7	Pass
SMOKE	2094	OFFICE #9 CONDO #7	Pass
SMOKE	2095	HALLWAY CONDO #7	Pass
SMOKE	2096	OFFICE #10 CONDO #7	Pass
SMOKE	2097	FILE ROOM CONDO #7	Pass

**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

SMOKE	2098	KITCHEN CONDO #7	Pass
HEAT	2099	MENS BATHROOM CONDO #7	Visual
HEAT	2100	WOMENS BATHROOM CONDO #7	Visual
PULL	2101	REAR EXIT CONDO #7	Pass
SMOKE	2102	RECEPTION AREA CONDO #7	Pass
PULL	2103	EXIT TO HIGH STREET CONDO #7	Pass
HEAT	2104	PEDESTRIAN WALKWAY	Visual
PULL	2108	PEDESTRIAN HALLWAY	Pass
PULL	2109	PEDESTRIAN HALLWAY	Pass
PULL	2110	PEDESTRIAN HALLWAY	Pass
SMOKE	2112	185 HIGH STREET BY BATHROOMS	Pass
SMOKE	2113	185 HIGH STREET BY REAR EXIT	Pass
SMOKE	2114	185 HIGH STEET FRONT HALL	Pass
SMOKE	2115	185 HIGH STREET FRONT ENTRANCE	Pass
SMOKE	2251	HIGH STREET BUS STOP WAITING AREA	Pass
PULL	2252	HIGH STREET BUS STOP WAITING AREA	Pass
Heat	3011	420 Cumberland Avenue 1 <sup>st</sup> Floor Mechanical Room # 108	Pass
Duct Detector	3012	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 102	Pass
Smoke	3013	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 102	Pass
Smoke	3015	420 Cumberland Avenue 1 <sup>st</sup> Floor Storage Room	Pass
Smoke	3016	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 103	Pass
Smoke	3017	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 104	Pass
Smoke	3018	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 105	Pass
Smoke	3019	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 106	Pass
Smoke	3020	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 107	Pass
Smoke	3021	420 Cumberland Avenue 1 <sup>st</sup> Floor Reception	Pass
Smoke	3022	420 Cumberland Avenue 1 <sup>st</sup> Floor Community Response Room	Pass
Smoke	3023	420 Cumberland Avenue 1 <sup>st</sup> Floor Room 101	Pass
Smoke	3024	420 Cumberland Avenue 1 <sup>st</sup> Floor Reception	Pass
Smoke	3025	420 Cumberland Avenue 1 <sup>st</sup> Floor Corridor by Bathrooms	Pass
Heat	3026	420 Cumberland Avenue 1 <sup>st</sup> Floor ADA Bathroom off Lobby	Pass
Heat	3027	420 Cumberland Avenue 1 <sup>st</sup> Floor ADA Bathroom off Lobby	Pass
Smoke	3028	420 Cumberland Avenue 1 <sup>st</sup> Floor Storage Room	Pass

**INITIATING DEVICE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

Smoke	3029	420 Cumberland Avenue 1 <sup>st</sup> Elevator Lobby Cumberland Avenue Side	Pass
Pull Station	3030	420 Cumberland Avenue 1 <sup>st</sup> Floor Lobby Cumberland Avenue Exit	Pass
Smoke	3031	420 Cumberland Avenue 1st Floor Room 201	Pass
Smoke	3032	420 Cumberland Avenue 2nd Floor Elevator Lobby	Pass
Smoke	3033	420 Cumberland Avenue 2nd Floor Stairwell A	Pass
Smoke	3034	420 Cumberland Avenue 2nd Floor Room 214	Pass
Smoke	3035	420 Cumberland Avenue 2nd Floor Outside of Office 214	Pass
Smoke	3036	420 Cumberland Avenue 2nd Floor Room 213	Pass
Smoke	3037	420 Cumberland Avenue 2nd Floor Room 212	Pass
Smoke	3038	420 Cumberland Avenue 2nd Floor Outside of Office 212	Pass
Smoke	3039	420 Cumberland Avenue 2nd Floor Room 211	Pass
Smoke	3040	420 Cumberland Avenue 2nd Floor Storage Next To Cafe	Pass
Smoke	3041	420 Cumberland Avenue 2 <sup>nd</sup> Floor Cafe	Pass
Heat	3042	420 Cumberland Avenue 2nd Floor ADA Bathroom	Pass
Heat	3043	420 Cumberland Avenue 2nd Floor ADA Bathroom	Pass
Smoke	3044	420 Cumberland Avenue 2 <sup>nd</sup> Floor Corridor Outside of Cafe	Pass
Smoke	3045	420 Cumberland Avenue 2nd Floor Room 210	Pass
Smoke	3046	2 <sup>nd</sup> Floor Corridor Outside Bathroom	Pass
Pull Station	3047	420 Cumberland Avenue 2nd Floor Stair B Exit	Pass
Smoke	3048	420 Cumberland Avenue 2nd Floor Storage	Pass
Smoke	3049	420 Cumberland Avenue 2nd Floor Room 209	Pass
Smoke	3050	420 Cumberland Avenue 2nd Floor Room 208	Pass
Smoke	3051	420 Cumberland Avenue 2nd Floor Room 207	Pass
Smoke	3052	420 Cumberland Avenue 2nd Floor Room 206	Pass
Smoke	3053	420 Cumberland Avenue 2nd Floor Corridor Outside Room 206	Pass
Smoke	3054	420 Cumberland Avenue 2nd Floor Room 215	Pass
Smoke	3055	420 Cumberland Avenue 2nd Floor Room 205	Pass
Smoke	3056	420 Cumberland Avenue 2nd Floor Room 204	Pass
Smoke	3057	420 Cumberland Avenue 2nd Floor Room 217	Pass
Smoke	3058	420 Cumberland Avenue 2nd Floor Room 216	Pass
Smoke	3059	420 Cumberland Avenue 2 <sup>nd</sup> Floor Common Grounds	Pass
Smoke	3060	420 Cumberland Avenue 2nd Floor Room 202	Pass
Smoke	3061	420 Cumberland Avenue 2nd Floor Room 203	Pass
Smoke	3062	420 Cumberland Avenue 2nd Floor Corridor Outside Room 217	Pass
Heat	3063	420 Cumberland Avenue 2nd Floor Mechanical Room 218	Pass







**NOTIFICATION APPLIANCE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING**

*This form is a supplement to the System Record of Inspection and Testing.  
It includes a notification appliance test record.*

*This form is to be completed by the system inspection and testing contractor at the time of the inspection and/or test.  
It shall be permitted to modify this form as needed to provide a more complete and/or clear record.  
Insert N/A in all unused lines.*

Inspection/Test Start Date/Time: \_\_\_\_\_ Inspection/Test Completion Date/Time: \_\_\_\_\_

Number of Supplemental Pages Attached: 5

**1. PROPERTY INFORMATION**

Name of property: Gateway Condominiums Acct#T510142

Address: 50 Forest Avenue / 420 Cumberland Avenue Portland, Maine 04101

**2. NOTIFICATION APPLIANCE TEST RESULTS**

Appliance Type	Location/Identifier	Test Results
V	BATHROOM CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	STORAGE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	STORAGE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	BATHROOM CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #1 CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #2 CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	MID RANGE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	MID RANGE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	FOREST AVE EXT 1 <sup>ST</sup> FLOOR COMM ROOM	PASS
AV	HALLWAY 1 <sup>ST</sup> FLOOR	PASS
AV	HALLWAY 1 <sup>ST</sup> FLOOR	PASS
AV	STORAGE ROOM 1 <sup>ST</sup> FLOOR	PASS
AV	COMMON HALLWAY 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	HALLWAY #1 ENTRANCE CONDO #2	PASS
AV	OFFICE #1 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	OFFICE #2 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	OFFICE #3 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	RECEPTION AREA 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	PASS

**NOTIFICATION APPLIANCE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

**2. NOTIFICATION APPLIANCE TEST RESULTS (continued)**

Appliance Type	Location/Identifier	Test Results
AV	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	MID RANGE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	MID RANGE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	FOREST AVE EXT 1 <sup>ST</sup> FLOOR COMM ROOM	PASS
AV	HALLWAY 1 <sup>ST</sup> FLOOR	PASS
AV	HALLWAY 1 <sup>ST</sup> FLOOR	PASS
AV	STORAGE ROOM 1 <sup>ST</sup> FLOOR	PASS
AV	COMMON HALLWAY 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	HALLWAY #1 ENTRANCE CONDO #2	PASS
AV	OFFICE #1 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	OFFICE #2 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	OFFICE #3 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	RECEPTION AREA 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	FOREST AVE EXIT 1 <sup>ST</sup> FLOOR CONDO #2	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #2 1 <sup>ST</sup> FLOOR	PASS
AV	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	TECH LAB CONDO #8 1 <sup>ST</sup> FLOOR	PASS
AV	EXIT FOREST AVE CONDO #8 1 <sup>ST</sup> FLOOR	PASS
V	WOMENS ROOM CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	EQUIPMENT ROOM #4 CONDO #3 1 <sup>ST</sup> FLR	PASS
AV	CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #5 CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #6 CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #7 CONDO #4 1 <sup>ST</sup> FLOOR	PASS
AV	PRODUCTION 1 <sup>ST</sup> FLOOR #4	PASS
AV	PRODUCTION RACKS 1 <sup>ST</sup> FLOOR #4	PASS
AV	REAR HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	REAR HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
V	WOMENS ROOM 1 <sup>ST</sup> FLOOR CONDO #4	PASS
V	MENS ROOM 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	DVD LOUNGE 1 <sup>ST</sup> FLOOR CONDO #4	PASS

**NOTIFICATION APPLIANCE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

AV	DVD HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	DVD AUTHORIZING 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	SIDE HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	SIDE HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	STORAGE 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	DOWNSTAIRS HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	HALLWAY 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	EDIT ROOM 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	UTILITY HALL 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	STUIDO 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	PRODUCTION OFFICE CONDO #4	PASS
AV	RECEPTION 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	CUMBERLAND AVE EXIT 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	SCOTTS OFFICE 1 <sup>ST</sup> FLOOR CONDO #4	PASS
AV	DOWNSTAIRS 1 <sup>ST</sup> FLOOR HALL CONDO #4	PASS
AV	1 <sup>ST</sup> FLOOR LOUNGE CONDO #4	PASS
V	WOMENS ROOM CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	EQUIPMENT ROOM #4 CONDO #3 1 <sup>ST</sup> FLR	PASS
AV	CONDO #3 1 <sup>ST</sup> FLOOR BY 50 FOREST ENTRANCE	PASS
AV	CONDO #3 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #5 CONDO # 3 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #6 CONDO # 3 1 <sup>ST</sup> FLOOR	PASS
AV	OFFICE #7 CONDO #4 1 <sup>ST</sup> FLOOR	PASS
AV	PRODUCTION 1 <sup>ST</sup> FLOOR #4	PASS
AV	PRODUCTION RACKS 1 <sup>ST</sup> FLOOR #4	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE CONDO #4	PASS
V	2 <sup>ND</sup> FLOOR PRODUCTION#2 CONDO#4	PASS
AV	2 <sup>ND</sup> FLOOR WOMENS RM CONDO#4	PASS
AV	2 <sup>ND</sup> FLOOR TOP OF STAIRS CONDO #4	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #4	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #4	PASS
AV	2 <sup>ND</sup> FLOOR REAR HVAC ROOM CONDO #4	PASS
AV	2 <sup>ND</sup> FLOOR STUDIO HVAC CONDO #4	PASS
AV	1 <sup>ST</sup> FLOOR STAIRWELL CONDO #3	PASS
AV	1 <sup>ST</sup> FLOOR FACP	PASS
AV	COMMON HALL EXIT TO PED HALL	PASS
AV	PRIVATE HALLWAY	PASS
AV	PRIVATE PARKING	PASS
AV	PRIVATE HALLWAY	PASS
AV	PRIVATE HALLWAY	PASS
AV	PRIVATE PARKING	PASS

**NOTIFICATION APPLIANCE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

AV	PRIVATE HALLWAY	PASS
AV	2 <sup>ND</sup> FLOOR EQUIPMENT ROOM #6 CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR KITCHEN CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #1 CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #2 CONDO #3 (computer)	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #3 CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR REAR HALLWAY CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR TOP OF STAIRS CONDO #3	PASS
V	2 <sup>ND</sup> FLOOR RESTROOM CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR HANDICAP BATH CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR TOP OF STAIRS CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR ELEVATOR LOBBY CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #3	PASS
AV	2 <sup>ND</sup> FLOOR EQUIP. ROOM #7 CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR TOP OF STAIRS CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR TOP OF STAIRS CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #1 CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #2 CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #3 CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR OFFICE #1 CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR CONDO #1	PASS
AV	2 <sup>ND</sup> FLOOR ELEVATOR MACH. ROOM CONDO #1	PASS
AV	KITCHEN CONDO #7	PASS
V	MENS BATHROOM CONDO #7	PASS
V	WOMENS BATHROOM CONDO #7	PASS
AV	REAR EXIT CONDO #7	PASS
AV	RECEPTION AREA CONDO #7	PASS
AV	CONDO #7 PHYSICAL THERAPY ROOM (RIGHT)	Pass
AV	CONDO #7 PHYSICAL THERAPY ROOM (LEFT)	PASS
AV	EXIT TO HIGH STREET CONDO #7	PASS
AV	PEDESTRIAN WALKWAY	PASS
AV	PEDESTRIAN HALLWAY	PASS
AV	PEDESTRIAN HALLWAY	PASS
V	185 HIGH STREET BY BATHROOMS	PASS
AV	185 HIGH STREET BY REAR EXIT	PASS
AV	185 HIGH STREET FRONT HALL	PASS
AV	185 HIGH STREET FRONT ENTRANCE	PASS
V	185 HIGH STREET BY BATHROOMS	PASS

**NOTIFICATION APPLIANCE  
SUPPLEMENTARY RECORD OF INSPECTION AND TESTING (continued)**

AV	185 HIGH STREET BY REAR EXIT	PASS
AV	185 HIGH STEET FRONT HALL	PASS
AV	185 HIGH STREET FRONT ENTRANCE	PASS
AV	HIGH STREET BUS STOP WAITING AREA	PASS
AV	HIGH STREET BUS STOP WAITING AREA	PASS
V	185 HIGH STREET BY BATHROOMS	PASS
AV	1 <sup>st</sup> Floor Community Response Open Work Area	Pass
AV	1 <sup>st</sup> Floor Reception	Pass
AV	1 <sup>st</sup> Floor Reception	Pass
V	1 <sup>st</sup> Floor ADA Bathroom	Pass
V	1 <sup>st</sup> Floor ADA Bathroom	Pass
AV	1 <sup>st</sup> Floor Elevator Lobby	Pass
V	2 <sup>nd</sup> Floor Room 201	Pass
AV	2 <sup>nd</sup> Floor Open Work Area Common Grounds	Pass
AV	2 <sup>nd</sup> Floor Hallway by Stairwell B	Pass
V	2 <sup>nd</sup> Floor Room 215	Pass
AV	2 <sup>nd</sup> Floor Open Work Area	Pass
AV	2 <sup>nd</sup> Floor Café	Pass
V	2 <sup>nd</sup> Floor ADA Bathroom	Pass
V	2 <sup>nd</sup> Floor ADA Bathroom	Pass
AV	2 <sup>nd</sup> Floor Hallway by Stairwell A	Pass
V	2 <sup>nd</sup> Floor Room 210	Pass
AV (EOL)	2 <sup>nd</sup> Floor Hallway by Room 210	Pass
AV	3 <sup>rd</sup> Floor Open Work Area	Pass
AV	3 <sup>rd</sup> Floor Hallway by Stairwell A	Pass
V	3 <sup>rd</sup> Floor ADA Bathroom	Pass
V	3 <sup>rd</sup> Floor ADA Bathroom	Pass
V	3 <sup>rd</sup> Floor Open Work Area	Pass
V	3 <sup>rd</sup> Floor Room 317	Pass
AV	3 <sup>rd</sup> Floor Outside Room 317 – Open Work Area	Pass
V	3 <sup>rd</sup> Floor Room 312	Pass
V	3 <sup>rd</sup> Floor ADA Bathroom	Pass
V	3 <sup>rd</sup> Floor ADA Bathroom	Pass
AV	3 <sup>rd</sup> Floor Open Work Area Outside Room 310	Pass
AV (EOL)	3 <sup>rd</sup> Floor Open Work Area Outside Boiler Room	Pass



