CITY OF PORTLAND DEPARTMENT OF PLANNING & URBAN DEVELOPMENT

389 Congress Street Portland, Maine 04101

Inspection Violations

Owner/Manager		Inspector	Inspection Date
TERBAX REALTY INC		Suzanne Hunt	9/16/2009
Locatation	CBL	Status	Inspection Type
562 Congress St 037 G014001		Re-Inspect 30 Days	Complaint-Inspection

	•				•			
	Code	Int/Ext			Floor	Unit No.	Area	Compliance Date
1)	6-108.(a)	Exterior					Various lo	ocations
	Violation:	Foundations of	s cellars, exterior walls, roofs					
	Notes:	Sec. 6 108. Minimum standards for structural elements. Foundations, basements, cellars, exterior walls, roofs. Every foundation, basement, cellar, exterior wall, and roof shall be substantially weathertight, watertight, and vermin proof; shall be structurally sound and in good repair; and shall be safe for the intended use as well as capable of supporting whatever load normal use may cause to be placed thereon. Every exterior wall or portion thereof shall be painted or stained. Insulation shall be installed and maintained so as not to present a health or safety hazard to occupants. Water from roofs shall be so drained and conveyed therefrom as not to cause repeatedly wet floors, walls, or ceilings, or hazard to						

Comments:

Loose and deteriorated brick windows casing are coming off building and falling onto roof at 570 Congress. Photos taken at site. Smh

adjacent buildings or the occupants thereof.