Reviewed for Code Compliance
Inspections Division
Approved with Conditions
Date: 03/07/16

New equipment to go between existing equipment 3'x3'. Installation can not be seen from the ground

Concentric Gas vent for warm air furnace exiting here