

**STRUCTURAL TEST AND INSPECTIONS REPORT**

**FIELD REPORT NO: 14**

Project: **53 Danforth Street**

**Portland, ME 04101**

Contractor: **Wright-Ryan Construction**

**10 Danforth Street**

**Portland, ME 04101**

Client: **Archetype**

**48 Union Wharf**

**Portland, ME 04101**

Date: **08/05/09**

Temperature/ Weather: **Sunny, 80 F**

**Present At Site:** Larry Ross, Wright Ryan Construction

**Work in Progress / Observations:**

- 14.1 As conveyed to us via a phone conversation with the project superintendant, items 11.2, 13.1, 13.2 have been completed and accepted.

**Action Required / Items to Verify**

Blair Budka

**FIELD REPRESENTATIVE**

Linas J. Dabrila

**REVIEWED BY**