

marked 10/21/08

STRUCTURAL TEST AND INSPECTIONS REPORT

FIELD REPORT NO: 2

Project: **53 Danforth Street**
Portland, ME 04101

Contractor: **Wright-Ryan Construction**
10 Danforth Street
Portland, ME 04101

Client: **Archetype**
48 Union Wharf
Portland, ME 04101

Date: **10/21/08**

Temperature/ Weather: **Sunny, 60F**

Present At Site: Larry Ross - Wright Ryan Construction

Work in Progress / Observations

- 2.1 The steel for the columns at line 15-J, 14-J, 12-J, 10-J, 8-K, 7-K, 4-K and 3-K as well as the footings at line 9-E, 10-E and 11-E were inspected. After making some minor corrections we found this work to be in compliance with the contract drawings.

Action Required / Items to Verify

Blair Budka

FIELD REPRESENTATIVE

Linus J. Dabrila

REVIEWED BY