




2696 Lake Shore Road, Unit 130
Gilford, NH 03249
Phone: (603) 293-8038

JOB NAME: 77 Danforth Street
JOB NO.: 15013.02
DATE OF VISIT: Sep 09, 2015
TIME: 11:00 A.M.
WEATHER: 70°, clear
CLIENT: Port Property Management
OBSERVERS: David Tetreault, SDC

I performed a visual inspection of repairs to the fire escape located at 77 Danforth Street, Portland, ME. Refer to my field notes dated 08/04/15 for a description of repairs.

I observed that the required landing repairs had been acceptably completed

No other repair were required at the time of the reinspection.



SIGNATURE: _____

David J. Tetreault